

Agenda Item Number

Date October 27, 2008

.....

Communication from Dorothy Spotts, 606 SE 28th Street, Des Moines, regarding traffic regulations in the vicinity of SE 28th Street and Scott Avenue.


Moved by ______ to

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT	CERTIFICATE
COWNIE					
COLEMAN					I, DIANE RAUH, City Clerk of said City hereby
HENSLEY					certify that at a meeting of the City Council of said City of Des Moines, held on the above date,
KIERNAN					among other proceedings the above was adopted.
MAHAFFEY					5
MLYER	1				IN WITNESS WHEREOF, I have hereunto set my
VLASS1S					hand and affixed my seal the day and year first above written.
TOTAL					
MOTION CARRIED			λ	PPROVED	
				Mayor	City Clerk

48A I am writing this letter often seeing This report I we apprecate the new readable signs but the Trucko Drives still ignow Them since the new sign were placed on 38th South of Scott. I have seen one semi back up and go book on Scott E. Where he belonged There are no signs off of moury going Nor That inducto not a Truck route. In fait while I was passing around This pelition I tolked to a lady on raccoon W. of 30th that said server Tome through thew all of the Time. also another person on 3 4 281 said They turn Noff a many and come up theretoo. I have also seen Them Ame on Scott and continue post 38th S. and turn N. a few blocks west which gives Thema a clean shot & market St. a new house on the coiner of scott and 38th the owner has had words with semi Driver about Quering up over the cultime onto the grass, there is a light pole that is supposed to have a guy ione but the semis have broke it so puch they don't bother to fix it. as for sidewook on 1. side of Scott. There are all brick sidewalk but are so overgroun they are unusable.

62 many St. is already a Truck route. as for going by a Community Center which is only a building for Senior aliger meals & voling the porte prea was taken by the city to build a greenhouse to beautify downtown no flowers are Used duer here in our drea. of the senis are going N. on 18th & doubt if they go all the way to Grand. Because On sure they are headed for SE14= St. I I'm so glad the childrent are catching The bus friedway on 28th S. S. but it doesn't help when the same still come up 28th from Mary, One morning The kids and parents standing with them yelled at them that it was not a thick route. we an this area are Continually yelling at them that this is not a truck rold but they either can't hear us an are just ignoring us and the laws. O lody on this street even stopped one Driver and all he did was strug and say So. Hove any of you Council members even been in This area. We have a large port colled Chesterful porkno play ground equepment Just a swing & slitt a wading pool they threaten & close every year with a tree full of dead

lembes kanging over it that parks I rec promised to this up this summer but havent. They did finally cut down a Dead the that had stood there for years, They claimed to be to busy this seemner but these problems exected before the summer and had been reported & Them. If we want & go & a park curth nice play equipment we have to go to S.F. 14# Ston 35 to Dean. of you wait for the St. connecta hand many more chiller will have to de before you to something Constructive Servicely Colothy Spott 606 S.E. 38th St Des moines da 50317



AGENDA HEADING:

Amending Chapter 114 of the Municipal Code regarding traffic regulations in the vicinity of SE 28thStreet and Scott Avenue.

SYNOPSIS:

Recommend approval of the Traffic Safety Committee recommendations, including first reading of the ordinance regarding traffic regulation changes to remove the truck route designation on SE 28th Street from Market Street to Scott Avenue and to create a four-way stop at the intersection of SE 28th Street and Scott Avenue.

FISCAL IMPACT:

Amount: Minor costs.

<u>Funding Source</u>: 2008-2009 Operating Budget, Page 131, Engineering Department Traffic & Transportation—Sign Installation and Maintenance, ENG100413.

ADDITIONAL INFORMATION:

At the June 23, 2008 City Council meeting, council requested that staff work with the Traffic Safety Committee to review the truck route and related safety issues on Scott Avenue in the vicinity of SE 28th Street. This followed a fatal crash that occurred on June 17 involving a five-year-old boy riding his bicycle who was run over by a turning truck at the intersection. By Roll Call No. 08-1149, this item was referred to the City Manager and Traffic Safety Committee for review and recommendation.

Several items were requested by City Council. Two items that didn't involve ordinance changes have already been implemented by staff. Several of the existing truck route signs were older and deteriorated, so these were replaced with new truck route signs. Also, speed limit signs were placed on SE 28th Street between Market Street and Scott Avenue to better advise of the existing 25 mph speed limit. The remaining items requested for study were: (1) change location of truck route; and (2) sidewalk review and recommendation.

Currently, the designated truck route through this area consists of Market Street from SE 18th Street to SE 28th Street; SE 28th Street from Market Street to Scott Avenue; and Scott Avenue from SE 25th Street to SE 30th Street. There are two main industries in this area that generate most of the truck traffic: MidAmerica Recycling at 2742 E. Market and Titan Tire at 2345 E. Market. If trucks are prohibited on SE 28th Street and Scott Avenue, these trucks would be required to travel west on Market to SE 18th

Street, then either south or north through other residential areas. The "out-of-distance" travel would be between two and five miles, depending on the truck's destination. While the removal of SE 28th and Scott from the City's truck route system would have benefits to this neighborhood, it would not have overall benefits to the City, since it would increase the overall truck-miles traveled, some of which would be through very similar residential areas (Maury Street through the Chesterfield area, and East 18th Street between Grand Avenue and Dean Avenue.) Based on this, staff recommended that the truck routes not be changed at this time.

Staff reviewed the current sidewalk conditions in the vicinity of the SE 28th and Scott intersection. A map is attached that identifies where sidewalks currently exist (in "green" and "yellow"), and where there are no sidewalks (in "red"). Based on this review, sidewalks exist on approximately one-quarter of the street frontages in this area. In general, it is desirable to have sidewalks along both sides of all residential streets. However, the cost of these sidewalks is generally borne by the adjacent property owner. In this case, staff recommends that a sidewalk network be established along one side of both Scott Avenue and SE 28th Streets. In reviewing the existing sidewalk locations, it appears that the most feasible locations would be along the north side of Scott Avenue and along the east side of SE 28th Street. It is recommended that the Engineering Department conduct a "feasibility study" of installing this sidewalk, which would include a cost estimate and assessed cost to the property owners. This information would then be forwarded to City Council for their consideration.

One concern raised by the residents was that a large number of school children were picked up at the intersection of SE 28th and Scott. Staff has worked with Des Moines School District transportation officials, and the school district has removed this as a designated pick-up point, and is instead providing two others nearby: one at the intersection of SE 27th and Raccoon, with approximately 23 children, and the other on SE 28th Street midway between Scott Avenue and Maury Street, with approximately 17 children.

Because the intersection of SE 28th Street and Scott Avenue is the intersection of two residential collectors, and also is the intersection of two truck routes, staff also reviewed the possibility of placing a four-way stop at this intersection. With the various turning traffic that occurs here, and the spacing between this intersection and nearby stop-controlled intersections along SE 28th and along Scott, this is an appropriate location for a four-way stop, and staff recommended that it be installed at this intersection.

At their August 12, 2008 meeting, the Traffic Safety Committee approved a staff recommendation that a sidewalk feasibility study be conducted by the Engineering Department in this vicinity, and that a fourway stop be installed at the intersection of SE 28th Street and Scott Avenue, but requested further study on the issue of SE 28th Street as a truck route between Market Street and Scott Avenue. Staff has collected additional data and looked at other alternatives.

Traffic counters were placed on SE 28th Street about midway between Market and Scott for a five-day period from mid-Wednesday, September 10, to mid-Monday, September 15, to collect traffic volumes, speeds and vehicle classification. The traffic volume averaged about 1,700 vehicles per day (vpd) on weekdays, about 1,100 vpd on Saturday, and about 700 vpd on Sunday. Vehicle speeds were also recorded, and showed an average speed of 24-25 mph for northbound and southbound traffic, with an 85th percentile speed of 29 mph.

A total of 608 three-axle or larger trucks were counted, representing 8.8% of the total 6,876 vehicles. An additional 379 two-axle trucks or buses were counted (5.5% of total). An additional 147 vehicles (2.1%

of total) could not be classified, but would most likely have been some type of truck or truck/trailer combination. Taken together, a total of 1,134 two-axle or larger trucks were counted during these five days, or 16.5% of the total traffic. This would represent approximately 182 trucks on an average weekday, with approximately half of those trucks being three-axle or larger.

Staff has investigated the possibility of extending Market Street east of SE 28th Street to connect directly with SE 30th Street. Such a connection could allow trucks to "bypass" the existing houses along SE 28th Street and on Scott Avenue between SE 28th and SE 30th Streets. However, this connection would run through other residentially-zoned property and would require acquisition of several residential properties. A rough cost estimate for this connection is \$1.6 million, including design, property acquisition and construction. The connection at SE 30th Street would be on the approach fill on the south side of the railroad viaduct, which would not be a very good location for an intersection, especially for heavy trucks to pull out onto this busy roadway. Overall, this connection is not considered to be a very viable alternate. At the October 14, 2008 meeting, a Traffic Safety Committee member made a proposal to extend Market Street to the east to go under the E. 30th Street viaduct and then connect back south to Scott Avenue east of E. 30th (copy attached). While eliminating the difficult connection with E. 30th Street just south of the viaduct, this route would be substantially more expensive and would impact additional residential properties cast of E. 30th Street.

Staff has also further reviewed the potential routing of trucks from the businesses in this area if the truck route designation is removed from SE 28th Street. For trucks to and from Mid America Recycling on SE 28th Street, they currently go past a total of 19 houses on SE 28th Street, and then an additional 15 houses on Scott Avenue over to SE 30th Street, with a total distance of 0.5 mile. If they went west on Market, they would still go past two houses on SE 28th Street, and five houses on Market to SE 18th Street. If they go south on SE 18th Street to Maury and then back east to SE 30th, they would go past 30 houses on Maury, as well as a medical clinic and the Chesterfield Community Center. Trucks making this loop of Market Street and Maury Street would travel a total distance of 3.2 miles and would also have to cross seven railroad lines, including the main north-south Chicago Northwestern line twice.

6.

Trucks from Titan Tire would be similar, except they would go past five houses on E. Market between the plant and SE 28th if they use SE 28th and Scott, and would not go past those houses if they go west on Market. If the trucks go north on SE 18th Street to Grand Avenue, they would cross numerous railroad crossings and go past a total of 16 houses, a small park and a fire station.

Staff did meet with the manager of MidAmerica Recycling, and he expressed his sympathy for the tragic accident, their emphasis on safety for their truck drivers and their willingness to comply with whatever the City decides regarding the truck routes. Officials from Titan Tire did not want to meet or comment about the truck route. Staff did not meet with the Iowa Department of Transportation or Department of Economic Development, as there are no known funding programs which would be available to fund any extension of Market Street to SE 30th Street. Future construction of the proposed SE Connector road would provide a major new connection to Market Street, and could reduce the out-of-distance travel for trucks by about one-half and eliminate several railroad crossings. Staff made the following recommendations.

1. That the current truck route designation through this area not be changed, until construction of a segment of the SE Connector that would minimize out of distance travel, eliminate some railroad crossings and avoid sending trucks in front of other houses.

2. That the Police Department work with the residents in this area concerning bicycle and pedestrian safety, through their HONRA (Hispanic Outreach Neighborhood Resource Advocate) unit officers.

Staff further recommended that the previous items approved by the committee be included in the overall recommendation:

- 3. That a sidewalk "feasibility study" be conducted by the Engineering Department.
- 4. That a four-way stop be installed at SE 28th Street and Scott Avenue.

At their October 14, 2008 meeting, the Traffic Salety Committee unanimously approved a motion to delete SE 28th Street as a truck route; step up police enforcement of the truck route ordinance; that Committee Member John Morrissey's suggestion to re-route truck traffic be included in the report being prepared for Council; and keep staff recommendations 2 through 4 intact.

PREVIOUS COUNCIL ACTION(S):

Date: June 23, 2008

Roll Call Number: 08-1149

Action: Moved by Meyer to refer to City Manager and Traffic Safety Committee for review and recommendation on the following: 1) signage designating as truck route, 2) speed limit, 3) change location of truck route, and 4) sidewalks in area. Motion Carried 7-0.

BOARD/COMMISSION ACTION(S): TRAFFIC SAFETY COMMITTEE

Date: August 12, 2008

Roll Call Number: N/A

<u>Action:</u> The Traffic Safety Committee approved a staff recommendation that a sidewalk feasibility study be conducted by the Engineering Department in this vicinity, and that a four-way stop be installed at the intersection of SE 28th Street and Scott Avenue, but requested further study on the issue of SE 28th Street as a truck route between Market Street and Scott Avenue.

Date: October 14, 2008

Roll Call Number: N/A

<u>Action:</u> The Traffic Safety Committee unanimously approved a motion to delete SE 28th Street as a truck route; step up police enforcement of the truck route ordinance; that Committee Member John Morrissey's suggestion to re-route truck traffic be included in the report being prepared for Council; and keep staff recommendations 2 through 4 intact.

ANTICIPATED ACTIONS AND FUTURE COMMITMENTS:

For more information on this and other agenda items, please call the City Clerk's Office at 515-283-4209 or visit the Clerk's Office on the second floor of City Hall, 400 Robert D. Ray Drive. Council agendas are available to the public at the City Clerk's Office on Thursday alternoon preceding Monday's Council meeting. Citizens can also request to receive meeting notices and agendas by email by calling the Clerk's Office or sending their request via email to cityclerk@dmgov.org.

, 19 u

With the recent fatality on June 17, 2008, at the corner of SE 28th and Scott Streets on Des Moines's Southeast side, the concerned families in the area hereby petition for the changing of the truck route that includes both Scott and SE 28th Streets be rerouted to exclude these streets and, instead, include SE 18th and Maury which would not be within a residential area.

The residents in support of this petition are signed below:

515 -238-6237 TH 50317 (616) 262-7237 515 265 9/00 204-7768 260-3905 PHONE NUMBER 21 ol 1-1950 21010-1300 14/1-292 208-1426 1320 3401 E HANN AN, DSN JA 508M IA 50317 50317 5231 7521 LOWIN AV. DEM TA EVENIN VIPOLSANANI TA SOSIT TH SSII EP-1 205 PLIME IA SULTS TA NAN O3M Sm F N5(1 4130 SE. 22ª St ADDRESS た 3900 238th St. DSm. Mondy Santillan 2747 E. Elmor DSM N K Burnardinho ODR S.S. ARth 1 611 SE 27CH 15 -132 35 MED F. Sar ま 701 30 CF 2808 Scott 955 Shurnluh 2709 anya teacurk Virkelas mana anau ", Vettan - C In we NAME Jeffrey ERRY taular 12. 10. d ŝ 6 4 e 6 00

NÚMERO DE TELÉFONO 010-108-401 1510)-Pre Kimmedmark 2769 S Washington Hur Josit Unter Bunding 2304 5 Rose are apt 14 Son, IA Tarth Michael 2709 2, Nathington Aue. 50317 のない Portorcherd JUANA SALAS 2739 SCODT AVE 50317 2739 SCOOTT AVE 500 17 Au 50317 7335E27427 5037 50320 S0320 DIRECCIÓN 12. Whisting Bruce 12223 Stewbert LOE Lavier MUNO 2 2500 MUMY + 250th 3132 KENON AUE 3152 IVIN Jananet PERDUC are tuis Kocio Salas XCL2 NOMBRE 11. 6500 10. 1 6 ~ 6. 00 N e 4 Ś

Con la fatalidad reciente el 17 de junio de 2008, en la esquina de SE 28th y las calles de Scott en el lado suroriental del DES Moines, las familias en cuestión en el área solicitan por este medio para cambiar de la ruta del carro que incluye a Scott y a SE 28th Las calles se reencaminen para excluir estas calles y, en lugar, para incluir SE 18th y Maury que no estaría dentro de un área residencial. Firman a los residentes en apoyo de esta petición abajo:

Con la fatalidad reciente el 17 de junio de 2008, en la esquina de SE 28th y las calles de Scott en el lado suroriental del DES Moines, las familias en cuestión en el área solicitan por este medio para cambiar de la ruta del carro que incluye a Scott y a SE 28th Las calles se reencaminen para excluir estas calles y, en lugar, para incluir SE 18th y Maury que no estaría dentro de un área residencial. Firman a los residentes en apoyo de esta petición abajo:

NÚMERO DE TELÉFONO 2660128	7 315 260-3725	4100492(S15) 4100492(S15)	615/339-8353	515) 975 CA352 69	262-1194
2500 E 40 HT St DEMTL SO37515) 2660128	620 8	650 56 28 ⁵¹ Des Housines JH 50317 515) 264-0019 650 56 28 ³² Des Housies TA (Sis) 2640019 646 55 38 ¹⁴ and Maines IN 50010 (Sis) 281-2128	3.8/8 ROCCON DEIMITA SSIT	3316 South Ave Down th SOUTH GIS 9750335	Pontollay 2747 E.ELM ST. DSM_ IA SO317 CUS 262-1194 Sonaled 2747 E Elm St Dermomos TA 50317515 3676755
1. Gobriela Arzola 2500	2. Maria Rodriguez 3. Diego Macelli	4. Amparo dezamo	Emand	9. Localin Contieras	11. Muen Dont May

With the recent fatality on June 17, 2008, at the corner of SE 28th and Scott Streets on Des Moines's Southeast side, the concerned families in the area hereby petition for the changing of the truck route that includes both Scott and SE 28th Streets be rerouted to exclude these streets and, instead, include SE 18th and Maury which would not be within a residential area.

The residents in support of this petition are signed below:

NAME	ADDRESS	PHONE NUMBER
1. TUNI LUNNY	2604 Mawry St. Dms TA 50317	3561340S
2. Col morel	least settist Dom IA feely	251-199
3. Shawn Kannenberg	LIEDS HIT-WAY to HAR JS HIG	577-9856
4. Tennifer Kannaberg	624 SE 2844 St DSM-IA 50317	9586-LLS
5. S CARLOS GLARGER	630SEZGTHST DENTA SOTT	2652428
6. Wight tamiler	654250 Hist. DSM IT 450317	265.0631
7. Desduarrus Taylor	205 George St Hartbud In souls	210-6267
8 onnie Larson	1325 Nardin Dr Grlisse 14 50047	210-3773
9. Denvis Timber	2800 SUM AVE. DW 7A 50317	6 kal- 2 h 2 - 5 15
10. Sing Rhuile	2630 2004 446 BDM. IA. 50317	515-453-6331
11. Hearthur Domielson	2830 Scott AUP N.N. IA SO317	515-953-6331
12. White Marie Br	917 8 The SMAD Altan, SUNG 917-1484	915-1484

With the recent fatality on June 17, 2008, at the corner of SE 28th and Scott Streets on Des Moines's Southeast side, the concerned families in the area hereby petition for the changing of the truck route that includes both Scott and SE 28th Streets be rerouted to exclude these streets and, instead, include SE 18th and Maury which would not be within a residential area.

The residents in support of this petition are signed below:

NAME	ADDRESS	PHONE NUMBER
1. Juna Nonuclu Bun	TIE OF SE OF A NM IT A BEST	
2. To the French 1	218 SEART AF NUM IA SAST	1
3. Netre Themanda	715 DE 28+ 11 NM TA 51317	\int
4 Dexxer Jont	4128 Empliser DSMITT 9 50317	1
5 Nimle McEdden	2227 Elm DAM, ZH S217	313-10731
· Brittanu Ramièrez	202 Coulder aver Den Ja 20315	\$72.098
7. Dholler Olonnoll	377 DANHERANG DEMITA SOZIS	
B. Deagu mundell	013 DOLKST DESCRIPTA SOMO9	
9. hord /	EDELM # DSM. IH SORIT	
10. LOCHONCE RENNUS	407 Hundford OSM, A. 50314	12845-Pala
11. Kupp Komug	424 TULEN PLEASANH HILLA. 50527	
12. Pulal A Come St	424 Tyler Pleasant Aill, A. SO377 Weeg-3328	Weeg-3328

With the recent fatality on June 17, 2008, at the corner of SE 28th and Scott Streets on Des Moines's Southeast side, the concerned families in the area hereby petition for the changing of the truck route that includes both Scott and SE 28th Streets be recouted to exclude these streets and, instead, include SE 18th and Maury which would not be within a residential area.

The residents in support of this petition are signed below:

NAME	ADDRESS	PHONE NUMBER
1. Christy Logman	101 SE 28TDSH Des Maines, 14. 50317	512-01012-515
2. Durintur Line	1014 ST 28 St. DOSMDINOS IA 50819	5152621715
3. Millet	WILL ST 28th St. Des Moines IA 50319	5152021715
4 Davance Scott	2016 Orgines St Knowills IA. Cold S.E. 28 15 St DAT SEGT 253-218-9201	641 523-218-9201
5. Billecollaton	616 SE Sturgt. DN IN. 52217	52317 2660790
6. Certor Rea M	LUID SE ZUTA & DEM, H. SUZIA	SPCO-2J212
7. Douthe Solt	606 S.F. 384 DSm da S0317	366-8614
8. thank w 200	606 S.E. 389 84 DSm da 50317	266-8614
2. But of alm	LICSICIZAME DSM TO SOZT 200-8624	266-5624
10. Charly Avenue	768583800 DSM IA 50317	an But
11. De Lago Huy /	600SE28th St DSMLA SO317	729-7010
12. MICHAR ALLANEN	600 St 28th ST DSM 14 STRIT	0102-602

With the recent fatality on June 17, 2008, at the corner of SE 28th and Scott Streets on Des Moines's Southeast side, the concerned families in the area hereby petition for the changing of the truck route that includes both Scott and SE 28th Streets be rerouted to exclude these streets and, instead, include SE 18th and Maury which would not be within a residential area.

The residents in support of this petition are signed below:

PHONE NUMBER (515) (181 - (039)		10-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	210-210-	210-
2009 10 ^{+h} 51 5W Altoona I A 5009 (515) (161 - (0335)	2435 Logan Aue Desmoines 7 A 50313 - 2435 Logan Auenes moines 7 A50317 -	1	SURE. Manon Knokille, A.SBS Tull-891-9326 5107 Convon Lane Son Anton, 78219 210-	5107 Crown Lave Sunthhnic, TK. 782A 210- 5127 Crown Lane SunthhnichTX 76819 -
1. Brandon Schrodur	3. Shawna thill 4. Vanny Kill	al Rumus	8. Chins Clybourd	10. Ever Torres 11. Amy ChiDM

With the recent fatality on June 17, 2008, at the corner of SE 28th and Scott Streets on Des Moines's Southeast side, the concerned families in the area hereby petition for the changing of the truck route that includes both Scott and SE 28th Streets be rerouted to exclude these streets and, instead, include SE 18th and Maury which would not be within a residential area.

The residents in support of this petition are signed below:

AA 366 Ques-lougx PHONE NUMBER 24 Minted 266 -1619 362-0148 326-075 50317 418-2661 マシの くろう 3327 IT DRU 121 Ja 5031 2510 Shaw St DSM IA 50317 078 ×1 mm + 2020 Ł ADDRESS 3700 E 315/24 Ant 12 MAN 2841 Kaccom St 3 284 Raccoon St UtCC シア JARK Grant 2328 6415 21912 x X 3 5 mall JOH Penhala 4 KO 3 AND (NULLY NAME HCon Mel S.I Racha Y Usal. an 12. The w 8. 1 11. 10. 6 R 6 N en i 4

With the recent fatality on June 17, 2008, at the corner of SE 28^{th} and Scott Streets on Des Moines's Southeast side, the concerned families ir the area hereby petition for the changing of the truck route that includes both Scott and SE 28^{th} Streets be recouted to exclude these streets and, instead, include SE 18th and Maury which would not be within a residential area.

The residents in support of this petition are signed below:

NAME	ADDRESS	PHONE NUMBER
1. Maryzeth Briffin	1013E Watrous Ave DSM SD315	787-0984
2. Makanani Scarlett	4030 second Ave	
3. Sale Schuler	118 Farmingdale Dr. Harpersville, Al. 3507	
4 Slerry & locale	118 Farming dale Dr. Hugesville, Al. 3208	
5. The IRI	110 Farming date Dr. Harpers ville, Ali 35078	
e. Aniley Risius	St Des	
7. Freddy Kisius	5132 SW 240 & Des Maines, H. 5035	
8. Diana Dietrich	1103 NINTAG ESthennile, H. SI334	
2 Ardrav Dieterich	1103 N. 644. ESHRANIL, A. 51334	
10. CERTENNATION	616 56 28th St DESMENES 1A 50317	
11. Chris Nath	2535 county line rd. 121 191 50321	
2530 MANNUM 2535	2535 county i'merd lot 191 50321	

Con la fatalidad reciente el 17 de junio de 2008, en la esquina de SE 28th y las calles de Scott en el lado suroriental del DES Moines, las familias en cuestión en el área solicitan por este medio para cambiar de la ruta del carro que incluye a Scott y a SE 28th Las calles se reencaminen para excluir estas calles y, en lugar, para incluir SE 18th y Maury que no estaría dentro de un área residencial. Firman a los residentes en apoyo de esta petición abajo:

NÚMERO DE TELÉFONO	515-440-8723									
ри (7473 yearling Sr. Oscarla 50213									
NOMBRE	1. Luis barcua 2. Catheriel Brundidge	3. 4.	5.	6.	7.	8.	9.	10.	11.	12.

48A