

BDH-IA

Date July 26, 2010

WHEREAS, the property located at 2620 Cornell Street, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure and garage structure in their present conditions constitute not only a menace to health and safety but are also a public nuisance; and

WHEREAS, the Titleholder Marsha J. Wheeler was notified more than thirty days ago to repair or demolish the main structure and as of this date has failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA, AND SITTING AS THE LOCAL BOARD OF HEALTH:

The main structure and the garage structure on the real estate legally described as LOT 14 MARTHA HALL HGTS PLAT 2, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 2620 Cornell Street, have previously been declared a public nuisance;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said main structure and garage structure.

Moved by_____to adopt.

FORM APPROVED: Vicky Long Mill. Assistant City Attorney

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT	CERTIFICATE
COWNIE					
COLEMAN					I, DIANE RAUH, City Clerk of said City hereby
GRIESS					certify that at a meeting of the City Council of
HENSLEY					 said City of Des Moines, held on the above among other proceedings the above was adop
MAHAFFEY					
MEYER					IN WITNESS WHEREOF, I have hereunto set my
MOORE	1.0				hand and affixed my seal the day and year first above written.
TOTAL					
MOTION CARRIED			A	PPROVED	
				Manar	City Clerk



Polk County Assessor

[Home] [General Query] [Legal Query] [HomeOwner Query] [Book/Page Query] [Commercial Query] [Res Sales Query] [Comm Sales Query] [Help]

District/Parcel	GeoParcel	Мар	Nbhd	Jurisdiction	Status
070/03114-000-000	7924-26-308-041	0836	DM86/Z	DES MOINES	ACTIVE
School District	Tax Increment Finance District	Bond	/Fire/Sew	er/Cemetery	
1/Des Moines				н	
Street Address			City Stat	e Zipcode	
2620 CORNEI	LST		DES MO	DINES IA 50313-	4839

		1110	Clic	k on parc	el to get i	new	listii	ng		
		27 14	-	27 13	27 16 :		27 17		27 10	5
	_	27 10	1	2709	27 12 :	ſ	27 13	i i	27 13	2
		2706		2705	2708 : 110.47	1	2709		2700	3
		2700	1	2703	2704 : 110 58		2705	5	270	¢ -
Get		2624	54.85	100	2700		2701	1	2700)
<u>Bigger</u>		2620	= }	2623 4 36	2620 110,75	1	2621		262) :
Map		2916	20	2619 18	26 16 10.85	-	2619		2614	÷ ۱
		53.76号半3	70-1	127.40	2612 ±	11.	2615	5		-
		17 1 17 1	5-25	2509 🐇	2606 *	-	2611		2610	Ĵ
	2	148206	13	65 37 5 2	2504	50				-
	57 737	2500 548 37,3	17 50	200 208 65.75 62	2600 m 111 25 2	525		310	314	318 022



Approximate date of photo 01/19/2005

Mailing Address


MARSHA J WHEELER 2620 CORNELL ST DES MOINES, IA 50313-4839

Legal Description

LOT 14 MARTHA HALL HGTS PLAT 2

Ownership	Name		Recorded	Book/Pag	e Re	vStamps
Title Holder #1	WHEELER, M	ARSHA J	2000-02-14	8428/452		
Assessment	Class	Kind	Land	Bldg	AgBd	Total
Current	Residential	Full	14,000	53,000	0	67,000
Market Adju	isted Cost Report	Estimate Taxes Taxe	Polk County	Treasurer Ta	x Informa	tion Pay

Taxable Value	xable Value Credit Name				Number	Info	
Homestead	Iomestead		WHEELER, MARSHA J				
Zoning	oning Description			SF	Assesso	Zoning	
R1~60	One Family, Lov	w Density Reside	ential District		Resident	ial	
*Condition	Docket_no 1436	j1					
Source: City of	Des Moines Com		ment Published: 1 515 283-4200	2010-03-0:	5 Contact	Planning and	
Land					hanna ^s ado' Alderen Mann ay B		
SQUARE FEET	5,550	FRONTAGE	50.0	DEPTH		111.0	
ACRES	0.127	SHAPE	RC/Rectangle	TOPOGRAPHY		N/Normal	
Residence # 1							
OCCUPANCY	SF/Single Family	RESID TYPE	S1/1 Story	BLDG ST	FYLE	RN/Ranch	
YEAR BUILT	1941	# FAMILIES	1	GRADE		4	
GRADE ADJUST	-10	CONDITION	BN/Below Normal	TSFLA		744	
MAIN LV AREA	744	BSMT AREA	744	FIN BMT AREA	C	350	
FIN BMT QUAL	LO/Low	OPEN PORCH	32	FOUNDA	ATION	B/Brick	
EXT WALL TYP	MT/Metal Siding	ROOF TYPE	GB/Gable	ROOF MATERI	C	A/Asphal Shingle	
HEATING	A/Gas Forced Air	AIR COND	100	BATHRO	DOMS	1	
BEDROOMS	2	ROOMS	4				



Detached # 101					Martin
OCCUPANCY	GAR/Garage	CONSTR. TYPE	FR/Frame	MEASCODE	D/Dimensions
MEASURE1	14	MEASURE2	24	STORY HEIGHT	1
GRADE	5	YEAR BUILT	1954	CONDITION	PR/Poor

Year	Туре	Class	Kind	Land	Bldg	AgBd	Total
2009	Assessment Roll	Residential	Full	14,000	53,000	0	67,000
2007	Assessment Roll	Residential	Full	13,300	50,400	0	63,700
2005	Assessment Roll	Residential	Full	11,100	54,100	0	65,200
2003	Assessment Roll	Residential	Full	9,820	48,760	0	58,580

http://www.assess.co.polk.ia.us/cgi-bin/invenquery/allquery.cgi

2001	Assessment Roll	Residential	Full	9,100	44,870	0	53,970
1999	Assessment Roll	Residential	Full	8,830	41,390	0	50,220
1997	Assessment Roll	Residential	Full	7,930	37,150	0	45,080
1995	Assessment Roll	Residential	Full	7,030	32,950	0	39,980
1993	Assessment Roll	Residential	Full	5,960	27,940	0	33,900
1990	Assessment Roll	Residential	Full	5,960	26,540	0	32,500

email this page

Room 195, 111 Court Avenue, Des Moines, IA 50309 Phone 515 286-3140 / Fax 515 286-3386 polkweb@assess.co.polk.ta.us



PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA



DATE OF NOTICE: Febru	ary 18, 2010	DATE OF INSPECTION:	February 12, 2010
CASE NUMBER:	COD2010-00562		
PROPERTY ADDRESS:	2620 CORNELL ST		
LEGAL DESCRIPTION:	LOT 14 MARTHA HALL HG	TS PLAT 2	2
MARSHA J WHEELER			

Title Holder 612 NE 4TH ST APT 4 GRIMES IA 50111

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-304 and 60-306 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. Failure to correct these violations will result in legal action. The violations noted must be corrected within 30 days from the date of this notice. The violations will result in a request to the City Council, sitting as the board of Health, to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

BREEDEND MOULDED DEDITION TO THE AND A DE THE ARE THE

NAMES OF A DESCRIPTION OF A DESCRIPTIONO

Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the city may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the Polk county Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Vince Travis

(515) 283-4077 limco.

Nid Inspector

DATE MAILED: 2/18/2010

MAILED BY: JDH

\\CDMAPPS1\D-VOLUME\APPDATA\Tidemark\prd 41\Forms & Reports\dsmCODPubNo.rp

BDH-IA

Areas that need attention: 2620 CORNELL ST

Component:	Exterior Doors/Jams	Defeat	Caralia (/Darline
	Extenor Doors/Jams	Defect:	Cracked/Broken
Requirement:			
		Location:	Garage
Comments:			
1 .			
Component:	Exterior Walls	Defect:	Deteriorated
Requirement:	Building Permit	Martin Chi	Detenorated
<u>Acquirementa</u>	Dunung Ferrin	Lassification	C
0		Location:	Garage
Comments:			
Component:	Roof	Defect:	Deteriorated
Requirement:	Building Permit		
	building remne	Location:	Camera
Comments:		Location	Galage
<u>comments:</u>			
Component:	Bathroom Lavatory	Defect:	Cracked/Broken
Requirement:	Plumbing Permit		
	5	Location:	Main Structure
Comments:			
Ē			
Component:	Electrical System	Defect:	In disrepair
Requirement:	Electrical Permit		
		Location:	Main Structure
Comments:			
Component:	Electrical Lighting Eisturge	Defect:	Ta disessaio
219 C 4	Electrical Lighting Fixtures	Delecti	In disrepair
Requirement:	Electrical Permit		
		Location:	Main Structure
Comments:			
Component:	Electrical Other Fixtures	Defect:	În disrepair
Requirement:	Electrical Permit		in distopul
		Location	Main Christian
Commenter		LUCATION:	Main Structure
Comments:			
Component:	Floor Joists/Beams	Defect:	In poor repair
Requirement:	Building Permit		
		Location*	Main Structure
Comments:		TARK CALL	
			· · · · · · · · · · · · · · · · · · ·

6			
<u>Component:</u> <u>Requirement:</u>	Flooring Building Perma	Defect:	Detrinrated
100		Location:	Main Structure
<u>Comments:</u>			
<u>Component:</u> <u>Requirement:</u>	Functioning Water Closet Plumbing Permit	Defect:	Cracked/Broken
Comments:	Fighting Ferring	Location:	Main Structure
Component:	Furnace	Defect:	To disconcio
Requirement:	Mechanical Permit	Delect:	In disrepair
Comments:		Location:	Main Structure
Component:	Interior Stairway	Defect	În poor repair
Requirement:	Building Permit	Location:	Main Structure
<u>Comments:</u>			
Component:	Interior Walls /Ceiling	Defect:	Cracked/Broken
<u>Requirement:</u>	Building Permit	Location:	Main Structure
Comments:			
Component:	Mechanical System	Defect:	In poor repair
<u>Requirement:</u>	Mechanical Permit	Location:	Main Structure
<u>Comments:</u>			
<u>Component:</u> <u>Requirement:</u>	Plumbing System Plumbing Permit	Defect:	In disrepair
Comments:		Location:	Main Structure
	· · ·		
Component:	62 Diumhing Dormit	Defect:	Cracked/Broken
<u>Requirement:</u>	Plumbing Permit	Location:	Main Structure
<u>Comments:</u>			
<u>Component:</u> <u>Requirement:</u>	Shingles Flashing Building Permit	Defect:	In poor repair
Comments:	- adding i or file	Location:	Main Structure

Component: Requirement: Comments:	Kitchen Sink Plumbing Perture	<u>Defect:</u> Location:	In r repair Kitchen
Component: Requirement: Comments:	Smoke Detectors	Defect: Location:	Missing Main Structure
<u>Component:</u> <u>Requirement:</u> <u>Comments:</u>	Foundation Building Permit	Defect: Location:	In poor repair Main Structure
<u>Component:</u> <u>Requirement:</u> <u>Comments:</u>	Soffit/Facia/Trim	<u>Defect:</u> Location:	In poor repair Main Structure
Component: Requirement: Comments:	Tub/Shower Walls Plumbing Permit	<u>Defect:</u> <u>Location:</u>	Cracked/Broken Main Structure
Component: Requirement: Comments:	Water Heater Plumbing Permit	Defect: Location:	In poor repair Main Structure
Component: Requirement: Comments:	Window Glazing/Paint	Defect: Location:	În poor repair Main Structure
Component: Requirement: Comments:	Windows/Window Frames Building Permit	Defect: Location:	In poor repair Main Structure
Component: Requirement: Comments:	Exterior Walls	<u>Defect:</u> <u>Location:</u>	Absence of paint Garage

BDH 1-A

