



Date September 27, 2010

WHEREAS, the property located at 2120 Washington Avenue, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure in its present condition constitutes not only a menace to health and safety but is also a public nuisance; and

WHEREAS, the Titleholder 610 40th, LLC and Contract Buyers: Lester Small and Portia Small, were notified more than thirty days ago to repair or demolish the main structure and as of this date have failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA, AND SITTING AS THE LOCAL BOARD OF HEALTH:

The main structure on the real estate legally described as LOT 18 WILLIAMS 3RD ADDITION TO DES MOINES, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 2120 Washington Avenue, has previously been declared a public nuisance;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owners fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said main structure.

Moved by to adopt.

FORM APPROVED:

Vicky Long Hill, Assistant City Attorney

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT
COWNIE				
COLEMAN				
GRIESS				
HENSLEY				1
MAHAFFEY				
MEYER				
MOORE				
TOTAL				
MOTION CARRIED			A	PPROVED

CERTIFICATE

I, DIANE RAUH, City Clerk of said City hereby certify that at a meeting of the City Council of said City of Des Moines, held on the above date, among other proceedings the above was adopted.

IN WITNESS WHEREOF, I have hereunto set my hand and affixed my seal the day and year first above written.

**	City Clerk
Mayor	City Citik



PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA



DATE OF NOTICE: August 5, 2010

DATE OF INSPECTION:

June 08, 2010

CASE NUMBER:

COD2010-03969

PROPERTY ADDRESS:

2120 WASHINGTON AVE

LEGAL DESCRIPTION:

LOT 18 WILLIAMS 3RD ADDITION TO DES MOINES

610 40TH, LLC Title Holder JOHN DAVIS - REG. AGENT 431 28TH ST DES MOINES IA 50312

LESTER SMALL & PORTIA SMALL Contract Buyer 5504 MEREDITH DR APT 15 DES MOINES IA 50310

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-304 and 60-306 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. Failure to correct these violations will result in legal action. The violations noted must be corrected within 30 days from the date of this notice. The violations noted must be corrected within 30 days from the date of this notice. Failure to correct these violations will result in a request to the City Council, sitting as the board of Health, to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.



Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the city may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the Polk county Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Neighborhood Inspection Division

Eni Moun

(515) 283-4208

Nid Inspector

DATE MAILED: 8/4/2010

MAILED BY: TSY



Areas that need attention: 2120 WASHINGTON AVE

Defect: In poor repair Component: Exterior Walls Compliance, International Property Requirement: Location: Maintenance Code **Comments:** Defect: Missing Sections Exterior Walls Component: Requirement: Compliance, International Property Maintenance Code Location: **Comments:** Exterior Walls Defect: not impervious to water Component: Requirement: Compliance, International Property **Location:** Maintenance Code **Comments: Defect:** In poor repair Exterior Doors/Jams Component: **Requirement:** Location: **Comments: Defect:** In poor repair Component: Soffit/Facia/Trim **Requirement:** Location: Comments: Defect: Soffit/Facia/Trim Missing Component: **Requirement:** Location: **Comments:** Defect: Missing Component: Flooring **Requirement: Location:** Throughout **Comments:** Defect: In poor repair Component: Flooring Requirement: **Location:** Throughout **Comments:**

Component: Bathroom Lavatory Defect: Missing BDHID Requirement: Plumbing Permit **Location:** Comments: Defect: Missing Sections Component: Ductwork **Requirement:** Mechanical Permit **Location:** Basement **Comments:** Electrical Lighting Fixtures Defect: In poor repair Component: **Requirement:** Location: Comments: Electrical Lighting Fixtures Defect: Missing Component: Requirement: **Electrical Permit Location:** Throughout **Comments:** Electrical Other Fixtures Defect: In poor repair Component: Requirement: **Electrical Permit** Location: **Comments:** Electrical System Defect: In poor repair Component: **Electrical Permit** Requirement: Location: Comments: Must be done by licensed electrician with permit Floor Joists/Beams **Defect:** In poor repair Component: Requirement: **Engineering Report Location:** Basement Comments: Component: Foundation Defect: In poor repair **Requirement: Engineering Report Location:** Basement **Comments: Defect:** In poor repair Component: Functioning Water Closet Plumbing Permit **Requirement:** Location: Bathroom **Comments:**

	_			
Component:	Furnace	Defect:	In poor repair	
Requirement:		Location:	Basement	
Comments:	Must be checked for safe operable conditi			
	Must be checked for sale operable colldic	on by reput	able company.	
Component:	Water Heater	Defect:	In poor repair	
Requirement:				
Comments:		Location:	Basement	
<u>comments.</u>	Must be checked for safe operable condition	on by reput	able comp any.	
Component:	Gas Lines	Dofostu	T	
Requirement:	Gas Lines	Defect:	In poor repair	
		Location:		
Comments:	Must be checked for safe operable condition	on by reput	able company.	
	The second of th	on by ropus	abic company	
Component:	Ground Fault Circuit Interrupters	Defect:	Not Supplied	
Requirement:	Electrical Permit	Locations		
Comments:		<u>Location:</u>		
	Kitchen & bathroom			
Component:	Hand Rails	Defect:	Not Supplied	
Requirement:	riana ivans	Defecti	Not Supplied	
		Locations	Decomont	
		Location:	Basement	
Comments:		Location:	basement	
Comments:		Location:	basement	
Comments:		Location:	basement	
Component:	Interior Stairway	Defect:	In poor repair	
	Interior Stairway Building Permit	Defect:	In poor repair	
Component:	•	Defect:		
Component: Requirement:	•	Defect:	In poor repair	
Component: Requirement:	•	Defect:	In poor repair	
Component: Requirement:	Building Permit	Defect: Location:	In poor repair Basement	
Component: Requirement: Comments:	•	Defect: Location: Defect:	In poor repair Basement In poor repair	
Component: Comments: Comments: Component: Requirement:	Building Permit	Defect: Location: Defect:	In poor repair Basement	
Component: Requirement: Comments: Component:	Building Permit	Defect: Location: Defect:	In poor repair Basement In poor repair	
Component: Comments: Comments: Component: Requirement:	Building Permit	Defect: Location: Defect:	In poor repair Basement In poor repair	
Component: Requirement: Comments: Component: Requirement: Comments:	Building Permit Interior Walls /Ceiling	Defect: Location: Defect: Location:	In poor repair Basement In poor repair Throughout	
Component: Requirement: Comments: Component: Requirement: Comments:	Building Permit	Defect: Location: Defect:	In poor repair Basement In poor repair	
Component: Requirement: Comments: Component: Requirement: Comments:	Building Permit Interior Walls /Ceiling	Defect: Location: Defect: Location:	In poor repair Basement In poor repair Throughout	
Component: Requirement: Comments: Component: Requirement: Comments:	Building Permit Interior Walls /Ceiling	Defect: Location: Defect: Location:	In poor repair Basement In poor repair Throughout	
Component: Requirement: Comments: Component: Requirement: Comments:	Building Permit Interior Walls /Ceiling	Defect: Location: Defect: Location:	In poor repair Basement In poor repair Throughout	
Component: Requirement: Comments: Component: Requirement: Comments:	Building Permit Interior Walls /Ceiling	Defect: Location: Defect: Location:	In poor repair Basement In poor repair Throughout	
Component: Requirement: Comments: Component: Requirement: Comments:	Interior Walls /Ceiling Interior Walls /Ceiling	Defect: Location: Defect: Location: Defect: Location:	In poor repair Basement In poor repair Throughout In poor repair	nt
Component: Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments:	Building Permit Interior Walls /Ceiling	Defect: Location: Defect: Location: Defect: Location:	In poor repair Basement In poor repair Throughout	nt
Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Requirement: Requirement:	Interior Walls /Ceiling Interior Walls /Ceiling	Defect: Location: Defect: Location: Defect: Location:	In poor repair Basement In poor repair Throughout In poor repair	nt
Component: Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments: Comments:	Interior Walls /Ceiling Interior Walls /Ceiling	Defect: Location: Defect: Location: Defect: Location:	In poor repair Basement In poor repair Throughout In poor repair	nt


Component: Kitchen Sink Defect: In poor repair Requirement: Location: Kitchen Comments: Missing Where Required Shutoff Valves Defect: Component: **Requirement:** Plumbing Permit **Location: Comments:** Kitchen & bathroom Component: **Smoke Detectors** Defect: Missing Where Required **Requirement: Location:** Throughout Comments: Tub/Shower Walls Component: **Defect:** Missing Requirement: **Location:** Bathroom **Comments:** No tub or shower **Component:** Waste Lines **Defect:** In poor repair Requirement: Plumbing Permit **Location:** Throughout Comments: Defect: Not Supplied Component: Water Service **Requirement:** Location: **Comments:** Component: Wiring Defect: Exposed Requirement: **Electrical Permit Location:** Comments: Various locations Defect: Component: Plumbing System In poor repair **Requirement:** Plumbing Permit **Location:** Throughout **Comments:** Must be done by licensed plumber





[Home] [General Query] [Legal Query] [HomeOwner Query] [Book/Page Query] [Commercial Query] [Res Sales Query] [Comm Sales Query] [Help]

District/Parcel	GeoParcel	Map	Nbhd	Jurisdiction	Status		
080/07336-000-000	7924-33-256-003	0184	DM75/Z	DES MOINES	ACTIVE		
School District Tax Increment Finance District		Bond/Fire/Sewer/Cemetery					
1/Des Moines		and a second second second		and the second s			
Street Address			City State Zipcode				
2120 WASHINGTON AVE			DES MOINES IA 50310				





Approximate date of photo 02/14/2004

Mailing Address

610 40TH, LLC POB 12282 DES MOINES, IA 50312

Legal Description

LOT 18 WILLIAMS 3RD ADDITION TO DES MOINES

Ownership	Name	Recorded	Book/Page	RevStamps
Title Holder #1	610 40TH, LLC	2010-07-09	13503/747	
Contract Buyer #1	SMALL, LESTER	2006-12-12	11988/311	
Contract Buyer #2	SMALL, PORTIA			

Assessment	Class	Kind	Land	Bldg	AgBd	Total
Current	Residential	Full	7,200	3,400	0	10,600
Market Adjusted Cost Report		Assessment Roll N	Notice Estin	nate Taxes	Polk County	Treasurer




Tax Information Pay Taxes

Zoning	Description	SF	Assessor Zoning
R1-60	One Family, Low Density Residential District		Residential
Source: (City of Des Moines Community Development Published: Urban Design 515 283-4200	2010-03-	05 Contact: Planning and

Land					
SQUARE FEET	5,650	FRONTAGE	45.0	DEPTH	125.0
ACRES	0.130	SHAPE	RC/Rectangle	TOPOGRAPHY	N/Normal

Residence # 1					^~
OCCUPANCY	SF/Single Family	RESID TYPE	S1/1 Story	BLDG STYLE	BG/Bungalow
YEAR BUILT	1900	# FAMILIES	1	GRADE	5
GRADE ADJUST	+05	CONDITION	VP/Very Poor	TSFLA	786
MAIN LV AREA	786	BSMT AREA	283	ENCL PORCH	192
FOUNDATION	B/Brick	EXT WALL TYP	WS/Wood Siding	ROOF TYPE	GB/Gable
ROOF MATERL	A/Asphalt Shingle	HEATING	A/Gas Forced Air	AIR COND	O
BATHROOMS	1	BEDROOMS	2	ROOMS	5





Seller	Buyer	Sale Date	Sale Price	Instrument	Book/Page
TAX ACQUISTIONS	SMALL, LESTER	2006-12- 05	35,000	C/Contract	11988/311
PRIMO ACQUISITIONS, I L.L.C.	CASH CONSULTANTS, LC	2002-12- 30	10,000	D/Deed	9546/925
PRIMO ACQUISITIONS, I L.L.C.	LUNA, JUDD G	2000-12-	60,000	C/Contract	8708/399
PRIMO ACQUISITIONS, I L.L.C.	LUNA, JUANA GONZALEZ	2000-11- 27	60,000	C/Contract	8647/620

Year	Type	Status	Application	Permit/Pickup Description
2010	U/Pickup	CP/Complete	2009-07-07	RV/BOARD OF REVIEW
The state of the s	and dispussion			

Page 4 of 4




1998	U/Pickup NA/N	o Add 199	Add 1998-03-16		RV/ABATEMENT FILED			
Year	Type	Class	Kind	Land	Bldg	AgBd	Total	
2010	Assessment Roll	Residential	Full	7,200	3,400	0	10,600	
2009	Board Action	Residential	Full	7,200	13,700	0	20,900	
2009	Assessment Roll	Residential	Full	7,200	30,800	0	38,000	
2008	Assessment Roll	Residential	Full	6,900	29,600	0	36,500	
2007	Assessment Roll	Residential	Full	6,900	29,600	0	36,500	
			Adj	6,900	26,930	0	33,830	
2005	Assessment Roll	Residential	Full	4,200	23,700	0	27,900	
**************************************		To the state of th	Adj	4,200	21,030	0	25,230	
2003	Assessment Roll	Residential	Full	3,410	19,440	0	22,850	
			Adj	3,410	16,770	0	20,180	
2001	Assessment Roll	Residential	Full	3,630	15,340	0	18,970	
			Adj	3,630	14,570	0	18,200	
1999	Assessment Roll	Residential	Full	3,830	19,840	0	23,670	
		To a contract of the contract	Adj	3,830	17,170	0	21,000	
1998	Assessment Roll	Residential	Full	3,540	18,320	0	21,860	
			Adj	3,540	15,650	0	19,190	
1997	Board Action	Residential	Full	3,540	18,320	0	21,860	
1997	Assessment Roll	Residential	Full	3,540	18,320	0	21,860	
1995	Board Action	Residential	Full	3,330	17,240	0	20,570	
1995	Assessment Roll	Residential	Full	3,330	17,240	0	20,570	
1989	Assessment Roll	Residential	Full	2,880	14,920	0	17,800	


email this page

Room 195, 111 Court Avenue, Des Moines, 1A 50309 Phone 515 286-3140 / Fax 515 286-3386 polkweb@assess.co.polk.ia.us


BDHI-D



BDHI-D



BDH1-D



BDH1-D

