



Date January 23, 2012

WHEREAS, the property located at 1327 24th Street, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure in its present condition constitutes not only a menace to health and safety but is also a public nuisance; and

WHEREAS, the Titleholder AJD Properties, LLC and the Mortgage Holder Northwest Bank were notified more than thirty days ago to repair or demolish the main structure and as of this date have failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA, AND SITTING AS THE LOCAL BOARD OF HEALTH:

The main structure on the real estate legally described as LOT 20 UNIVERSITY PLACE, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 1327 24th Street, has previously been declared a public nuisance;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said main structure.

Moved by_____to adopt.

FORM APPROVED:

Vicky Long Hill, Assistant City Attorney

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT	CERTIFICATE
COWNIE					
COLEMAN					I, DIANE RAUH, City Clerk of said City herek certify that at a meeting of the City Council
GRIESS					said City of Des Moines, held on the above dat
HENSLEY					among other proceedings the above was adopted
MAHAFFEY					IN WITHERS WHEREOF I have become as a
MEYER					IN WITNESS WHEREOF, I have hereunto set m hand and affixed my seal the day and year fir
MOORE					above written.
TOTAL					
MOTION CARRIED			A	APPROVED	
				Mayor	City Clerl



Polk County Assessor [CAD3

[Home] [General Query] [Legal Query] [HomeOwner Query] [Book/Page Query] [Commercial Query] [Res Sales Query] [Comm Sales Query] [Help]

District/Parcel	GeoParcel	Map	Nbhd	Jurisdiction	Status	
080/06898-000-000		0156	DM75/Z	DES MOINES	ACTIVE	
School District	Tax Increment Finance District	Bond/Fire/Sewer/Cemetery				
1/Des Moines						
Street Address			City Sta	te Zipcode		
			DES MO	DINES IA 50311		

1327 24TH SI

Click on parcel to get new listing 92 5 1335 1355 5 80 64¹⁶²²98 c 1337 40 532.60 1333 127.5 127.5 QD. Get 162 Bigger 1330 : 1331 -23RD-24-T-H-S-T Map 1324 = 1327 2410 ဟ် 1322 ÷ 1325 Google = Map 1318 1323 : 1314 : 1321 1310,162 ÷ 06.4 1317 =

Approximate date of photo 06/01/2011

Mailing Address


A J D PROPERTIES, LLC 9902 SWANSON BLVD CLIVE, IA 50325-6932

Legal Description

Ownership	Name]	Recor	ded	Book/Page	e Re	evStamps
Title Holder #1 A J D PROPERTIES, LL		LC 2011-04-25		13832/841			
Assessment	Class	Kind		Lan	d Bldg	AgBo	d Tota
Current	Commercial Multiple	Full		14,40	0 7,500	(0 21,900
Protest 1	Notice Assessment Roll Not Inform		imate ay Ta:		Polk County	Treasur	er Tax
Zoning De	scription			SF	Assessor Zo	ning	

http://www.assess.co.polk.ia.us/cgi-bin/invenquery/allquery.cgi

Multi-Family Residential Multiple Family Residential District R-3 Source: City of Des Moines Community Development Published: 2011-05-25 Contact: Planning and Urban Design 515 283-4200 Land 0.198 TOPOGRAPHY B/Blank SQUARE FEET 8,618 ACRES **Commercial Summary** 1B/Apartment WEIGHTED STORY 2 1897 **OCCUPANCY** HEIGHT Conversion AGE FINISH 2,085 2,085 LAND AREA 8.618 **GROSS AREA** AREA NUMBER 3 0 601 **BSMT FINISH BSMT UNFIN** UNITS **Residence #1** YEAR 1897 CV/Conversion **RESID TYPE** SH/1.5 Stories **OCCUPANCY** BUILT GRADE -05 4 3 GRADE **#FAMILIES** ADJUST MAIN LV 2,085 1,311 VP/Very Poor TSFLA CONDITION AREA **OPEN UPPR LV** 36 601 774 **BSMT AREA** PORCH AREA EXT WALL **GB**/Gable AS/Asbestos **ROOF TYPE** Т FOUNDATION TYP A/Gas Forced A/Asphalt ROOF AIR COND 0 HEATING Shingle Air MATERL 3 **BATHROOMS**



Seller	Buyer	Sale Date	Sale Price	Instrument	Book/Page
JACKMAN, CRAIG A	CRITELLI PROPERTIES, LLC	<u>2007-</u> 02-02	76,900	D/Deed	12068/805
JACKMAN, EDWIN W TRUST/S J JACKMAN EXECU	JACKMAN, CRAIG A & JOEL W	<u>1995-</u> 09-10	55,000	C/Contract	7899/230

Year	Туре	Status	Application	Permit/Pickup Description
Current	U/Pickup	PA/Pass	2011-06-27	RV/Review Value BOARD OF REVIEW

Year	Туре	Appellant	Case	Status
2009	PAAB	CRITELLI PROPERTIES, LLC	09-77-1521	Stipulated
2008	PAAB	CRITELLI PROPERTIES, LLC	08-77-0172	Stipulated

Year	Туре	Class	Kind	Land	Bldg	AgBd	Total
2011	Board Action	Commercial Multiple	Full	14,400	7,500	0	21,900
2011	Assessment Roll	Commercial Multiple	Full	14,400	49,600	0	64,000
2010	Correction	Commercial Multiple	Full	14,400	57,600	0	72,000
2010	Board Action	Commercial Multiple	Full	14,400	64,000	0	78,400
2009	PAAB Order	Commercial Multiple	Full	14,400	57,600	0	72,000
2009	Board Action	Commercial Multiple	Full	14,400	64,000	0	78,400
2009	Assessment Roll	Commercial Multiple	Full	14,400	64,000	0	78,400
2008	PAAB Order	Commercial Multiple	Full	14,400	58,600	0	73,000
2008	Board Action	Commercial Multiple	Full	14,400	64,000	0	78,400
2007	Assessment Roll	Commercial Multiple	Full	14,400	64,000	0	78,400
2006	Assessment Roll	Commercial Multiple	Full	13,100	65,300	0	78,400
2005	Assessment Roll	Commercial Multiple	Full	13,100	49,600	0	62,700
2003	Assessment Roll	Commercial Multiple	Full	11,400	45,100	0	56,500
2001	Assessment Roll	Commercial Multiple	Full	10,770	29,600	0	40,370
1999	Assessment Roll	Commercial Multiple	Full	7,000	29,600	0	36,600
1995	Assessment Roll	Commercial Multiple	Full	6,800	27,400	0	34,200
1993	Assessment Roll	Commercial Multiple	Full	6,430	26,070	0	32,500
1993	Was Prior Year	Commercial Multiple	Full	6,430	22,480	0	28,910

email this page

Room 195, 111 Court Avenue, Des Moines, IA 50309 Phone 515 286-3140 / Fax 515 286-3386 polkweb@assess.co.polk.ia.us



PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA



DATE OF INSPECTION:

December 28, 2010

CASE NUMBER:	COD2010-08823
PROPERTY ADDRESS:	1327 24TH ST
LEGAL DESCRIPTION:	LOT 20 UNIVERSITY PLACE

A J D PROPERTIES, LLC Title Holder MARK A CRITELLI - REG. AGENT 9902 SWANSON BLVD CLIVE IA 50325

NORTHWEST BANK Mortgage Holder PAUL PICK - SR. VICE PRESIDENT 5700 UNIVERSITY, STE 100 WEST DES MOINES IA 50266

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-304 and 60-306 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. Failure to correct these violations will result in legal action. The violations noted must be corrected within 30 days from the date of this notice. The violations noted must be corrected within 30 days from the date of this notice. The violations will result in a request to the City Council, sitting as the board of Health, to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES. Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the city may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Eric Moore (515) 283-4759

Eni Moon

Nid Inspector DATE MAILED: 11/16/2011

MAILED BY: TSY

WCOMADDC11D VOLUME\ADDDATA\Tidemark\ord 41\Forms & Reports\dsmCODPubNo.rp

BDH/D

Areas that need	d attention: 1327 24TH ST		
Component:	Flooring	Defect:	In poor repair
Requirement:		Location:	
Comments:	All 3 units		
	All 5 units		
Component:	Bathroom Lavatory	Defect:	Cracked/Broken
Requirement:		Location:	
Comments:			
	All 3 units		
Component:	Electrical Lighting Fixtures	Defect:	In poor repair
Requirement:		Location:	
Comments:			
	All 3 units		
Component:	Exterior Walls	Defect:	In poor repair
Requirement:		Location:	
Comments:		Location	
Component:	Foundation	Defect:	In poor repair
Requirement:		Location	
Comments:		EUGation	
	Exterior		
Component:	Furnace	Defect:	In poor repair
Requirement:		Location	
Comments:		Location	-
<u>commencer</u>	All furnaces		
Component:	Functioning Water Closet	Defect:	Cracked/Broken
Requirement:		Location	
Comments:		LUCALION	<u>.</u>
Commentar	# 1		
Component:	Water Heater	Defect:	In poor repair
Requirement:		Location	
Comments:		LOCALION	<u>.</u>
	All water heaters		

Component: Requirement:			Insufficient water drainage
		Location:	
Comments:			
Component:	Interior Walls /Ceiling	Defect:	Holes or major defect
Requirement:		Location:	
Comments:	All 3 units		
Component:	Interior Walls /Ceiling	Defect:	Water Damage
Requirement:		Location:	
Comments:	# 1 & 2		
Component:	Roof	Defect:	Improperly Installed
Requirement:		Location:	
Comments:	South side		
Component:	Shingles Flashing	Defect:	In poor repair
<u>Requirement:</u>		Location:	
<u>Comments:</u>			
Component:	Smoke Detectors	Defect:	In poor repair
Requirement:		Location:	<u>.</u>
<u>Comments:</u>	# 1, 2, & 3		
Component:	Soffit/Facia/Trim	Defect:	In poor repair
Requirement:		Location	<u>.</u>
<u>Comments:</u>			
<u>Component:</u> Requirement:	Stairs/Stoop	Defect:	In poor repair
		Location	<u>i</u>
Comments:	2nd egress as well as north entry stairway	1	
Component:	Sub Floor	Defect:	Missing Sections
Requirement:		Location	<u>:</u>
Comments:	# 3		

The second se

component:	Stairs/Stoop	Defect:	Structurally Unsound	3DI-
equirement:		Location:		ALL
<u>comments:</u>	North stairway			
Component:	Sub Floor	Defect:	Structurally Unsound	
Requirement:		Location:		
<u>Comments:</u>	# 1 bathroom			
	Tub/Chourey Walls	Defect:	In poor repair	
<u>Component:</u> Requirement:	Tub/Shower Walls	Location:	III poor	
<u>Comments:</u>	# 1 & 2			
Component:	Waste Lines	Defect:	Missing	
Requirement:		Location:		
<u>Comments:</u>	# 1 bathroom			
Component:	Windows/Window Frames	Defect:	In poor repair	
Requirement:		Location:	2	
<u>Comments:</u>				
Component:	Wiring	Defect:	In poor repair	
<u>Requirement:</u>		Location:	<u>.</u>	
Comments:				
Component:	Wiring	Defect:	Exposed	
Component: Requirement:	Wiring	Defect: Location:		
	Wiring			
Requirement:	Wiring Plumbing System			
<u>Requirement:</u> <u>Comments:</u>		Location: Defect:	<u>:</u>	
Requirement: Comments: Component:		Location: Defect:	: In poor repair	
Requirement: Comments: Component: Requirement:	Plumbing System	Location: Defect:	: In poor repair	
Requirement: Comments: Component: Requirement: Comments:	Plumbing System Must be checked by licensed plumber Mechanical System	Location: Defect: Location	In poor repair In froughout	

Component:	Electrical	System
Requirement:		

Defect: In poor repair

JDH-D


Location: Throughout

Comments: Must be checked by licensed electrician


BDH 1-D












BDH I-D



BDH 1-D







