



Date February 27, 2012

WHEREAS, the property located at 1521 E. Pleasant View Drive, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure in its present condition constitutes not only a menace to health and safety but is also a public nuisance; and

WHEREAS, the Titleholder Doris I. Holloway (Sherman M. Holloway, deceased) was notified more than thirty days ago to repair or demolish the main structure and as of this date has failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA, AND SITTING AS THE LOCAL BOARD OF HEALTH:

The main structure on the real estate legally described as LT 125 OP SW 1/4 SW 1/4 -EX N 20 F- SEC 14-78-24, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 1521 E. Pleasant View Drive, has previously been declared a public nuisance;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said main structure.

Moved by \_\_\_\_\_to adopt.

FORM APPROVED:

Vicky Long Hill, Assistant City Attorney

COWNIE COLEMAN GRIESS			
GRIESS			I, DIANE RAUH, City Clerk of said City hereb certify that at a meeting of the City Council of
			said City of Des Moines, held on the above date
HENSLEY			among other proceedings the above was adopted.
MAHAFFEY			THE AUTOR WITERFOR I have become on the
MEYER			IN WITNESS WHEREOF, I have hereunto set m hand and affixed my seal the day and year first
MOORE			above written.
TOTAL			
MOTION CARRIED	Α	PPROVED	

Mayor



#### PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA



DATE OF NOTICE: November 17, 2011		DATE OF INSPECTION:	November 17, 2011
CASE NUMBER:	COD2011-07494		
PROPERTY ADDRESS:	1521 E PLEASANT VIEW D	R	
LEGAL DESCRIPTION:	LT 125 OP SW 1/4 SW 1/4	-EX N 20 F- SEC 14-78-24	
DORTS I HOLLOWAY & SHE	RMAN M HOLLOWAY		


Title Holder 1521 E PLEASANT VIEW DR DES MOINES IA 50320

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-304 and 60-306 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. Failure to correct these violations will result in legal action. The violations noted must be corrected within 30 days from the date of this notice. The violations noted must be corrected within 30 days from the date of this notice. The violations will result in a request to the City Council, sitting as the board of Health, to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

#### ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.



If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the city may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Mike F Lehman

(515) 283-4299

Nid Inspector

DATE MAILED: 11/17/2011

MAILED BY: KMD



### Areas that need attention: 1521 E PLEASANT VIEW DR

	d attention: 1521 E PLEASANT VIEW DR		
Component: Requirement:	Bathroom Lavatory Compliance, International Property	Defect:	In poor repair
	Maintenance Code	Location:	Unknown
Comments:			
Component:	Electrical Receptacles	Defect:	In poor repair
<u>Requirement:</u>	Compliance, International Property Maintenance Code	Location:	Throughout
Comments:			
Component:	Wiring	Defect:	Improperly Installed
<u>Requirement:</u>	Electrical Permit	Location:	Unknown
Comments:			
Component:	Exterior Walls	Defect:	Absence of paint
Requirement:	Compliance, International Property Maintenance Code	Location:	Throughout
Comments:	Maintendrice Couc		moughout
		Defects	
Component: Requirement:	Furnace Mechanical Permit	Defect:	In poor repair
Comments:		Location:	Basement
<u>comments.</u>			
Component: Requirement:	Guardrails Compliance, International Property	Defect:	Not installed as required
	Maintenance Code	Location:	Basement
Comments:			
Component:	Hand Rails	Defect:	Not installed as required
Requirement:	Compliance, International Property Maintenance Code	Location:	Basement
Comments:			
	Creake Detectors	Defect:	Not installed as required
Component:	Smoke Detectors		
Component: Requirement:	Compliance, International Property Maintenance Code	Location:	: Throughout
	Compliance, International Property	Location:	: Throughout
Requirement:	Compliance, International Property	<u>Location</u> :	: Throughout

Companyant		Defects	To near youris	
<u>Component:</u> Requirement:	Soffit/Facia/Trim Compliance, International Property	Defect:	In poor repair Main Structure	BDH
Comments:	Maintenance Code	LOCATION:	Main Structure	
Component:	Soffit/Facia/Trim	Defect:	Absence of paint	
<u>Requirement:</u>	Compliance, International Property Maintenance Code	Location:	Main Structure	
Comments:				
Component:	Sub Floor	Defect:	Deteriorated	
Requirement:	Compliance, International Property Maintenance Code	Location:	Bathroom	
Comments:				
Component:	Window Glazing/Paint	Defect:	In poor repair	
<u>Requirement:</u>	Compliance, International Property Maintenance Code	Location:	Main Structure	
Comments:				
Component:	Windows/Window Frames	Defect:	Cracked/Broken	
<u>Requirement:</u>	Compliance, International Property Maintenance Code	Location:	Main Structure	
Comments:				
Component:	Interior Walls /Ceiling	Defect:	Water Damage	
Requirement:	Compliance, International Property Maintenance Code	Location:	Basement	
Comments:				
<u>Component:</u> Requirement:	Waste Lines Plumbing Permit	Defect:	In poor repair	
	Plumbing Permit	Location:	Basement	
<u>Comments:</u>				
Component:	See Comments	Defect:	Insect Infestation	1
	Compliance, International Property Maintenance Code	Location:	Main Structure	
Requirement: Comments:				
<u>Comments:</u> <u>Component:</u>	See Comments	Defect:	See Comments	
Comments:	See Comments Compliance, International Property Maintenance Code		See Comments Main Structure	

Polk/Des Moines Assessor - 010/06275-000-000 Listing


Page 1 of 4



# Polk County Assessor

[ <u>Home</u>] [ <u>General Query</u> ] [ <u>Legal Query</u> ] [ <u>HomeOwner Query</u> ] [ <u>Book/Page Query</u> ] [ <u>Commercial Query</u> ] [ <u>Res Sales</u> <u>Query</u> ] [ <u>Comm Sales Query</u> ] [ <u>Help</u> ]

District/Parcel	GeoParcel	Мар	Nbhd	Jurisdiction	Status	
010/06275-000-000	7824-14-353-015	0647	DM25/Z	<b>DES MOINES</b>	ACTIVE	
School District Tax Increment Finance District		Bond/Fire/Sewer/Cemetery				
1/Des Moines						
Street Address			City Stat	te Zipcode		
1521 E PLEAS	SANT VIEW DR		DES MC	DINES IA 50320-	1314	





Approximate date of photo 01/08/2009

## Mailing Address

DORIS I HOLLOWAY 1521 E PLEASANT VIEW DR DES MOINES, IA 50320-1314

## **Legal Description**

LT 125 OP S	W 1/4 SW 1/4 -EX	N 20 F- SEC 14-78-24
-------------	------------------	----------------------

<u>Ownership</u>	Name	Recorded	Book/Page	RevStamps
Title Holder #1	HOLLOWAY, SHERMAN M	1978-10-24	4856/74	15.95
Title Holder #2	HOLLOWAY, DORIS I			

Assessment	Class	Kind	Land	Bldg	AgBd	Total
Current	Residential	Full	13,200	50,600	0	63,800
Market Adjus	sted Cost Report A	Assessment Roll		ate Taxes	Polk County	<u>Freasurer</u>
		Tax Informatio	<u>n</u> Pay Taxes			

Page 2 of 4


		E	BDH
Taxable Value Credit	Name	Number	Info
Homestead	HOLLOWAY, DORIS I	88467	
Military	HOLLOWAY, SHERMAN M	48307	Korean

Zoning	Description	SF	Assessor Zoning
R1-60	One Family, Low Density Residential District		Residential


Source: City of Des Moines Community Development Published: 2011-05-25 Contact: Planning and Urban Design 515 283-4200

Land					
SQUARE FEET	11,343	FRONTAGE	57.0	DEPTH	199.0
ACRES	0.260	SHAPE	RC/Rectangle	TOPOGRAPHY	N/Normal


Residence # 1					-unit the second
OCCUPANCY	SF/Single Family		S1/1 Story	BLDG STYLE	RN/Ranch
YEAR BUILT	1958	<b># FAMILIES</b>	1	GRADE	4
GRADE ADJUST	-05	CONDITION	BN/Below Normal	TSFLA	875
MAIN LV AREA	875	BSMT AREA	864	FOUNDATION	P/Poured Concrete
EXT WALL TYP	WS/Wood Siding	ROOF TYPE	GB/Gable	ROOF MATERL	A/Asphalt Shingle
HEATING	A/Gas Forced Air	AIR COND	100	BATHROOMS	1
BEDROOMS	3	ROOMS	5		



Year	Type	Class	Kind	Land	Bldg	AgBd	Total
2011	Assessment Roll	Residential	Full	13,200	50,600	0	63,800
2009	Assessment Roll	Residential	Full	14,300	54,700	0	69,000
2007	Assessment Roll	Residential	Full	14,400	67,100	0	81,500
2005	Assessment Roll	Residential	Full	15,900	64,700	0	80,600
2003	Assessment Roll	Residential	Full	13,700	55,980	0	69,680
2001	Assessment Roll	Residential	Full	12,420	49,660	0	62,080
1999	Assessment Roll	Residential	Full	10,500	44,030	0	54,530
1997	Assessment Roll	Residential	Full	9,540	39,990	0	49,530
1995	Assessment Roll	Residential	Full	8,590	36,020	0	44,610
1993	Assessment Roll	Residential	Full	7,880	33,050	0	40,930









# BDHIA



BDHIA



BDHIA



# BDHIA





