



Date June 11, 2012

WHEREAS, the property located at 1322 23rd Street, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure and accessory structure in their present conditions constitute not only a menace to health and safety but are also a public nuisance; and

WHEREAS, the Titleholders Darin Wilson and Christine Wilson were notified more than thirty days ago to repair or demolish the main structure and accessory structure and as of this date have failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA, AND SITTING AS THE LOCAL BOARD OF HEALTH:

The main structure and accessory structure on the real estate legally described as Lot 14 in UNIVERSITY PLACE AND Lot 416 in UNIVERSITY LAND COS SECOND ADDITION, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 1322 23rd Street, have previously been declared a public nuisance;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owners fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said main structure and accessory structure.

Moved by_____to adopt.

FORM APPROVED:

icky Long Hill, Assistant City Attorney

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT	CERTIFICATE
COWNIE					
COLEMAN					I, DIANE RAUH, City Clerk of said City hereby
GRIESS					certify that at a meeting of the City Council of said City of Des Moines, held on the above date
HENSLEY					among other proceedings the above was adopted.
MAHAFFEY					
MEYER					IN WITNESS WHEREOF, I have hereunto set my hand and affixed my seal the day and year firs
MOORE					above written.
TOTAL					
MOTION CARRIED			A	PPROVED	
					Cline Charles
				Mayor	City Clerk

Polk/Des Moines Assessor - 080/06846-001-000 Listing

Page 1 of 4

Polk County Assessor

[Home] [General Query] [Legal Query] [HomeOwner Query] [Book/Page Query] [Commercial Query] [Res Sales Query] [Comm Sales Query] [Help]

District/Parcel	GeoParcel	Мар	Nbhd	Jurisdiction	Status	
080/06846-001-000	7924-33-378-019	0156	DM75/Z	DES MOINES	ACTIVE	
School District Tax Increment Finance Distric		Bond/Fire/Sewer/Cemetery				
1/Des Moines						
Street Address			City Stat	e Zipcode		
1322 23RD ST			DES MC	DINES IA 50311-	3118	

ſ	: 9	1355	trcel to get n	80 A	3 1357
	8	1337	21 64 1822 98	10.2 4055	1351
	8	162.5 1333	P 162	53 40	1343
Get	- F** =	1331	1330		1339
Bigger Map	- 24-T-H	1327	: 1324	÷ ÷	1329
		1325	* 1322	: 00	1327
Google		1323	1318	333	1325
Map		1321	1314	-	1319
		1017	1310	:	1315
	: 1	1317	4	+	1309
	127.5	25	2311230723 19 8 584 50 98	1.583	P303 16 P32 2219



Approximate date of photo 03/27/2012

Mailing Address

CHRISTINE WILSON 4127 DUBUQUE AVE DES MOINES, IA 50317

Legal Description

LT 14 UNIVERSITY PLACE; AND LOT 416 UNIVERSITY LAND COS 2ND ADDITION


Ownership	Name		Recorded	Book/Page	e RevS	tamps
Title Holder #1	WILSON, DA	RIN	2006-02-03	03 <u>11509/631</u>		
Title Holder #2	WILSON, CH	RISTINE				
Assessment	Class	Kind	Land	Bldg	AgBd	Total
Current	Residential	Full	8,500	28,300	0	36,800
Market Adju	sted Cost Report	<u>Estimate Taxes</u> <u>Tax</u>		Treasurer Ta	x Informatio	on <u>Pay</u>

Page 2 of 4 BDH1-B

Zoning	Description	SF	Assessor Zoning
R-3	Multiple Family Residential District		Multi-Family Residential
Source: (City of Des Moines Community Development I Urban Design 515		: 2012-03-20 Contact: Planning and

Land					
SQUARE FEET	8,586	FRONTAGE	53.0	DEPTH	162.0
ACRES	0.197	SHAPE	RC/Rectangle	TOPOGRAPHY	N/Normal

Residence # 1		Silvers - Silve			
OCCUPANCY	SF/Single Family	RESID TYPE	FA/1 Story with Finished Attic	BLDG STYLE	ET/Early 20s
YEAR BUILT	1884	# FAMILIES	1	GRADE	5
GRADE ADJUST	+10	CONDITION	PR/Poor	TSFLA	1,752
MAIN LV AREA	1,298	ATTIC FINISH	454	BSMT AREA	896
ENCL PORCH	35	FOUNDATION	B/Brick	EXT WALL TYP	WS/Wood Siding
ROOF TYPE	GB/Gable	ROOF MATERL	A/Asphalt Shingle	HEATING	A/Gas Forced Air
AIR COND	0	BATHROOMS	2	BEDROOMS	3
ROOMS	9				



Detached # 101					
OCCUPANCY	GAR/Garage	CONSTR TYPE	FR/Frame	MEASCODE	D/Dimensions
MEASURE1	18	MEASURE2	18	STORY HEIGHT	1
GRADE	5	YEAR BUILT	1910	CONDITION	PR/Poor

Seller	Buyer	Sale Date	Sale Price	Instrument	Book/Page
SELLEN, DENIS J	WILSON, DARIN	1998-05-01	24,000	C/Contract	7919/215

Year	Type	Class	Kind	Land	Bldg	AgBd	Total
2011	Assessment Roll	Residential	Full	8,500	28,300	0	36,800
2009	Assessment Roll	Residential	Full	8,300	26,700	0	35,000

Polk/Des Moines Assessor - 080/06846-001-000 Listing




2007	Assessment Roll	Residential	Full	7,900	25,600	0	33,500
2005	Assessment Roll	Residential	Full	8,100	45,900	0	54,000
2003	Assessment Roll	Residential	Full	6,450	36,350	0	42,800
2001	Assessment Roll	Residential	Full	6,620	26,200	0	32,820
1999	Assessment Roll	Residential	Full	5,480	20,450	0	25,930
1997	Assessment Roll	Residential	Full	5,060	18,880	0	23,940
1997	Was Prior Year	Residential	Full	4,760	17,770	0	22,530

email this page


Room 195, 111 Court Avenue, Des Moines, IA 50309 Phone 515 286-3140 / Fax 515 286-3386 polkweb@assess.co.polk.ia.us




6-7-12 1322-23









ELL 6-7-12 322-23









PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA

BDHI-B

DATE OF NOTICE: Octob	er 4, 2011	DATE OF INSPECTION:	April 10, 2008
CASE NUMBER:	COD2008-02180		
PROPERTY ADDRESS:	1322 23RD ST		
LEGAL DESCRIPTION:	LT 14 UNIVERSITY PLACE;	AND LOT 416 UNIVERSITY LA	AND COS 2ND ADDITION
CHRISTINE WILSON			

Title Holder 4127 DUBUQUE AVE DES MOINES IA 50317

DARIN WILSON Title Holder ADDRESS UNKNOWN

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-304 and 60-306 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. Failure to correct these violations will result in legal action. The violations noted must be corrected within 30 days from the date of this notice. The violations noted must be corrected within 30 days from the date of this notice. Failure to correct these violations will result in a request to the City Council, sitting as the board of Health, to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the city may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Eric Moore

(515) 283-4759

Eni Mon

Nid Inspector DATE MAILED: 10/4/2011

MAILED BY: TSY

BDH1-B

Areas that nee	d attention: 1322 23RD ST		
Component: Requirement: Comments:	Shingles Flashing	Defect: Location:	Deteriorated
Component: Requirement: Comments:	Shingles Flashing	Defect: Location:	Three Layers Max
Component: Requirement: Comments:	Exterior Walls	Defect: Location:	Missing Sections
Component: Requirement: Comments:	Exterior Walls	Defect: Location:	not impervious to water
Component: Requirement: Comments:	Exterior Walls	Defect: Location:	Severly peeling paint
Component: Requirement: Comments:	Soffit/Facia/Trim	Defect: Location:	Severly peeling paint
Component: Requirement: Comments:	Soffit/Facia/Trim	Defect: Location:	In poor repair
Component: Requirement: Comments:	Exterior Doors/Jams	Defect: Location:	In poor repair

<u>Component:</u> <u>Requirement:</u>	Stairs/Stoop	Defect:	In poor repair
Commontor		Location:	
<u>Comments:</u>	Front, rear, side		
Component:	Windows/Window Frames	Defect:	In poor repair
Requirement:		Location:	
<u>Comments:</u>			
Component:	Windows/Window Frames	Defect:	Missing Where Required
Requirement:		Location:	
<u>Comments:</u>			
Component:	Windows/Window Frames	Defect:	not impervious to water
Requirement:		Location:	
<u>Comments:</u>			
Component:	Foundation	Defect:	Missing Sections
<u>Requirement;</u>		Location:	
<u>Comments:</u>			
Component:	Foundation	Defect:	Structurally Unsound
Requirement:		Location:	
<u>Comments:</u>			
Component:	General Grade Around Structure	Defect:	Insufficient water drainage
<u>Requirement:</u>		Location:	
<u>Comments:</u>			
Component:	Flooring	Defect:	In poor repair
Requirement:		Location:	
<u>Comments:</u>	Throughout		
Component:	Bathroom Lavatory	Defect:	Missing
Requirement:		Location:	
<u>Comments:</u>			
		de Nie - unit	

Component: Requirement: Comments:	Functioning Water Closet	Defect: Location:	Missing	BDHI
Component: Requirement: Comments:	Interior Walls /Ceiling	<u>Defect:</u> Location:	In poor repair	
<u>Component:</u> <u>Requirement:</u> <u>Comments:</u>	Interior Stairway	Defect: Location:	In poor repair	
<u>Component:</u> <u>Requirement:</u> <u>Comments:</u>	Hand Rails	Defect: Location:	In poor repair	
Component: Requirement: Comments:	Kitchen Sink Kitchen	<u>Defect:</u> Location:	In poor repair	
Component: Requirement: Comments:	Smoke Detectors	Defect: Location:	Missing	
<u>Component:</u> <u>Requirement:</u> <u>Comments:</u>	Tub/Shower Walls	Defect: Location:	In poor repair	
Component: Requirement: Comments:	Waste Lines Permit Required	Defect: Location:	Improperly In	stalled
Component: Requirement: Comments:	Water Heater Permit Required	Defect: Location:	Improperly In	stalled

Component: Requirement: Comments:	Water Meter Jump	<u>Defect:</u> Location:	Missing	BDH /-
Component: Requirement: Comments:	Window Glazing/Paint	Defect: Location:	In poor repair	
Component: Requirement: Comments:	Wiring Electrical Permit	Defect: Location:	Exposed	
Component: Requirement: Comments:	Plumbing System Plumbing Permit	Defect: Location:	Missing Sections	
Component: Requirement: Comments:	Electrical System Electrical Permit	Defect:	Missing Sections	
Component: Requirement: Comments:	Mechanical System Mechanical Permit	Defect: Location	Missing Sections	
Component: Requirement: Comments:	Furnace Mechanical Permit	Defect: Location	Improperly Insta	Iled
Component: Requirement: Comments:	Accessory Buildings	Defect: Location	In poor repair <u>:</u>	
Component: Requirement: Comments:	Accessory Buildings	Defect: Location	Severly peeling	paint