Roll Call I	Number
-------------	--------

Age	nda l	tem.	Nun	ıber
			1	_4
		1 A		17

Date	October 8, 2012	

WHEREAS, the property located at 708 Hickman Road, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the fire-damaged main structure and garage structure in their present conditions constitute not only a menace to health and safety but are also a public nuisance; and

WHEREAS, the previous Titleholders Salvador Gonzalez and Roxana Gonzalez and the current Titleholder The Bank of New York Mellon as Trustee for Popular Financial Services Mortgage/Pass Through Certificate Series #2006-D were notified more than thirty days ago to repair or demolish the fire-damaged main structure and garage structure and as of this date have failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA, AND SITTING AS THE LOCAL BOARD OF HEALTH:

The fire-damaged main structure and garage structure on the real estate legally described as LT 31 & -EX S 45F- LT 32 CORRECTED PLAT 2ND PLAT PROSPECT PARK, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 708 Hickman Road, have previously been declared a public nuisance;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said fire-damaged main structure and garage structure.

Moved byto	adopt
------------	-------

FORM APPROVED:

Vieky Long Hill Assistant City Attorney

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT		
COWNIE						
COLEMAN						
GRIESS						
HENSLEY						
MAHAFFEY						
MEYER						
MOORE						
TOTAL						
MOTION CARRIED			A	APPROVED		

## **CERTIFICATE**

I, DIANE RAUH, City Clerk of said City hereby certify that at a meeting of the City Council of said City of Des Moines, held on the above date, among other proceedings the above was adopted.

IN WITNESS WHEREOF, I have hereunto set my hand and affixed my seal the day and year first above written.

City	Clerk





[ Home ] [ General Query ] [ Legal Query ] [ HomeOwner Query ] [ Book/Page Query ] [ Commercial Query ] [ Res Sales Query ] [ Comm Sales Query ] [ Help ]

District/Parcel	GeoParcel	Map	Nbhd	Jurisdiction	Status	
080/05482-001-000	7924-34-205-021	0118	DM78/Z	DES MOINES	ACTIVE	
School District Tax Increment Finance District		Bond/Fire/Sewer/Cemetery				
1/Des Moines						
Street Address			City Stat	e Zipcode		
708 HICKMAN RD			DES MO	DINES IA 50314-	2934	





Approximate date of photo 04/13/2006

## **Mailing Address**

OCWEN LOAN SERVICING LLC POB 24737 WEST PALM BEACH, FL 33416-4737

## **Legal Description**

LT 31 & -EX S 45F- LT 32 CORRECTED PLAT 2ND PLAT PROSPECT PARK

Ownership	Name	Recorded	Book/Page	RevStamps
Title Holder #1	BANK OF NEW YORK MELLON (TRUSTEE)	2012-08- 15	14394/699	

Assessment	Class	Kind	Land	Bldg	AgBd	Total
Current	Residential	Full	9,600	45,000	0	54,600
Market Adjus	ted Cost Report	Assessment Roll Tax Informatio		nate Taxes	Polk County	Treasurer




Zoning	Description	SF	Assessor Zoning
R1-60	One Family, Low Density Residential District		Residential
*Condition	Docket_no <u>14361</u>		

Source: City of Des Moines Community Development Published: 2012-03-20 Contact: Planning and Urban Design 515 283-4182

Land					
SQUARE FEET	13,888	ACRES	0.319	SHAPE	IR/Irregular
TOPOGRAPHY	N/Normal				

Residence # 1					
OCCUPANCY	SF/Single Family	RESID TYPE	SH/1.5 Stories	BLDG STYLE	CV/Conventional
YEAR BUILT	1915	YEAR REMODEL	2004	# FAMILIES	1
GRADE	4	GRADE ADJUST	+00	CONDITION	PR/Poor
TSFLA	2,845	MAIN LV AREA	2,064	UPPR LV AREA	781
ATT GAR AREA	576	BSMT AREA	1,776	ENCL PORCH	20
DECK AREA	270	FOUNDATION	B/Brick	EXT WALL TYP	VN/Vinyl Siding
ROOF TYPE	GB/Gable	ROOF MATERL	A/Asphalt Shingle	HEATING	A/Gas Forced Air
AIR COND	100	BATHROOMS	3	BEDROOMS	4
ROOMS	7				





Year	Type	Status	Application	Permit/Pickup Description
Current	U/Pickup	TW/To Work	2011-07-12	RV/Review Value FIRE
2012	U/Pickup	PR/Partial	2011-07-12	RV/FIRE
2006	P/Permit	CP/Complete	2003-11-19	NC/GARAGE (484 sf)
2005	P/Permit	NA/No Add	2004-09-30	AD/FENCE
2005	P/Permit	CP/Complete	2004-05-20	AD/DECK
2005	P/Permit	PR/Partial	2003-11-19	NC/GARAGE (484 sf)

Year	Type	Class	Kind	Land	Bldg	AgBd	Total
2012	Assessment Roll	Residential	Full	9,600	45,000	0	54,600
2011	Assessment Roll	Residential	Full	9,600	123,700	0	133,300
2009	Assessment Roll	Residential	Full	9,700	121,200	0	130,900



2008	Assessment Roll	Residential	Full	10,000	124,900	0	134,900
2007	Assessment Roll	Residential	Full	10,000	124,900	0	134,900
			Adj	10,000	113,730	0	123,730
2006	Assessment Roll	Residential	Full	10,900	106,800	0	117,700
			Adj	10,900	95,630	0	106,530
2005	Assessment Roll	Residential	Full	10,900	78,400	0	89,300
			Adj	10,900	67,230	0	78,130

email this page

Room 195, 111 Court Avenue, Des Moines, IA 50309 Phone 515 286-3140 / Fax 515 286-3386 polkweb@ussess.co.polk.ia.us



## PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA



**DATE OF NOTICE: October 6, 2011** 

DATE OF INSPECTION: August 16, 2011

CASE NUMBER:

COD2011-05581

PROPERTY ADDRESS:

708 HICKMAN RD

**LEGAL DESCRIPTION:** 

LT 31 & -EX S 45F- LT 32 CORRECTED PLAT 2ND PLAT PROSPECT PARK

SALVADOR GONZALEZ & ROXANA GONZALEZ Title Holder 1801 11TH ST DES MOINES IA 50314

POPULAR HOUSING SERVICES, INC Mortgage Holder KIMBERLY DUNBAR - ASST VP/SEC 301 LIPPINCOTT DR MARLTON NJ 08053

THE BANK OF NY MELLON CORPFKA THE BANK OF NEW YORK Mortgage Holder ATTN: GENERAL COUNSEL ONE WALL STREET NEW YORK NY 10286

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-304 and 60-306 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. Failure to correct these violations will result in legal action. The violations noted must be corrected within 30 days from the date of this notice. The violations noted must be corrected within 30 days from the date of this notice. Failure to correct these violations will result in a request to the City Council, sitting as the board of Health, to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.



Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the city may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Robert Reynolds

(515) 283-4128

Nid Inspector

DATE MAILED: 10/6/2011

MAILED BY: TSY



Areas that need attention: 708 HICKMAN RD

Component: Requirement: Condensation T

Mechanical Permit

Not Supplied Defect:

**Comments:** 

Location: Basement

Component:

Arc Fault Circuit Breakers

Requirement: **Electrical Permit** 

Not Supplied Defect:

**Comments:** 

**Location:** Throughout

Component:

Ductwork

Requirement: Mechanical Permit Defect:

Smoke Damage

**Comments:** 

**Location:** Throughout

Component: Requirement: **Electrical Lighting Fixtures** 

**Electrical Permit** 

Defect:

In disrepair

**Location:** Bedroom

Comments:

Component:

Exterior Doors/Jams

Defect:

Fire damaged

**Requirement:** 

**Building Permit** 

**Location:** Garage

**Comments:** 

Component:

Electrical System

Defect:

Smoke Damage

Requirement:

**Electrical Permit** 

**Location:** Garage

Comments:

**Component: Requirement:**  **Electrical System** 

Defect:

Smoke Damage

**Electrical Permit** 

**Building Permit** 

**Location:** Bedroom

**Comments:** 

Component: Requirement: Flooring

Defect:

Fire damaged

Comments:

**Location:** Bedroom

Defect: In disrepair Component: Furnace Requirement: Mechanical Permit **Location:** Basement Comments: Defect: Not Supplied Gas Line to Water Heater Component: Mechanical Permit Requirement: Location: Basement **Comments:** Defect: In disrepair Gas Lines Component: Mechanical Permit **Requirement: Location:** Throughout Comments: Defect: Deteriorated Component: General Grade Around Structure Requirement: **Location:** Throughout Comments: Defect: Fire damaged Interior Walls /Ceiling Component: **Requirement: Building Permit Location:** Garage Comments: Fire damaged Defect: Component: Interior Walls /Ceiling **Building Permit Requirement: Location:** Bedroom **Comments:** Defect: In disrepair Mechanical System Component: Mechanical Permit Requirement: **Location:** Throughout **Comments:** Defect: In disrepair Component: Plumbing System **Requirement:** Plumbing Permit **Location:** Throughout **Comments:** Not Supplied Protective Covering/Junction Box Defect: Component: **Requirement: Electrical Permit Location:** Basement **Comments:** 

Component: Requirement:	Smoke Detectors	Defect:	Not Supplied	30
Comments:		<u>Location:</u>	Throughout	
<u>comments.</u>				
Component: Requirement:	Soffit/Facia/Trim	<u>Defect:</u>	In disrepair	
		<u>Location:</u>	Throughout	
Comments:				
Component:	Water Heater	Defect:	Not Supplied	
Requirement:	Plumbing Permit	Location:	Basement	
Comments:				
Component:	Windows/Window Frames	Defect:	Not Supplied	
Requirement:		<u>Location:</u>	Throughout	
Comments:				
Component:	Wiring	Defect:	In disrepair	
Requirement:	Electrical Permit	Location:	Throughout	
Comments:			, moughout	
Component:	Waste Lines	Defect:		
Requirement:	Tradic Lines			
Comments:		<u>Location:</u>		
		Defeate		
Component: Requirement:		<u>Defect:</u>		
		Locations	1	
Comments:				
1				


BDH - 1(A)



708 Hickman


Front view

BDH - 1(A)



708 Hickman Rear view

BDH 1-(A)



708 Hickman

South side of property



708 HICKMAN


2<sup>ND</sup> FLOOR BEDROOM.

BDH I (A)



708 HICKMAN
INTERIOR GARAGE AREA.


BDH 1/A)



708 HICKMAN

MISSING WATER HEATER, NO GAS LINES TO FURNACE IN

BASEMENT AREA.



708 HICKMAN
IMPROPER WASTE LINE IN BASEMENT.



708 HICKMAN
KITCHEN FLOOR.