

Agenda Item Number



Date June 10, 2013

WHEREAS, the property located at 4146 E. 30th Street, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the fire-damaged main structure and garage structure in their present conditions constitute not only a menace to health and safety but are also a public nuisance; and

WHEREAS, the Titleholder Ann Henrichs was notified more than thirty days ago and Mortgage Holder Mortgage Electronic Registration Systems, Inc., was notified via certified mail to repair or demolish the main structure and garage structure and as of this date have failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA, AND SITTING AS THE LOCAL BOARD OF HEALTH:

The main structure and garage structure on the real estate legally described as N ½ LOT 46 DOUGLAS ACRES, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 4146 E. 30th Street, have previously been declared a public nuisance;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said structures.

Moved by_____to adopt.

FORM APPROVED:


Vicky Long Hill, Assistant City Attorney


COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT	CERTIFICATE
COWNIE			24		
COLEMAN					I, DIANE RAUH, City Clerk of said City hereby
GRIESS					certify that at a meeting of the City Council of said City of Des Moines, held on the above date,
HENSLEY					among other proceedings the above was adopted.
MAHAFFEY					
MEYER					IN WITNESS WHEREOF, I have hereunto set my hand and affixed my seal the day and year first
MOORE					above written.
TOTAL		43			
MOTION CARRIED			A	PPROVED	
				Mayor	City Clerk

Polk County Assessor

111 Court Avenue #195 Des Moines, IA 50309-0904 (515) 286-3014 Fax (515) 285 3 polkweb@assess.co.polk.ia.us

Location						
Address	4146 E 30TH ST					
City	DES MOINES	Zip	50317	Jurisdiction	Des Moines	
District/Parcel	060/01408-000-000	Geoparcel	7923-20-301-016	Status	Active	
School	Des Moines	Nbhd/Pocket	DM02/B	Submarket	Northeast Des Moines	
Appraiser	Michelle Henderson 515 -286-3361		A	h		





Р	hoto Pro	cessed	on 2001	1-04-09	a
				440	1
Y		J.	*		

Book/Page

4133/533

Google Map¹² Pictometry²³

1

Num

Historical PhotosOwnership - 1 RecordNameRecordedHENRICHS, ANN1970-06-18

Legal Description and Mailing Address

N 1/2 LOT 46 DOUGLAS ACRES

Ownership

Title Holder

ANN HENRICHS 4146 E 30TH ST DES MOINES, IA 50317

	2-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1	Current Value	S		
Туре	Class	Kind	Land	Bldg	Total
Assessment Roll	Residential	Full	\$17,200	\$57,000	\$74,200
Current	Residential	Full	\$17,200	\$57,900	\$75,100
	Assessment Roll No Auditor	tice Market Ad		ort	
Category	Name		Informati	on	
Homestead Credit			Applicatio	n #90047	

Polk County Assessor 060/01408-000-000

1

formation			Name Infor		Category			
7	ation #4126	n Applica	Korea	HENRICHS, ANN	1	ilitary Exemption		
			ecord	Zoning - 1 R				
sor Zoning	Asses	SF		Description	Loning			
sidential				One Family, Low Density Residential District				
2012-03-20)	83-4182 (ign 515 28	and Urban Des	Development Planning	s Community	City of Des Moine		
				Land		State of the		
50.0	ntage	Fro	0.447	Acres	19,450	Square Feet		
Rectangle	Shape	S	Normal	Topography	389.0	Depth		
			No	Unbuildable	No	Vacancy		
			1 Record	Residences -				
		1	#1	Residence				
Bungalow	uilding Style	B	1 Story Finished Attic	Residence Type	Single Family	Occupancy		
4+00	Grade		1	Number Families	1927	Year Built		
884	Living Area	Main	1193	Total Square Foot Living Area	Below Normal	Condition		
208	nclosed ch Area		884	Basement Area	309	Attic Finished Area		
Brick	ndation	Four	228	Canopy Square Foot	228	Patio Area		
Asphalt Shingle	Roof Iaterial	М	Gable	Roof Type	Metal Siding	Exterior Wall Type		
1	Number hrooms		100	Air Conditioning	Gas Forced Air	Heating		

ł

			19 12 Patio 228 19	12			BDI
			le a	attic <u>15</u> Smt 384	34		
			8 Enc.	26 26 208 208 25 26	ð		
			B Enc Detached Struc	26 27 26 27 26 26			
Occupa	ncy	Garage	B Enc Detached Struc	Porch 208 26		ent Code	Dimensions
Occupa: Measur	re 1	Garage 24	B Enc. Detached Struc Detached Struc Detached St Construction Type Measure 2	etures - 1 Rec ructure #10 Frame 24	1 Measurem Stor	y Height	Dimensions 1
Measur			B Enc Detached Struc Detached Struc Detached St Construction Type Measure 2 Year Built	Porch 26 ctures - 1 Rec tructure #10 Frame 24 1982	1 Measurem Stor		
Measur Gra	re 1 ade	24 4	B Enc Detached Struc Detached Struc Detached St Construction Type Measure 2 Year Built Historic	etures - 1 Rec ructure #10 Frame 24 1982 al Values	1 Measurem Stor C	ry Height Condition	1 Poor
Measur Gra Yr	re 1 ade Tyj	24 4	B Enc Detached Struct Detached Struct Struct Neasure 2 Year Built Historic Class	Porch 26 etures - 1 Rec tructure #10 Frame 24 1982 al Values Kind	1 Measurem Stor C Land	ry Height Condition Bldg	1 Poor Total
Measur Gr: Yr 2011	re 1 ade Tyj	24 4 De bessment Roll	B Enc. Detached Struct Detached Struct Detached Struct Struction Type Measure 2 Year Built Historic Class Residential	etures - 1 Rec ructure #10 Frame 24 1982 al Values Kind Full	1 Measurem Stor C Land \$17,200	y Height Condition Bldg \$57,900	1 Poor Total \$75,100
Measur Gr: Yr 2011 2009	re 1 ade Tyj <u>Ass</u> <u>Ass</u>	24 4 De sessment Roll sessment Roll	B Enc. Detached Struct Detached Struct Detached Struct Detached Struct Detached Struct Measure 2 Year Built Historic Class Residential Residential	Porch 26 ctures - 1 Rec tructure #10 Frame 24 1982 al Values Kind Full Full	1 Measurem Stor C Land \$17,200 \$19,000	ry Height Condition Bldg \$57,900 \$64,500	1 Poor Total \$75,100 \$83,500
Measur Gr: Yr 2011 2009 2007	re 1 ade Tyr Ass Ass	24 4 be sessment Roll sessment Roll	B Enc. Detached Struct Measure 2 Year Built Historic Class Residential Residential Residential Residential	Porch 200 ctures - 1 Rec cructure #10 Frame 24 1982 al Values Kind Full Full Full	1 Measurem Stor C Land \$17,200 \$19,000 \$19,400	ry Height Condition Bldg \$57,900 \$64,500 \$65,800	1 Poor Total \$75,100 \$83,500 \$85,200
Measur Gr: Yr 2011 2009 2007 2005	re 1 ade Tyr Ass Ass Ass	24 4 De eessment Roll eessment Roll eessment Roll	B Enc. Detached Struct Detached Struct Detached Struct Detached Struct Measure 2 Year Built Historic Class Residential Residential Residential Residential Residential Residential Residential Residential	Porch 26 etures - 1 Rec tructure #10 Frame 24 1982 al Values Kind Full Full Full Full Full	1 Measurem Stor C Land \$17,200 \$19,000 \$19,400 \$19,800	ry Height Condition Bldg \$57,900 \$64,500 \$65,800 \$60,000	1 Poor Total \$75,100 \$83,500 \$85,200 \$79,800
Measur Gr: Yr 2011 2009 2007 2005 2003	re 1 ade Tyr Ass Ass Ass Ass Ass	24 4 be essment Roll essment Roll essment Roll essment Roll	B Enc. Detached Struct Detached Struct Detached Struct Detached Struct Detached Struct Measure 2 Year Built Historic Class Residential	Porch 200 ctures - 1 Rec cructure #10 Frame 24 1982 al Values Kind Full Full Full Full Full Full	1 Measurem Stor C Land \$17,200 \$19,000 \$19,400 \$19,800 \$18,500	Py Height Condition Condition Bldg \$57,900 \$64,500 \$65,800 \$60,000 \$55,890	1 Poor Total \$75,100 \$83,500 \$85,200 \$79,800 \$79,800
Measur Gr: 2011 2009 2007 2005 2003 2001	re 1 ade Tyr Ass Ass Ass Ass Ass Ass	24 4 5e sessment Roll sessment Roll sessment Roll sessment Roll sessment Roll	B Enc. Detached Struct Detached Struct Detached Struct Detached Struct Detached Struct Detached Struct Measure 2 Year Built Historic Class Residential	Porch 26 27 28 29 29 20 20 20 20 20 20 20 20 20 20	1 Measurem Stor C Land \$17,200 \$19,000 \$19,400 \$19,800 \$19,800 \$18,500 \$17,520	y Height Condition Bldg \$57,900 \$64,500 \$65,800 \$60,000 \$56,890 \$50,740	1 Poor Total \$75,100 \$83,500 \$85,200 \$79,800 \$75,390 \$68,260
Measur Gr: 2011 2009 2007 2005 2003 2001 1999	re 1 ade Tyr Ass Ass Ass Ass Ass Ass Ass Ass	24 4 be essment Roll essment Roll essment Roll essment Roll essment Roll essment Roll essment Roll	B Enc. Enc. Detached Struct Measure 2 Year Built Historic Residential Residential <td>Porch 20 ctures - 1 Rec cructure #10 Frame 24 1982 al Values Kind Full Full Full Full Full Full Full Ful</td> <td>1 Measurem Stor C Land \$17,200 \$19,000 \$19,400 \$19,800 \$19,800 \$18,500 \$17,520 \$7,480</td> <td>ry Height Condition Bldg \$57,900 \$64,500 \$65,800 \$66,000 \$56,890 \$50,740 \$45,440</td> <td>1 Poor Total \$75,100 \$83,500 \$85,200 \$79,800 \$75,390 \$68,260 \$52,920</td>	Porch 20 ctures - 1 Rec cructure #10 Frame 24 1982 al Values Kind Full Full Full Full Full Full Full Ful	1 Measurem Stor C Land \$17,200 \$19,000 \$19,400 \$19,800 \$19,800 \$18,500 \$17,520 \$7,480	ry Height Condition Bldg \$57,900 \$64,500 \$65,800 \$66,000 \$56,890 \$50,740 \$45,440	1 Poor Total \$75,100 \$83,500 \$85,200 \$79,800 \$75,390 \$68,260 \$52,920
Measur Gr: 2011 2009 2007 2005 2003 2001 1999 1997	re 1 ade Tyr Ass Ass Ass Ass Ass Ass Ass Ass	24 4 50 50 50 50 50 50 50 50 50 50 50 50 50	Enc. Detached Struct Struction Type Measure 2 Year Built Historic Class Residential	Porch 200 etures - 1 Rec eructure #10 Frame 24 1982 al Values Kind Full Fu	1 Measurem Stor C Land \$17,200 \$19,000 \$19,400 \$19,800 \$19,800 \$18,500 \$17,520 \$7,480 \$6,560	ry Height Condition Bldg \$57,900 \$64,500 \$65,800 \$60,000 \$56,890 \$50,740 \$45,440 \$39,860	1 Poor Total \$75,100 \$83,500 \$85,200 \$79,800 \$75,390 \$68,260 \$52,920 \$46,420
Measur Gr: 2011 2009 2007 2005 2003 2001 1999 1997 1995	re 1 ade Tyj Ass Ass Ass Ass Ass Ass Ass Ass Ass	24 4 9e eessment Roll eessment Roll eessment Roll eessment Roll eessment Roll eessment Roll eessment Roll eessment Roll	Enc. Detached Struct Measure 2 Year Built Historic Class Residential	Porch 26 ctures - 1 Rec cructure #10 Frame 24 1982 al Values Kind Full	1 Measurem Stor C Land \$17,200 \$19,000 \$19,400 \$19,800 \$19,800 \$18,500 \$17,520 \$7,480 \$6,560 \$5,820	ry Height P Condition P Condition P S57,900 S64,500 \$65,800 S65,800 \$65,800 S56,890 \$56,890 S50,740 \$45,440 \$39,860 \$35,360 S35,360	1 Poor Total \$75,100 \$83,500 \$85,200 \$79,800 \$75,390 \$68,260 \$52,920 \$46,420 \$41,180
Measur Gr: 2011 2009 2007 2005 2003 2001 1999 1997	re 1 ade Tyj Ass Ass Ass Ass Ass Ass Ass Ass Ass As	24 4 50 50 50 50 50 50 50 50 50 50 50 50 50	Enc. Detached Struct Measure 2 Year Built Historic Class Residential	Porch 200 etures - 1 Rec eructure #10 Frame 24 1982 al Values Kind Full Fu	1 Measurem Stor C Land \$17,200 \$19,000 \$19,400 \$19,800 \$19,800 \$18,500 \$17,520 \$7,480 \$6,560	ry Height Condition Bldg \$57,900 \$64,500 \$65,800 \$60,000 \$56,890 \$50,740 \$45,440 \$39,860	1 Poor Total \$75,100 \$83,500 \$85,200 \$79,800 \$75,390 \$68,260 \$52,920 \$46,420

This template was last modified on Fri May 3 13:32:27 2013





DATE OF NOTICE: May 31, 2013

PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA



DATE OF INSPECTION:

January 14, 2013

CASE NUMBER:	COD2012-06663
PROPERTY ADDRESS:	4146 E 30TH ST
LEGAL DESCRIPTION:	N 1/2 LOT 46 DOUGLAS ACRES

ANN HENRICHS Title Holder 2726 LYON ST DES MOINES IA 50317

MORTGAGE ELECTRONIC REGISTRATIONS SYS. INC. Mortgage Holder ATTN: CAMELIA MORTIN REG.AGENT 1818 LIBRARY ST STE 300 RESTON VA 20190

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-304 and 60-306 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. Failure to correct these violations will result in legal action. The violations noted must be corrected within 30 days from the date of this notice. The violations noted must be corrected within 30 days from the date of this notice. Failure to correct these violations will result in a request to the City Council, sitting as the board of Health, to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.



Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Justin S. Denning

i feming off (515) 237-1484 Nid Inspector

DATE MAILED: 5/31/2013


MAILED BY: TSY





Areas that need attention: 4146 E 30TH ST


Component: Requirement: Comments: Component:	Exterior Walls Building Permit Roof	Defect: Location: Defect:	Fire damaged Bedroom Fire damaged
Requirement: Comments:	Building Permit	Location:	
<u>Component:</u> <u>Requirement:</u> <u>Comments:</u>	Interior Walls /Ceiling Compliance with Int. Exiting Building Code	<u>Defect:</u> Location:	Flame/Smoke Spread Throughout
Component: Requirement: Comments:	Electrical Receptacles Electrical Permit	<u>Defect:</u> Location:	Fire damaged Throughout
<u>Component:</u> <u>Requirement:</u> <u>Comments:</u>	Tub/Shower Walls Plumbing Permit	<u>Defect:</u> Location:	Fire damaged Throughout
Component:			
Comments:	Flooring Complaince with Int Residential Code	Defect:	Flame/Smoke Spread Throughout
Requirement:		Location: Defect:	

Component:	Interior Walls /Ceiling	Defect:	Water Damage	BU
Requirement:	Complaince with Int Residential Code	Location:	Throughout	
Comments:		Locacioni	moughout	
				1
Component:	Interior Walls /Ceiling	Defect:	Smoke Damage	
Requirement:	Complaince with Int Residential Code	Location:	Throughout	
Comments:		Location	moughout	
Component:	Interior Walls /Ceiling	Defect:	Fire damaged	
<u>Requirement:</u>	Compliance with Int. Exiting Building	Location:	Throughout	
Comments:	Couc		moughout	
Component:	Soffit/Facia/Trim	Defect:	Fire damaged	
<u>Requirement:</u>	Compliance with Int. Exiting Building Code	Location:	Throughout	
Comments:				









BDH /

