

Agenda Item Number

Date March 9, 2015

WHEREAS, the property located at 1312 Boyd Street, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the garage structure in its present condition constitutes not only a menace to health and safety but is also a public nuisance; and

WHEREAS, the Titleholder, Linda J. White, and Mortgage Holder, Bank of the West fka Commercial Federal Bank, and Tax Lien Holder, Iowa Department of Revenue, were notified by personal service more than thirty days ago to repair or demolish the garage structure and as of this date have failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA, AND SITTING AS THE LOCAL BOARD OF HEALTH:

The garage structure on the real estate legally described as Lot 19 in Block 1, GRAND VIEW, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 1312 Boyd Street, has previously been declared a public nuisance;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said garage structure.

Moved by\_\_\_\_\_to adopt.

FORM APPROVED:

Vicky Long Hill, Assistant City Attorney


COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT	CERTIFICATE
COWNIE					
COLEMAN					I, DIANE RAUH, City Clerk of said City hereby
GRIESS					certify that at a meeting of the City Council of said City of Des Moines, held on the above date, among
HENSLEY		-			other proceedings the above was adopted.
MAHAFFEY					enter proceedings ine above thas adopted
MEYER					IN WITNESS WHEREOF, I have hereunto set my
MOORE					hand and affixed my seal the day and year first above written.
TOTAL					above written.
MOTION CARRIED			API	ROVED	
				Mayor	City Clerk




# Polk County Assessor

[ Home ] [ General Query ] [ Legal Query ] [ HomeOwner Query ] [ Book/Page Query ] [ Commercial Query ] [ Res Sales Query ] [ Comm Sales Query ] [ Help ]

District/Parcel	GeoParcel	Map	Nbhd	Jurisdiction	Status
110/02801-000-000	7924-26-430-019	0267	DM86/A	DES MOINES	ACTIVE
School District	Tax Increment Finance District	Bond/Fire/Sewer/Cemetery			
1/Des Moines					
Street Address			City State Zipcode		
1312 BOYD ST		DES MOINES IA 50316-1452			





Approximate date of photo 10/24/2013

### Mailing Address

ROLAND W WHITE 1312 BOYD ST DES MOINES, IA 50316-1452

#### Legal Description

LOT 19 BLK 1 GRAND VIEW

<u>Ownership</u>	Name	Recorded	Book/Page	RevStamps
Title Holder #1	WHITE, ROLAND W	1996-11-19	7525/745	
Title Holder #2	WHITE, LINDA J			

Assessment	Class	Kind	Land	Bldg	AgBd	Total
Current	Residential	Full	14,300	57,800	0	72,100
Market Adjusted (	Cost Report Estima	te Taxes	Polk County T	reasurer Tax	Information	Pay Taxes


Taxable Value Credit	Name	Number	Info

# Polk/Des Moines Assessor - 110/02801-000-000 Listing



Page 2 of 4

							, <u>,</u>		
Homestead			WHITE, R	OLAND W	-		51944		
Zoning	Desc	cription				SF	Assesso	or Zonii	ıg
R1-60	One	Family, Low De	nsity Residentia	l District			Resider	itial	
Source: City of Des Moines Community Development Published: 2012-03-20 Contact: Planning and Urban Design 515 283-4182									
Land									
SQUARE FEET		6,600	FRONTAGE	50.0	DE	PTH			132.0
ACRES		0.152	SHAPE	RC/Rectangle	TO	POGI	RAPHY	N	[/Normal
Residence #	1								
OCCUPANO	CY	SF/Single Family	RESID TYPE	SH/1.5 Stories	BL	DG S'	FYLE	ET/E	Early 20s
YEAR BUIL	T.	1913	# FAMILIES	1	GR	ADE			4
GRADE ADJUST		+05	CONDITION	BN/Below Normal	TS	FLA			1,537
MAIN LV AREA		927	UPPR LV AREA	610	BSI	MT A	REA		910
ENCL PORG	СН	135	PATIO AREA	336	FO	UND	ATION		B/Brick
EXT WALL TYP		MT/Metal Siding	ROOF TYPE	GB/Gable	RO MA	OF TER	L	A	/Asphalt Shingle
HEATING		A/Gas Forced Air	AIR COND				DOMS	:	1
XTRA FIXTURE		1	BEDROOMS	3	RO	OMS			7



Detach	<u>ed #</u> 101	4										
OCCU	PANCY	GA	AR/Garage	CONST TYPE	'R	FR/Frame		FR/Frame MEASCODE		ASCODE D/Dimen		
MEAS	URE1		14	MEASU	SURE2 26 STORY HEIGHT		261		261		1	
GRAD	E		5	YEAR BUILT		1945		1945 CONDITION		1945 CONDITION PR/		PR/Poor
Year	Туре		Status	atus Applic			Pern	Permit/Pickup Description				
1995	U/Picku	ıp	CP/Comp	lete	1994-(	06-03	Rem	ove	Basement	Finish		
Year	Type			Class		Kind	Lan	ıd	Bldg	AgBo	l Total	
2013	Assessn	nent R	<u>oll</u>	Residenti	al	Full	14,30	00	57,800		72,100	
2011	Assessm	nent R	<u>oll</u>	Residenti	al	Full 17,40		00	69,900	(	87,300	
										•		

# Polk/Des Moines Assessor - 110/02801-000-000 Listing

BDH I(A)

Page 4 of 4

2009	Assessment Roll	Residential	Full	19,800	76,000	0	95,800
2007	Assessment Roll	Residential	Full	18,600	71,600	·0	90,200
2005	Assessment Roll	Residential	Full	15,600	67,500	-0	83,100
2003	Assessment Roll	Residential	Full	14,010	60,340	0	74,350
2001	Assessment Roll	Residential	Full	14,210	59,860	0	74,070
1999	Assessment Roll	Residential	Full	10,050	56,190	0	66,240
1997	Assessment Roll	Residential	Full	9,020	54,080	0	63,100
1995	Assessment Roll	Residential	Full	8,000	47,970	0	55,970
1993	Assessment Roll	Residential	Full	6,780	40,680	0	47,460
1990	Assessment Roll	Residential	Full	6,780	38,720	. 0	45,500

# email this page

Room 195, 111 Court Avenue, Des Moines, IA 50309 Phone 515 286-3140 / Fax 515 286-3386 polkweh@assess.co.polk.ia.us



#### PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA

BDH I(A)

DATE OF NOTICE: Janua	ry 13, 2015	DATE OF INSPECTION:	July 08,	2014
CASE NUMBER:	COD2014-04535		·9.	•
PROPERTY ADDRESS:	1312 BOYD ST			
LEGAL DESCRIPTION:	LOT 19 BLK 1 GRAND VIE	N		

LINDA J WHITE Title Holder 1312 BOYD ST DES MOINES IA 50316-1452

IOWA DEPT. OF REVENUE C/O MARK SCHULING, DIRECTOR Contact HOOVER STATE OFFICE BLDG 1305 E WALNUT ST DES MOINES IA 50319

BANK OF THE WEST F/N/A COMMERCIAL FED BANK Mortgage Holder C T CORP SYS., REG AGENT 400 E COURT AVE DES MOINES IA 50309

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-304 and 60-306 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from data of notice. Failure to correct these violations will result in a request to the City Council, sitting as the Board of Health, to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

#### ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

\\CDMAPPS1\D-VOLUME\APPDATA\Tidemark\prd\_41\Forms & Reports\dsmCODPubNo.rp

COD2014-04535



Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

**Daniel Adams** (515) 237-1612

Nid Inspector

DATE MAILED: 1/13/2015

MAILED BY: JDH

BDH I(A)


### Areas that need attention: 1312 BOYD ST

Component:	Roof	Defect:	In poor repair
Requirement:	Compliance with International Building Code	Location	Carac
Comments:	Code	Location:	Garage
<u>.</u>			
	•		
Component:	Exterior Walls	Defect:	In poor repair
Requirement:	Building Permit		
Comments:		Location:	Garage
Commentar	A	8	
Component:	Exterior Doors/Jams	Defect:	In poor repair
Requirement:	Compliance with International Building	Delect	
	Code	Location:	Garage
Comments:			
<u>Component:</u> <u>Requirement:</u>	Shingles Flashing	Defect:	In poor repair
<u>Requirement.</u>	Compliance with International Building Code	Location:	Garage
Comments:			
			e
			5. 
Component:	Soffit/Facia/Trim	Defect:	In poor repair
<u>Component:</u> <u>Requirement:</u>	Compliance with International Building		
		<u>Defect:</u> <u>Location:</u>	
Requirement:	Compliance with International Building		
Requirement:	Compliance with International Building		
Requirement: Comments: Component:	Compliance with International Building		
<u>Requirement:</u> <u>Comments:</u>	Compliance with International Building Code Windows/Window Frames Compliance with International Building	Location: Defect:	Garage In poor repair
Requirement: Comments: Component: Requirement:	Compliance with International Building Code Windows/Window Frames	Location:	Garage In poor repair
Requirement: Comments: Component:	Compliance with International Building Code Windows/Window Frames Compliance with International Building	Location: Defect:	Garage In poor repair
Requirement: Comments: Component: Requirement:	Compliance with International Building Code Windows/Window Frames Compliance with International Building	Location: Defect:	Garage In poor repair
Requirement: Comments: Component: Requirement: Comments:	Compliance with International Building Code Windows/Window Frames Compliance with International Building Code	Location: Defect: Location:	Garage In poor repair Garage
Requirement: Comments: Component: Requirement:	Compliance with International Building Code Windows/Window Frames Compliance with International Building	Location: Defect: Location: Defect:	Garage In poor repair Garage Absence of paint
Requirement:         Comments:         Component:         Requirement:         Comments:         Comments:         Comments:	Compliance with International Building Code Windows/Window Frames Compliance with International Building Code	Location: Defect: Location:	Garage In poor repair Garage Absence of paint
Requirement:         Comments:         Component:         Requirement:         Comments:	Compliance with International Building Code Windows/Window Frames Compliance with International Building Code	Location: Defect: Location: Defect:	Garage In poor repair Garage Absence of paint
Requirement:         Comments:         Component:         Requirement:         Comments:         Comments:         Comments:	Compliance with International Building Code Windows/Window Frames Compliance with International Building Code	Location: Defect: Location: Defect:	Garage In poor repair Garage Absence of paint
Requirement:         Comments:         Component:         Requirement:         Comments:         Component:         Requirement:         Component:         Requirement:         Component:         Component:         Component:         Requirement:         Component:         Requirement:         Comments:	Compliance with International Building Code Windows/Window Frames Compliance with International Building Code Exterior Walls	Location: Defect: Location: Defect: Location:	Garage In poor repair Garage Absence of paint Garage
Requirement:         Comments:         Component:         Requirement:         Comments:         Component:         Requirement:         Component:         Component:         Component:         Comments:	Compliance with International Building Code Windows/Window Frames Compliance with International Building Code	Location: Defect: Location: Defect: Location:	Garage In poor repair Garage Absence of paint
Requirement:         Comments:         Component:         Requirement:         Comments:         Component:         Requirement:         Component:         Requirement:         Component:         Component:         Component:         Requirement:         Component:         Requirement:         Comments:	Compliance with International Building Code Windows/Window Frames Compliance with International Building Code Exterior Walls	Location: Defect: Location: Defect: Location:	Garage In poor repair Garage Absence of paint Garage Absence of paint
Requirement:         Comments:         Component:         Requirement:         Comments:         Component:         Requirement:         Component:         Component:         Component:         Comments:	Compliance with International Building Code Windows/Window Frames Compliance with International Building Code Exterior Walls	Location: Defect: Location: Defect: Location:	Garage In poor repair Garage Absence of paint Garage Absence of paint
Requirement:         Comments:         Component:         Requirement:         Comments:         Component:         Requirement:         Component:         Requirement:         Component:         Requirement:         Component:         Requirement:         Component:         Requirement:	Compliance with International Building Code Windows/Window Frames Compliance with International Building Code Exterior Walls	Location: Defect: Location: Defect: Location:	Garage In poor repair Garage Absence of paint Garage Absence of paint





BDH (A)



BDH /(A)