*	Roll	Call	Number
---	------	------	--------

Agenda	Item	Number
	5	2C

Date	October 12, 2015	
1 all		

## ABATEMENT OF PUBLIC NUISANCES AT 1535 24th Street

WHEREAS, the property located at 1535 24th Street, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure in its present condition constitutes not only a menace to health and safety but is also a public nuisance; and

WHEREAS, the Titleholder, Oak Park Investments partnership LXI, was notified more than thirty days ago to repair or demolish the main structure and as of this date has failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA:

The main structure on the real estate legally described as Lot 8 in CURTIS BLUFF PARK ADDITION, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 1535 24<sup>th</sup> Street, has previously been declared a public nuisance;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said structure.

Moved by\_\_\_\_\_to adopt.

FORM APPROVED:

Luke DeSmet, Assistant City Attorney

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT
COWNIE				
COLEMAN				
GATTO				
GRAY				
HENSLEY				
MAHAFFEY				
MOORE				
TOTAL				
MOTION CARRIED		-	API	PROVED

#### **CERTIFICATE**

I, DIANE RAUH, City Clerk of said City hereby certify that at a meeting of the City Council of said City of Des Moines, held on the above date, among other proceedings the above was adopted.

IN WITNESS WHEREOF, I have hereunto set my hand and affixed my seal the day and year first above written.

	I	
		City Clerk
Mayor		City Cierk
Mayor		






[ Home ] [ General Query ] [ Legal Query ] [ HomeOwner Query ] [ Book/Page Query ] [ Commercial Query ] [ Res Sales

Query ] [ Comm Sales Query ] [ Help ]

District/Parcel	GeoParcel	Map	Nbhd	Jurisdiction	Status	
080/01380-000-000	7924-33-327-006	0163	DM75/Z	DES MOINES	<u>ACTIVE</u>	
School District Tax Increment Finance District			Bond/Fire/Sewer/Cemetery			
1/Des Moines	1/Des Moines					
Street Address City State Zipcode						
1535 24TH ST			DES MO	INES IA 50311		





Approximate date of photo 03/27/2012

#### **Mailing Address**

OAK PARK INVESTMENTS PARTNERSHIP 100 N LA SALLE ST STE 1111 CHICAGO, IL 60602-3537

#### Legal Description

LOT 8 CURTIS BLUFF PARK ADDITION

Ownership	Name	Recorded	Book/Page	RevStamps
	The first of the second	2010-03- 03	13371/472	

Assessment	Class	Kind	Land	Bldg	AgBd	Total
Current	Residential	Full	8,500	4,800	0	13,300
FINE NO. 200 N. 2000 N. 2000		N-9 DOM: 005				

<u>Market Adjusted Cost Report</u> <u>Assessment Roll Notice</u> <u>Estimate Taxes</u> <u>Polk County Treasurer</u> <u>Tax Information Pay Taxes</u>


Zoning Description	SF	Assessor Zoning	
--------------------	----	-----------------	--

R1-60	One Family, Low Density Residential District	Residential				
Source: C	Source: City of Des Moines Community Development Published: 2012-03-20 Contact: Planning and					
	Urban Design 515 283-4182					

Land					
SQUARE FEET	8,000	FRONTAGE	50.0	DEPTH	160.0
ACRES	0.184	SHAPE	RC/Rectangle	TOPOGRAPHY	N/Normal

Residence # 1					
OCCUPANCY	SF/Single Family	RESID TYPE	SH/1.5 Stories	BLDG STYLE	ET/Early 20s
YEAR BUILT	1900	# FAMILIES	1	GRADE	4
GRADE ADJUST	-05	CONDITION	VP/Very Poor	TSFLA	1,026
MAIN LV AREA	676	UPPR LV AREA	350	BSMT AREA	313
OPEN PORCH	50	FOUNDATION	B/Brick	TYP	MS/Hardboard
ROOF TYPE	GM/Gambrel	ROOF MATERL	A/Asphalt Shingle	HEATING	A/Gas Forced Air
AIR COND	0	BATHROOMS	1	BEDROOMS	3
ROOMS	6				





Seller	Buyer	Sale Date	Sale Price	Instrument	Book/Page
MC DERMOTT, JOSEPH M SR	CORTLANDT, ROBERT	<u>1997-06-</u> <u>07</u>	77,000	IC/Connact	7671/5 Multiple Parcels
HAISIED BELLY	MC DERMOTT, JOSEPH M JR	1992-09- 22	9,000	D/Deed	6689/276

Year	Type	Class	Kind	Land	Bldg	AgBd	Total
2015	Assessment Roll	Residential	Full	8,500	4,800		13,300
2013	Assessment Roll	Residential	Full	8,000	40,200	0	48,200
2011	Assessment Roll	Residential	Full	8,000	40,200	0	48,200
2009	Assessment Roll	Residential	Full	8,000	37,900	0	45,900
2007	Assessment Roll	Residential	Full	7,700	36,300	0	44,000
2005	Assessment Roll	Residential	Full	7,200	35,600	0	42,800

2003	Assessment Roll	Residential	Full	5,380	26,270	0	31,650
2001	Assessment Roll	Residential	Full	6,650	21,420	0	28,070
1999	Assessment Roll	Residential	Full	5,100	19,910	0	25,010
1997	Assessment Roll	Residential	Full	4,710	18,380	0	23,090
1995	Assessment Roll	Residential	Full	4,430	17,300	0	21,730
1989	Assessment Roll	Residential	Full	3,830	14,970	0	18,800

# email this page

Room 195, 111 Court Avenue, Des Moines, IA 50309 Phone 515 286-3140 / Fax 515 286-3386 polkweb@assess.co.polk.ia.us



# PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA



**DATE OF NOTICE: July 27, 2015** 

**DATE OF INSPECTION:** 

October 23, 2008

**CASE NUMBER:** 

COD2008-07924

PROPERTY ADDRESS:

1535 24TH ST

**LEGAL DESCRIPTION:** 

LOT 8 CURTIS BLUFF PARK ADDITION

OAK PARK INVESTMENTS PARTNERSHIP Title Holder TIMOTHY T BALIN, PRESIDENT 100 N LASALLE ST STE 1111 CHICAGO II 60602

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-304 and 60-306 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council, sitting as the Board of Health, to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Chris Reindl

(515) 283-4797

Nid Inspector

DATE MAILED: 7/27/2015

MAILED BY: JDH



### Areas that need attention: 1535 24TH ST

Areas that nee	d attention: 1535 24TH ST		
Component: Requirement:	Mechanical System	Defect:	In disrepair
<u>Kequilement.</u>		Location:	Throughout
Comments:	Must be checked by licensed contractor		,
Component:	Soffit/Facia/Trim	Defect:	Excessive rot
Requirement:	Compliance, International Property Maintenance Code	Location:	
Comments:	Maintenance code	Location	
	,		
Commonate	Caffib II asia / Tuina	Defect:	Holes or major defect
Component: Requirement:	Soffit/Facia/Trim Compliance, International Property		noies of major defect
Comments:	Maintenance Code	<u>Location:</u>	
<u> </u>	,		
Component: Requirement:	Soffit/Facia/Trim Compliance, International Property	Defect:	Absence of paint
5920	Maintenance Code	Location:	
<u>Comments:</u>			
Component:	Windows/Window Frames	Defect:	Absence of paint
Requirement:	Compliance, International Property Maintenance Code	Location:	
Comments:	. I a literature e e a e		
Component:	Windows/Window Frames	Defect:	Cracked/Broken
Requirement:	Compliance, International Property		·
Comments:	Maintenance Code	<u>Location:</u>	
Component: Requirement:	Windows/Window Frames Compliance, International Property	Defect:	Excessive rot
		Locations	
Comercia	Maintenance Code	<u>Location:</u>	
Comments:	Maintenance Code	LOCATION	
Comments:	Maintenance Code	<u>Location:</u>	
Component:	Exterior Doors/Jams	Defect:	Severly peeling paint
* 5			Severly peeling paint
Component:	Exterior Doors/Jams Compliance, International Property	Defect:	Severly peeling paint
Component: Requirement:	Exterior Doors/Jams Compliance, International Property Maintenance Code	Defect:	Severly peeling paint

Component: Exterior Doors/Jams **Defect:** In disrepair Requirement: Compliance, International Property Maintenance Code Location: **Comments:** Rear **Exterior Walls** Component: **Defect:** In disrepair Requirement: Compliance, International Property Maintenance Code **Location: Comments: Exterior Walls** Defect: **Component:** Deteriorated **Requirement:** Compliance, International Property Maintenance Code **Location: Comments: Component: Exterior Walls Defect:** Holes or major defect Requirement: Compliance, International Property **Location:** Maintenance Code **Comments:** Component: **Defect:** Unsafe to carry Load Flooring **Requirement:** Compliance, International Property Maintenance Code Location: Porch **Comments:** Front porch **Component:** Hand Rails **Defect:** Improperly Installed Requirement: Compliance, International Property Maintenance Code **Location: Comments:** On front stairway both porch & by street Component: Improperly Installed Guardrails Defect: Requirement: Compliance, International Property Maintenance Code **Location:** Porch Comments: Guardrail around front porch also no ballastars **Component: Electrical Lighting Fixtures Defect:** In poor repair **Requirement: Location: Comments:** Exterior rear Component: General Grade Around Structure **Defect:** Inadequate **Requirement: Location: Comments:** This also includes the concrete slab in back

Component:	Roof	Defect:	Leaks 1
Requirement:		Location:	
Comments:		LUCALIUII.	
,			
Component:	Shingles Flashing	Defect:	Improperly Installed
Requirement:			
<u>Comments:</u>		<u>Location:</u>	
<u> </u>			
Component:	Shingles Flashing	Defect:	not impervious to water
Requirement:			
Comments:		<u>Location:</u>	ć
<u>comments.</u>			
Component:	Weather Head	Defect:	In disrepair
Requirement:	Wedther Fledd		III disrepail
Comments		Location:	
Comments:	Electrical service drop is obstructed by veg	itation- SE	
Component:	Interior Walls /Ceiling	Defect:	Water Damage
Requirement:	Therior wais / ceiling	Defecti	water barriage
C		<u>Location:</u>	
<u>Comments:</u>	Kitchen & bathroom		
Component:	Interior Walls /Ceiling	Defect:	Absence of paint
Requirement:	inchor wans / centrig	·	Absence of paint
		Location:	Throughout
<u>Comments:</u>			
Component:	Interior Walle /Cailing	Defects	Holos or major defect
Requirement:	Interior Walls /Ceiling	<u>Defect:</u>	Holes or major defect
		<b>Location:</b>	Throughout
Comments:			
Component	Wising	Dofoot	Evnered
Component: Requirement:	Wiring	Defect:	Exposed
		<b>Location:</b>	
Comments:	Several areas		
		D ( :	
Component: Requirement:	Flooring	<u>Defect:</u>	Deteriorated
2104311 011101101		Location:	Throughout
Comments:			

Component:	Interior Stairway	Defect:	In poor repair
Requirement:		Location:	
Comments:	Both	Bocaeronn	
	boui		
Component:	Hand Rails	Defect:	Missing
<u>Requirement:</u>		Lasskiane	
Comments:		Location:	
	Both		
Component:	Smoke Detectors	Defect:	Missing Where Required
Requirement:			
Comments:		<u>Location:</u>	Throughout
<u>comments.</u>			
Component:	Bathroom Lavatory	Defect:	Missing
Requirement:	Batilloom Lavatory	Balada	Filssing
		<u>Location:</u>	
Comments:			
Component:	Functioning Water Closet	Defect:	Missing
Requirement:	Functioning water closet	<u>Defect.</u>	Hissing
		<b>Location:</b>	*
Comments:			
Commonanti	Tub/Chousey Walls	Defect:	Missing
Component: Requirement:	Tub/Shower Walls	Defect.	Missing
	*	<b>Location:</b>	
Comments:			
		D-fl-	N. C.
Component: Requirement:	Window Glazing/Paint	<u>Defect:</u>	Not impervious to weather
ittegun ementi		<b>Location:</b>	Throughout
Comments:			
Component: Requirement:	Foundation	<u>Defect:</u>	Leaks
<u> </u>		Location:	Basement
Comments:			
Component:	Floor Joists/Beams	Defect:	Excessive rot
Requirement:		Location:	Basement
Comments:			<u> </u>

Component: Requirement: Comments:	Floor Joists/Beams Engineering Report	Defect: Location:	Structurally inadequate  Basement
Component: Requirement:	Floor Joists/Beams	<u>Defect:</u>	Insect Infestation
Comments:	Need to be checked by pest control compa		Basement rovide invoice.
<u> </u>			
Component: Requirement:	Furnace Compliance, Uniform Mechanics Code	Defect:	In disrepair
Comments:	Have cleaned & checked for safe operable invoice	Location: condition b	by reputable company-provide
Component: Requirement:	Water Heater	Defect:	In disrepair
Comments:	Have cleaned & checked for safe operable invoice	Location: condition b	by reputable company-provide
Component: Requirement:	Electrical Other Fixtures	Defect:	In disrepair
Comments:	Panel is water damaged, must be checked	Location: by licensed	d contractor
Component:	Plumbing System	Defect:	In disrepair
Requirement: Comments:	Must be checked by licensed contractor	Location:	Throughout
Component:	Incompatible Breaker Panel	Defect:	In disrepair
Requirement: Comments:	Must be checked by licensed contractor	<u>Location:</u>	Throughout



56 C

thathe seel



thuthe sest