

.....

Date <u>April 17, 2017</u>

ABATEMENT OF PUBLIC NUISANCES AT 1530 4th STREET

WHEREAS, the property located at 1530 4th Street, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure and garage structure in their present condition constitutes not only a menace to health and safety but are also public nuisances; and

WHEREAS, the Titleholder, August Bauer, was notified more than thirty days ago to repair or demolish the main structure and garage structure and as of this date has failed to abate the nuisances.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA:

The main structure and garage structure on the real estate legally described as Lot 30 in BATES ADDITION to North Des Moines, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 1530 4th Street, have previously been declared public nuisances;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisances, and should the owner(s) fail to abate the nuisances, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said structures.

Moved by_____to adopt.

FORM APPROVED: <u>Justica D. Spoden</u>, Assistant City Attorney

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT	CERTIFICATE
COWNIE					
COLEMAN					I, DIANE RAUH, City Clerk of said City hereby
GATTO					certify that at a meeting of the City Council of said City of Des Moines, held on the above date, among
GRAY					other proceedings the above was adopted.
HENSLEY					
MOORE					IN WITNESS WHEREOF, I have hereunto set my
WESTERGAARD					hand and affixed my seal the day and year first above written.
TOTAL					
MOTION CARRIED			API	PROVED	
			1	Mayor	City Clerk



PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA

DATE OF INSPECTION:

December 15, 2016

CASE NUMBER:	COD2016-06921
PROPERTY ADDRESS:	1530 4TH ST
LEGAL DESCRIPTION:	LOT 30 BATES ADDITION

DATE OF NOTICE: January 19, 2017

AUGUST BAUER A/K/A MICHAEL AUGUST BAUER Title Holder 1311 4TH ST DES MOINES IA 50314

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-192 and 60-191 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council, sitting as the Board of Health, to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Jan L. Shafer (515) 283-4008

Nid Inspector

DATE MAILED: 1/18/2017

MAILED BY: JDH

400

Areas that need attention: 1530 4TH ST

Component:	Water	Defect:	Disconnected Utility
Requirement:	N N N N N N N N N N N N N N N N N N N		Water/Gas/Electric
Requirement		Looplans	
, ·		Location:	Main Structure
Comments:			
	Restore water service to structure.	14	· ·
	and a second		
Common and	Electrical Contine	Defect:	See Comments
Component:	Electrical Service	Delecti	See Comments
Requirement:	Compliance with National Electrical Code	t:	
		Location	Main Structure
		<u></u>	
Comments:	Repair vandalized meter socket. Requires	electrical ne	ermit and final inspection for
	· · ·		
	compliance.		x
Component:	Exterior Walls	Defect:	In poor repair
Requirement:			
<u>Requirement:</u>			Coverage
	ж.	Location:	Garage
Comments:			*
			;
(4)			
Commence	Wining	Defect	In poor repair
Component:	Wiring	Defect:	In poor repair
Requirement:	Compliance with National Electrical Code		е — — — — — — — — — — — — — — — — — — —
		Location:	
		modelvill	
Comments:	Electrical permit and final inspection requi	red for com	Inliance
	Electrical permit and final inspection requi		
Component:	Interior Stairway	Defect:	In poor repair
Component: Requirement:	Interior Stairway	Defect:	In poor repair
<u>Component:</u> <u>Requirement:</u>	Compliance with International Building	~	
		Defect: Location:	
Requirement:	Compliance with International Building	~	
	Compliance with International Building	~	
Requirement:	Compliance with International Building	~	
Requirement:	Compliance with International Building	~	
Requirement:	Compliance with International Building	~	
<u>Requirement:</u> <u>Comments:</u>	Compliance with International Building Code	Location:	
Requirement: Comments: Component:	Compliance with International Building Code Plumbing System	~	
<u>Requirement:</u> <u>Comments:</u>	Compliance with International Building Code Plumbing System	Location: Defect:	In poor repair
Requirement: Comments: Component:	Compliance with International Building Code	Location: Defect:	In poor repair
Requirement: Comments: Component: Requirement:	Compliance with International Building Code Plumbing System	Location:	In poor repair
Requirement: Comments: Component:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code	Location: Defect: Location:	In poor repair
Requirement: Comments: Component: Requirement:	Compliance with International Building Code Plumbing System	Location: Defect: Location:	In poor repair
Requirement: Comments: Component: Requirement:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code	Location: Defect: Location:	In poor repair
Requirement: Comments: Component: Requirement:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code	Location: Defect: Location:	In poor repair
Requirement: Comments: Component: Requirement: Comments:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code Plumbing permit and final inspection requi	Location: Defect: Location: red for com	In poor repair npliance/
Requirement: Comments: Component: Requirement: Comments:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code Plumbing permit and final inspection requi	Location: Defect: Location:	In poor repair
Requirement: Comments: Component: Requirement: Comments:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code	Location: Defect: Location: red for com	In poor repair npliance/
Requirement: Comments: Component: Requirement: Comments:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code Plumbing permit and final inspection requi	Location: Defect: Location: red for com	In poor repair npliance/ Cracked/Broken
Requirement: Comments: Component: Requirement: Comments:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code Plumbing permit and final inspection requi	Location: Defect: Location: red for com	In poor repair npliance/ Cracked/Broken
Requirement: Comments: Component: Requirement: Comments: Comments: Component: Requirement:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code Plumbing permit and final inspection requi	Location: Defect: Location: red for com	In poor repair npliance/ Cracked/Broken
Requirement: Comments: Component: Requirement: Comments:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code Plumbing permit and final inspection requi	Location: Defect: Location: red for com	In poor repair npliance/ Cracked/Broken
Requirement: Comments: Component: Requirement: Comments: Comments: Component: Requirement:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code Plumbing permit and final inspection requi	Location: Defect: Location: red for com	In poor repair npliance/ Cracked/Broken
Requirement: Comments: Component: Requirement: Comments: Comments: Component: Requirement:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code Plumbing permit and final inspection requi	Location: Defect: Location: red for com	In poor repair npliance/ Cracked/Broken
Requirement: Comments: Component: Requirement: Comments: Comments: Component: Requirement:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code Plumbing permit and final inspection requi	Location: Defect: Location: red for com	In poor repair npliance/ Cracked/Broken
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Requirement: Component: Component: Component: Requirement: Comments:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code Plumbing permit and final inspection requi Windows/Window Frames Repair all broken windows.	Location: Defect: Location: red for com Defect: Location:	In poor repair npliance/ Cracked/Broken
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Comments:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code Plumbing permit and final inspection requi	Location: Defect: Location: red for com	In poor repair npliance/ Cracked/Broken
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Comments:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code Plumbing permit and final inspection requi Windows/Window Frames Repair all broken windows.	Location: Defect: Location: red for com Defect: Location:	In poor repair npliance/ Cracked/Broken
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Requirement: Component: Component: Component: Requirement: Comments:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code Plumbing permit and final inspection requi Windows/Window Frames Repair all broken windows.	Location: Defect: Location: red for com Defect: Location: Defect:	In poor repair npliance/ Cracked/Broken In poor repair
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code Plumbing permit and final inspection requi Windows/Window Frames Repair all broken windows.	Location: Defect: Location: red for com Defect: Location:	In poor repair npliance/ Cracked/Broken In poor repair
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Comments:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code Plumbing permit and final inspection requi Windows/Window Frames Repair all broken windows. Interior Walls /Ceiling	Location: Defect: Location: red for com Defect: Location: Defect:	In poor repair npliance/ Cracked/Broken In poor repair
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code Plumbing permit and final inspection requi Windows/Window Frames Repair all broken windows.	Location: Defect: Location: red for com Defect: Location: Defect:	In poor repair npliance/ Cracked/Broken In poor repair
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code Plumbing permit and final inspection requi Windows/Window Frames Repair all broken windows. Interior Walls /Ceiling	Location: Defect: Location: red for com Defect: Location: Defect:	In poor repair npliance/ Cracked/Broken In poor repair
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Compliance with International Building Code Plumbing System Compliance with Uniform Plumbing Code Plumbing permit and final inspection requi Windows/Window Frames Repair all broken windows. Interior Walls /Ceiling	Location: Defect: Location: red for com Defect: Location: Defect:	In poor repair npliance/ Cracked/Broken In poor repair

\\CDMAPPS1\D-VOLUME\APPDATA\Tidemark\prd_41\Forms & Reports\dsmCODPubNo.rp

Component:	Foundation	Defect: Cracked/Broken		
Requirement:	Compliance with International Building			lind
2	Code	Location:		400
Comments:	Building permit and final inspection requir	ed for compliance.	,	
	· · · · ·			
Component:	Flooring	Defect: In poor repair		
Requirement:		ب	7	
		Location:		
Comments:	Repair hardwood floors and carneting	Location:	•	• •
<u>Comments:</u>	Repair hardwood floors and carpeting.	Location:		•
<u>Comments:</u>	Repair hardwood floors and carpeting.	Location:	-	

Polk County Assessor 📆

[Home] [General Query] [Legal Query] [HomeOwner Query] [Book/Page Query] [Commercial Ouery] [Res Sales Query] [Comm Sales Query] [Help]

District/Parcel	GeoParcel	Map	Nbhd	Jurisdiction	Status		
080/00331-000-000	7924-34-426-011	0136	DM79/Z	DES MOINES	ACTIVE		
School District	Tax Increment Finance District	Bond/Fire/Sewer/Cemetery					
1/Des Moines							
Street Address		City State Zipcode					
1530 4TH ST					DES MOINES IA 50314		

	Click on pa	arcel to get new listing	/ 14/1 1
60- CC	95	2-coule	<u>∫^щ*bd 05</u> 3:E-A\/:E-∞-
-18			135 EP
	0 0 		₽ \"€
	· · ·	1542 1543	305 300
Get	: :	1538 : : 1537	1536 -
Bigger 🖏	1534 = =	1534 : 1533	1534 5
Map F	: 1535	1530 : 슈 1531	:
Google	1522 : 2	$1530 = \frac{1}{1526} = 1531$ $1526 = \frac{1}{100}$ = 1525	1530 *
<u>Map</u>	а Пра	1520 : 1521	5
-	1520 = =	1518 - 1519	1528
-	1518 : :	1514 1- 1515	1514 9
-	1510 : 🙀 : 1511	1508 : m 1511	:
-	1506		1508 9



Approximate date of photo 07/17/2013

Mailing Address

AUGUST BAUER 1530 4TH ST DES MOINES, IA 50314-3212

Legal Description

LOT 30 BATES ADDITION

Ownership	Name	Recorded	Book/Page	RevStamps	
Title Holder #1	BAUER, AUGUST	2014-01-21	15087/220	40.80	

Assessment	Class	Kind	Land	Bldg	AgBd	Total			
Assmt Roll	Residential	Full	5,600	81,200	0	86,800			
Current	Residential	Full	5,100	73,500	0	78,600			
A	Assessment Roll Notice Estimate Taxes Polk County Treasurer Tax Information Pay Taxes								

ZoningDescriptionSFAssessor ZoningR1-60One Family, Low Density Residential DistrictResidential

http://www.assess.co.polk.ia.us/cgi-bin/invenquery/pickdp.cgi?dp08000331000000=080%2F00331-000-000&... 4/10/2017


401

Source: City of Des Moines Community Development Published: 2012-03-20 Contact: Planning and Urban Design 515 283-4182

Land					
SQUARE FEET	6,500	FRONTAGE	50.0	DEPTH	130.0
ACRES	0.149	SHAPE	RC/Rectangle	TOPOGRAPHY	N/Normal

Residence # 1					
OCCUPANCY	SF/Single Family	RESID TYPE	SP/Over 2 Stories	BLDG STYLE	CV/Conventional
YEAR BUILT	1905	# FAMILIES	1	GRADE	4
GRADE ADJUST	+05	CONDITION	AN/Above Normal	TSFLA	1,632
MAIN LV AREA	852	UPPR LV AREA	780	ATTIC UNFIN	273
BSMT AREA	780	OPEN PORCH	208	ENCL PORCH	30
DECK AREA	136	FOUNDATION	B/Brick	EXT WALL TYP	VN/Vinyl Siding
ROOF TYPE	H/Hip	ROOF MATERL	A/Asphalt Shingle	HEATING	A/Gas Forced Air
AIR COND	0	BATHROOMS	1	BEDROOMS	3
ROOMS	6				





Detached	<u># 101</u>										
OCCUPA	ANCY	GA	R/Garage	CONSTR 7	FYPE	FR	FR/Frame ME		SCODE	D/Dimensions	
MEASUI	RE1		18	MEASURE	2 <u>2</u> 22		22	22 STORY HEIGHT		1	
GRADE			4	YEAR BUI	LT	1989		89 CONDITION		NM/Normal	
Seller]	Buyer	yer Sale D		e Date	Sal	Sale Price Instrument		Book/Page	
JONES, N	ARK .	A	BAUER, A	UGUST	201	<u>4-01-14</u>		26,000 D/Deed		15087/220	
Year	Туре		Status		Appli	ication	Per	Permit/Pickup Description			
2006	U/Pick	tup	CP/Comp	lete	2005-	10-05	RV/CHECK CONDITION			N	
1990	P/Pern	nit	CP/Comp	blete 1988-06-28		06-28 New Garage					
1989	P/Pern	nit	PA/Pass		1			6-28 New Garage			

Year	Type	Class	Kind	Land	Bldg	AgBd	Total
2015	Assessment Roll	Residential	Full	5,100	73,500	0	78,600

http://www.assess.co.polk.ia.us/cgi-bin/invenquery/pickdp.cgi?dp08000331000000=080%2F00331-000-000&... 4/10/2017

Contractor and the second second

40D

2013	Assessment Roll	Residential	Full	5,100	72,600	0	77,700
2011	Assessment Roll	Residential	Full	5,100	74,700	0	79,800
2009	Assessment Roll	Residential	Full	4,900	68,500	0	73,400
2007	Assessment Roll	Residential	Full	5,200	72,100	0	77,300
2006	Assessment Roll	Residential	Full	4,600	49,000	0	53,600
2005	Assessment Roll	Residential	Full	4,600	44,600	0	49,200
2003	Assessment Roll	Residential	Full	4,430	42,330	0	46,760
2001	Assessment Roll	Residential	Full	3,960	36,350	0	40,310
1999	Assessment Roll	Residential	Full	4,580	25,270	0	29,850
1997	Assessment Roll	Residential	Full	3,750	20,680	0	24,430
1995	Assessment Roll	Residential	Full	3,370	18,580	0	21,950
1990	Assessment Roll	Residential	Full	2,920	16,080	0	19,000
1989	Assessment Roll	Residential	Full	2,920	13,880	0	16,800

email this page

Room 195, 111 Court Avenue, Des Moines, 1A 50309 Phone 515 286-3140 / Fax 515 286-3386 polkweb@assess.co.polk.ia.us

1000





