

Agenda Item Number 57B

Date May 8, 2017

ABATEMENT OF PUBLIC NUISANCE AT 2908 SE 14th STREET

WHEREAS, the property located at 2908 SE 14th Street, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure in its present condition constitutes not only a menace to health and safety but is also a public nuisance; and

WHEREAS, the Titleholders, All Known and Unknown Heirs to Eugene C. Anderson; Titleholders, All Known and Unknown Heirs to Frances E. Anderson; and Mortgage Holder, Community State Bank, were notified more than thirty days ago to repair or demolish the main structure and as of this date have failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA:

The main structure on the real estate legally described as The North 100 feet of Lot 41 OAK HILL, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, Except the East 7 feet thereof, and Except the East 185 feet of the South 40 feet of the North 100 feet of said Lot 41; And Except that part conveyed to the State of Iowa recorded in Book 5224 Page 567 and locally known as 2908 SE 14th Street, has previously been declared a public nuisance;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner(s) fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said structure.

Moved by ______to adopt.

FORM APPROVED:

Jessica D. Spoden, Assistant City Attorney

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT	CERTIFICATE
COWNIE					
COLEMAN					I, DIANE RAUH, City Clerk of said City hereby
GATTO					certify that at a meeting of the City Council of said
GRAY					City of Des Moines, held on the above date, among other proceedings the above was adopted.
HENSLEY					
MOORE					IN WITNESS WHEREOF, I have hereunto set my
WESTERGAARD					hand and affixed my seal the day and year first above written.
TOTAL					above written.
MOTION CARRIED			APP	ROVED	
			1	Mayor	City Clerk



PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA

DATE OF NOTICE: Februa	ary 7, 2017	DATE OF INS	SPECTION:	June 09, 2016		÷
CASE NUMBER:	COD2016-03288		÷	,		
PROPERTY ADDRESS:	2908 SE 14TH ST	٢				
LEGAL DESCRIPTION:	-EX BEG 7F W OF NE COR S 40F N 100F- N 100F LOT		TO N LN E 1.2	8F TO POB- & -EX	E 7F- & -EX	E 185F
FRANCES E ANDERSON Title Holder DECEASED				х. У		
COMMUNITY STATE BANK Mortgage Holder RONALD NAGEL, PRESIDEN 817 N ANKENY BLVD ANKENY IA 50023				к		
EUGENE ANDERSON Title Holder DECEASED						
An inspection of the reference Des Moines. It has been de menace to health and safety	termined from that inspectio	on that the dwe	lling currently	constitutes not only	ya	

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-192 and 60-191 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council, sitting as the Board of Health, to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free-to call. I can usually be reached between 8:00am and 9:00am, Monday

through Friday. Mike F Lehman

(515) 283-4299

Nid Inspector

DATE MAILED: 2/7/2017

MAILED BY: JDH

		Defe	Dehavlarstad		
Component:	Brick Chimney	Defect:	Deteriorated		
Requirement:	Compliance with International Building	s	12		
	Code	Location:	Roof		
Comments:					
				-	
				-	
		Defe	In noor		
Component:	Electrical System	Defect:	In poor repair		
<u>Requirement:</u>	Electrical Permit	nga panaga			
		Location:	Throughout		
Comments:				1.	
					£
			•		
Component:	Exterior Doors/Jams	Defect:	In poor repair		
Requirement:	Compliance with International Building				à.
<u>itequirententi</u>	Code	Location	Throughout		
Commenter			moughout		
Comments:					
		~			
		i.			•
		Defe	In many		
Component:	Exterior Walls	Defect:	In poor repair		
<u>Requirement:</u>	Compliance with International Building	2 12 10 10 10 10 10 10 10 10 10 10 10 10 10	T I		
	Code	Location:	Throughout		
Comments:		(Conc)			
				5	
	•			٤.	
Component:	Floor Joists/Beams	Defect:	In poor repair	9	
<u>Component:</u> <u>Requirement:</u>	Floor Joists/Beams Building Permit				
			In poor repair Throughout		
Requirement:					
Requirement:					
Requirement:					
Requirement: Comments:	Building Permit				
Requirement: Comments: Component:	Building Permit	Location:	Throughout	- -	
Requirement: Comments:	Building Permit	Location: Defect:	Throughout In poor repair		
Requirement: Comments: Component: Requirement:	Building Permit	Location: Defect:	Throughout		
Requirement: Comments: Component:	Building Permit	Location: Defect:	Throughout In poor repair		
Requirement: Comments: Component: Requirement:	Building Permit	Location: Defect:	Throughout In poor repair		
Requirement: Comments: Component: Requirement:	Building Permit	Location: Defect:	Throughout In poor repair		
Requirement: Comments: Component: Requirement: Comments:	Building Permit Flooring Complaince with Int Residential Code	Location: Defect: Location:	Throughout In poor repair Throughout		
Requirement: Comments: Component: Requirement: Comments:	Building Permit Flooring Complaince with Int Residential Code Mechanical System	Location: Defect:	Throughout In poor repair		
Requirement: Comments: Component: Requirement: Comments:	Building Permit Flooring Complaince with Int Residential Code	Location: Defect: Location: Defect:	Throughout In poor repair Throughout In poor repair		
Requirement: Comments: Component: Requirement: Comments: Comments: Component: Requirement: Component: Requirement:	Building Permit Flooring Complaince with Int Residential Code Mechanical System	Location: Defect: Location: Defect:	Throughout In poor repair Throughout		
Requirement: Comments: Component: Requirement: Comments:	Building Permit Flooring Complaince with Int Residential Code Mechanical System	Location: Defect: Location: Defect:	Throughout In poor repair Throughout In poor repair		
Requirement: Comments: Component: Requirement: Comments: Comments: Comments:	Building Permit Flooring Complaince with Int Residential Code Mechanical System	Location: Defect: Location: Defect:	Throughout In poor repair Throughout In poor repair		
Requirement: Comments: Component: Requirement: Comments: Comments: Comments:	Building Permit Flooring Complaince with Int Residential Code Mechanical System	Location: Defect: Location: Defect:	Throughout In poor repair Throughout In poor repair		
Requirement: Comments: Component: Requirement: Comments: Comments: Component: Requirement: Component: Requirement:	Building Permit Flooring Complaince with Int Residential Code Mechanical System	Location: Defect: Location: Defect: Location:	Throughout In poor repair Throughout In poor repair Throughout		
Requirement: Comments: Component: Requirement: Comments: Comments: Component: Requirement: Component: Requirement:	Building Permit Flooring Complaince with Int Residential Code Mechanical System	Location: Defect: Location: Defect:	Throughout In poor repair Throughout In poor repair		
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Comments:	Building Permit Flooring Complaince with Int Residential Code Mechanical System Mechanical Permit Interior Walls /Ceiling	Location: Defect: Location: Defect: Location: Defect:	Throughout In poor repair Throughout In poor repair Throughout In poor repair		
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Requirement: Component: Component: Component: Requirement: Comments:	Building Permit Flooring Complaince with Int Residential Code Mechanical System Mechanical Permit	Location: Defect: Location: Defect: Location: Defect:	Throughout In poor repair Throughout In poor repair Throughout In poor repair		
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Building Permit Flooring Complaince with Int Residential Code Mechanical System Mechanical Permit Interior Walls /Ceiling	Location: Defect: Location: Defect: Location: Defect:	Throughout In poor repair Throughout In poor repair Throughout		
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Comments:	Building Permit Flooring Complaince with Int Residential Code Mechanical System Mechanical Permit Interior Walls /Ceiling	Location: Defect: Location: Defect: Location: Defect:	Throughout In poor repair Throughout In poor repair Throughout In poor repair		
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Building Permit Flooring Complaince with Int Residential Code Mechanical System Mechanical Permit Interior Walls /Ceiling	Location: Defect: Location: Defect: Location: Defect:	Throughout In poor repair Throughout In poor repair Throughout In poor repair		
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Building Permit Flooring Complaince with Int Residential Code Mechanical System Mechanical Permit Interior Walls /Ceiling	Location: Defect: Location: Defect: Location: Defect:	Throughout In poor repair Throughout In poor repair Throughout In poor repair		

Areas that need attention: 2908 SE 14TH ST

	,	,
Component:	Plumbing System	Defect: In poor repair
Requirement:	Plumbing Permit	· · · ·
· ·		Location: Throughout
Comments:	· · · · · · · · · · · · · · · · · · ·	·
a a		· · · ·
2		
Component:	Smoke Detectors	Defect: Not installed as required
Requirement:	Compliance with International Building	a a a a a a a a a a a a a a a a a a a
	Code	Location: Throughout
Comments:		
Component:	Soffit/Facia/Trim	Defect: In disrepair
Requirement:	Compliance with International Building	
	Code	Location: Throughout
Comments:		
Component:	Window Glazing/Paint	Defect: In disrepair
Requirement:	Complaince with Int Residential Code	
		Location: Throughout
Comments:		
	6	
Component:	Windows/Window Frames	Defect: In poor repair
Requirement:	Compliance with International Building	
	Code	Location: Throughout
Comments:	5	·
	,	• · · · · · · · · · · · · · · · · · · ·
		٩






2908 SE 14th St



Page 1 of 3

Polk County Assessor

111 Court Avenue #195 Des Moines, IA 50309-0904 (515) 286-3014 Fax (515) 286-3386 polkweb@assess.co.polk.ia.us



http://wah.agagag.ag.nolls.ig.ug/agi.hin/wah/tt/infagry.agi?tt=gard/gard&dn=01003859001000&amn

Square Fee	t 34	,520 Acre	s 0	.792	Topography	Norma
Square ree	and the second state of the local division o	The second se		No	Unbuildable	No
		THE REAL PROPERTY OF THE PROPE	s - 1 Record		e un la companya di seconda di Oricci nen la se la policie da la policie di	NA TELEVISION TO BE TRANSPORTED TO A CONTRACT OF THE DESCRIPTION OF THE DESCRIPTION OF THE DESCRIPTION OF THE D
	angest designed i Andreadour ar ange for states a stat states.	Reside			a na ana amin'ny fana amin'ny fananana amin'ny fananana amin'ny fananana amin'ny fananana amin'ny fananana amin	
Occupancy	Single Family	Residence Type	e Finis	1 Story shed Attic	Building Style	Conventiona
Year Built	1920	Number Families	5	1	Grade	4+00
Condition	Poor	Total Square Foo Living Area		1444	Main Living Area	1074
Attic Finished Area	370	Attached Garage Square Foot		176	Basement Area	49'
Enclosed Porch Area	160	Foundatior	1	Masonry	Exterior Wall Type	Hardboar
Roof Type	Gable	Roof Materia	I Aspha	lt Shingle	Number Fireplaces	
Heating	Gas Forced Air	Air Conditioning		0	Number Bathrooms	
Bedrooms	3	Rooms	<u> </u>	6 11		
	14 3 6	21 33 14 14 14 14 14 14 14 14 14 14 14 8 7 8 8	- <u>ic</u>	11	14 2 14 8	
		Permits - 2				
Year Type	Permit S Complete	and a second	cation		Description e/check condition	

Yr	Туре	Class	Kind	Land	Bldg	Total
2015	Assessment Roll	Residential	Full	\$29,100	\$28,400	\$57,500
2013	Assessment Roll	Residential	Full	\$26,800	\$26,400	\$53,200
2012	Assessment Roll	Residential	Full	\$26,800	\$26,100	\$52,900
2011	Assessment Roll	Residential	Full	\$26,800	\$46,000	\$72,800
2009	Assessment Roll	Residential	Full	\$28,600	\$47,300	\$75,900
2007	Assessment Roll	Residential	Full	\$30,800	\$50,900	\$81,700
2005	Assessment Roll	Residential	Full	\$24,000	\$47,400	\$71,400
2003	Assessment Roll	Residential	Full	\$21,550	\$43,410	\$64,960
2001	Board Action	Residential	Full	\$18,700	\$34,540	\$53,240
2001	Assessment Roll	Residential	Full	\$18,700	\$34,540	\$53,240
1999	Assessment Roll	Residential	Full	\$15,440	\$33,830	\$49,270
1997	Assessment Roll	Residential	Full	\$13,590	\$29,780	\$43,370
1995	Assessment Roll	Residential	Full	\$12,570	\$27,550	\$40,120
1993	Assessment Roll	Residential	Full	\$11,120	\$24,380	\$35,500
1991	Assessment Roll	Residential	Full	\$10,590	\$23,220	\$33,810
1991	Was Prior Year	Residential	Full	\$10,590	\$20,540	\$31,130

Historical Values

This template was last modified on Sat Mar 4 12:31:48 2017 .

http://wah agagag ag palls is us/agi him/wah/tt/infogmy agi2tt-good/good & dr-01002850001000 & -----