

Agenda Item Number

Date June 26, 2017

ABATEMENT OF PUBLIC NUISANCE AT 2020 10th STREET

WHEREAS, the property located at 2020 10th Street, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure in its present condition constitutes not only a menace to health and safety but is also a public nuisance; and

WHEREAS, the Titleholder, Tanisha Ransey, was notified more than thirty days ago to repair or demolish the main structure and as of this date has failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA:


The main structure on the real estate legally described as Lot 112 in THIRD PLAT OF PROSPECT PARK, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 2020 10th Street, has previously been declared a public nuisance;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner(s) fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said structure.

Moved by_____to adopt.

FORM APPROVED: Jessica D. Spoden, Assistant City Attorney

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT	CERTIFICATE
COWNIE					
COLEMAN					I, DIANE RAUH, City Clerk of said City hereby
GATTO					certify that at a meeting of the City Council of said City of Des Moines, held on the above date, among
GRAY					other proceedings the above was adopted.
HENSLEY					
MOORE				÷	IN WITNESS WHEREOF, I have hereunto set my
WESTERGAARD					hand and affixed my seal the day and year first above written.
TOTAL					
MOTION CARRIED			AP	PROVED	
				Mayor	City Clerk



2020 10th Jt

dat






38G

Polk County Assessor

[<u>Home</u>][<u>General Query</u>][<u>Legal Query</u>][<u>HomeOwner Query</u>][<u>Book/Page Query</u>][<u>Commercial Query</u>][<u>Res Sales Query</u>] [<u>Comm Sales Query</u>][<u>Help</u>]

District/Parcel	GeoParcel	Map	Nbhd	Jurisdiction	Status
080/05571-000-000	7924-34-128-017	0120	DM78/Z	DES MOINES	ACTIVE
School District	Tax Increment Finance District	Bond/Fire/Sewer/Cemetery			
1/Des Moines					
Street Address	Zipcode				
2020 10TH ST		DES MOI	NES IA 50314		





Approximate date of photo 07/09/2013

Mailing Address

TANISHA RANSEY 1839 LOGAN AVE DES MOINES, IA 50316-3730

Legal Description

LOT 112 THIRD PLAT PROSPECT PARK


Ownership	Name	Name		Book/Page	R	RevStamps		
Title Holder #1	RANSEY, TANISHA	RANSEY, TANISHA		2002-05-06 9130/749		3.60		
Assessment	Class	Kind	Land	Bldg	AgB	d Total		
Assmt Roll	Residential	Full	10,900	45,400		0 56,300		
Current	Residential	Full	10,200	43,000		0 53,200		
Asses	Assessment Roll Notice Estimate Taxes Polk County Treasurer Tax Information Pay Taxes							

Zoning	Description	SF	Assessor Zoning	
R-3	Multiple Family Residential District		Multi-Family Residential	
		_		

Source: City of Des Moines Community Development Published: 2012-03-20 Contact: Planning and Urban Design 515 283-4182

Land					
SQUARE FEET	11,553	FRONTAGE	50.0	ACRES	0.265
SHAPE	RT/Rectangular	TOPOGRAPHY	N/Normal		

Residence # 1									
OCCUPANCY	SF/Single Family	RESID TYPE	S1/1 Story	BLDG STYLE	BG/Bungalow				
YEAR BUILT	1921	# FAMILIES	1	GRADE	4				
GRADE ADJUST	-05	CONDITION	NM/Normal	TSFLA	1,040				
MAIN LV AREA	1,040	BSMT AREA	1,031	FOUNDATION	B/Brick				
EXT WALL TYP	ST/Stucco	ROOF TYPE	GB/Gable	ROOF MATERL	A/Asphalt Shingle				
HEATING	A/Gas Forced Air	AIR COND	0	BATHROOMS	1				
BEDROOMS	2	ROOMS	5						



http://www.assess.co.polk.ia.us/cgi-bin/invenquery/homequery.cgi

Seller		Buyer			Sale Date	Sale Price	Instrument	Book/Page
CASTR	O, RAFAEL	ANSEY-ELNOUR, TANISHA			59,000	D/Deed	9130/749	
FATHER & SON, ENTERPRISES CASTR			O, RAFAEL		<u>1995-05-</u> <u>01</u>	26,000	C/Contract	7187/999
ROBER	TS, DWAINE L		TO, CHARLES DB ENTERP	A FATHEF	R <u>1993-06-</u> <u>22</u>	15,000	C/Contract	6806/123
ROBERTS, DWAINE L SHOUL					<u>1993-02-</u> <u>04</u>	16,000	C/Contract	6720/587
Year	Туре		Class	Kind	Land	Bldg	g AgBd	Total
2015	Assessment Roll		Residential	Full	10,200	43,000	0 0	53,200
2013	Assessment Roll		Residential	Full	9,700	40,400) 0	50,100
2011	Assessment Roll		Residential	Full	9,700	40,700	0 0	50,400
2009	Assessment Roll		Residential	Full	9,700	43,500) 0	53,200
2007	Assessment Roll		Residential	Full	10,000	44,800) 0	54,800
2005	Assessment Roll		Residential	Full	10,800	40,100	0 0	50,900
2003	Assessment Roll		Residential	Full	9,050	34,080	0 0	43,130
2001	Assessment Roll		Residential	Full	6,780	24,730	0 0	31,510
1999	Assessment Roll		Residential	Full	5,140	14,910	0 0	20,050
1997	Assessment Roll		Residential	Full	4,750	13,770	0 0	18,520
1995	Assessment Roll		Residential	Full	4,310	12,480	0 0	16,790
1995	Was Prior Year		Residential	Full	3,730	13,060	0 0	16,790

email this page

Room 195, 111 Court Avenue, Des Moines, IA 50309 Phone 515 286-3140 / Fax 515 286-3386 polloveb@assess.co.polk.ia.us



PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA

DATE OF NOTICE: March 6, 2017DATE OF INSPECTION:February 20, 2017CASE NUMBER:COD2017-01112PROPERTY ADDRESS:2020 10TH STLEGAL DESCRIPTION:LOT 112 THIRD PLAT PROSPECT PARK

TANISHA RANSEY Title Holder 1839 LOGAN AVE DES MOINES IA 50316-3730

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-192 and 60-191 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council, sitting as the Board of Health, to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

\CDMAPPS1\D-VOLUME\APPDATA\Tidemark\prd_41\Forms & Reports\dsmCODPubNo.rp

Appropriate building permits may required for those violations noted in the ecial Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Jan L. Shafer ((515) 283-4008

Nid Inspector DATE MAILED: 3/6/2017

MAILED BY: JDH

\CDMAPPS1\D-VOLUME\APPDATA\Tidemark\prd_41\Forms & Reports\dsmCODPubNo.rp

386

Areas that need attention: 2020 10TH ST

<u>Component:</u> <u>Requirement:</u>	Electrical System Compliance with National Electrical Code	Defect:	Deteriorated
		Location:	
<u>Comments:</u>	Permit and final inspection required for co	mpliance.	
<u>Component:</u>	Floor Joists/Beams	Defect:	Deteriorated
<u>Requirement:</u>	Compliance with International Building Code	Location:	
Comments:	Permit and final inspection required for co	mpliance.	
8			
Component:	Foundation	Defect:	Collapsed
Requirement:	Compliance with International Building Code	Location:	
Comments:	Have foundation inspected by qualified en		
	Must be done with building permit and fin		
Component:	Furnace	Defect:	In disrepair
Requirement:	Compliance, Uniform Mechanics Code		
Comments:		Location:	
	Have furnace inspected and serviced by que receipt.	ualified con	tractor. Provide copy of
	·		
<u>Component:</u> Requirement:	Flooring	Defect:	Deteriorated
Requirement:	Flooring	<u>Defect:</u> Location:	
	Flooring		
Requirement:	Flooring		
Requirement:	Flooring Interior Walls /Ceiling		
<u>Requirement:</u> <u>Comments:</u>	Interior Walls /Ceiling Compliance with International Building	Location: Defect:	
Requirement: Comments: Component:	Interior Walls /Ceiling	Location:	
Requirement: Comments: Component: Requirement:	Interior Walls /Ceiling Compliance with International Building	Location: Defect:	
Requirement: Comments: Component: Requirement: Comments:	Interior Walls /Ceiling Compliance with International Building Code	Location: Defect: Location:	Cracked/Broken
Requirement: Comments: Component: Requirement:	Interior Walls /Ceiling Compliance with International Building	Location: Defect:	
Requirement: Comments: Component: Requirement: Comments: Comments: Component: Requirement: Requirement: Requirement:	Interior Walls /Ceiling Compliance with International Building Code Landings	Location: Defect: Location:	Cracked/Broken
Requirement: Comments: Component: Requirement: Comments: Comments:	Interior Walls /Ceiling Compliance with International Building Code Landings	Location: Defect: Location: Defect: Location:	Cracked/Broken
Requirement: Comments: Component: Requirement: Comments: Comments: Component: Requirement: Requirement: Requirement:	Interior Walls /Ceiling Compliance with International Building Code Landings Complaince with Int Residential Code	Location: Defect: Location: Defect: Location:	Cracked/Broken
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Interior Walls /Ceiling Compliance with International Building Code Landings Complaince with Int Residential Code Repair front steps to meet height requirem Plumbing System	Location: Defect: Location: Defect: Location:	Cracked/Broken
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Interior Walls /Ceiling Compliance with International Building Code Landings Complaince with Int Residential Code Repair front steps to meet height requirem	Location: Defect: Location: Defect: hents.	Cracked/Broken Major sagging
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Interior Walls /Ceiling Compliance with International Building Code Landings Complaince with Int Residential Code Repair front steps to meet height requirem Plumbing System Compliance with Uniform Plumbing Code	Location: Defect: Location: Defect: Location: nents. Defect: Location:	Cracked/Broken Major sagging
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Interior Walls /Ceiling Compliance with International Building Code Landings Complaince with Int Residential Code Repair front steps to meet height requirem Plumbing System	Location: Defect: Location: Defect: Location: nents. Defect: Location:	Cracked/Broken Major sagging

<u>Component:</u> <u>Requirement:</u> <u>Comments:</u>	Windows/Window Frames Compliance w ^{*****} *nternational Building Code	Defect: Deteriorated	38
Component: Requirement: Comments:	Wiring Compliance with National Electrical Code Permit and final inspection required for co	<u>Defect:</u> In poor repair <u>Location:</u> mpliance.	
Component: <u>Requirement:</u> Comments:	Flooring Compliance with International Building Code Replace broken concrete floor throughout	Defect: Cracked/Broken Location: basement.	
Component: Requirement: Comments:		Defect: Location:	

.....

.

,

•