

Date July 24, 2017

ABATEMENT OF PUBLIC NUISANCE AT 1108 13th STREET

WHEREAS, the property located at 1108 13th Street, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure in its present condition constitutes not only a menace to health and safety but is also a public nuisance; and

WHEREAS, the Titleholder, Susan Hill, was notified more than thirty days ago to repair or demolish the main structure and as of this date has failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA:

The main structure on the real estate legally described as Lot 1 in SAUCERMAN & ENGLISH ADDITION, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 1108 13th Street, has previously been declared a public nuisance;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner(s) fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said structure.

Moved by_____to adopt.

FORM APPROVED:

Jessica D. Spoden, Assistant City Attorney


COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT	CERTIFICATE
COWNIE					
COLEMAN					I, DIANE RAUH, City Clerk of said City hereby
GATTO					certify that at a meeting of the City Council of said City of Des Moines, held on the above date, among
GRAY					other proceedings the above was adopted.
HENSLEY					
MOORE					IN WITNESS WHEREOF, I have hereunto set my
WESTERGAARD					hand and affixed my seal the day and year first above written.
TOTAL					
MOTION CARRIED		•	API	ROVED	
			1	Mayor	City Clerk

48.

Polk County Assessor 📆

[Home] [General Query] [Legal Query] [HomeOwner Query] [Book/Page Query] [Commercial Query] [Res Sales Query] [Comm Sales Query] [Help]

District/Parcel	GeoParcel	Map	Nbhd	Jurisdiction	Status
030/04524-000-000	7824-04-104-015	0063	DM76/Z	DES MOINES	ACTIVE
School District	Tax Increment Finance District	Bond/Fire/Sewer/Cemetery			
1/Des Moines					
Street Address		City State Zipcode			
1108 13TH ST		DES MOINES IA 50314-2250			



Mailing Address

SUSAN G HILL 2958 KADING RD PERRY, IA 50220-2374

Legal Description

LOT 1 SAUCERMAN & ENGLISH ADD

Ownership	Name	Recorded	Book/Page	RevStamps
Title Holder #1	HILL, SUSAN	2011-03-28	13807/649	


Assessment	Class		Kind		Land	Bldg	AgBd	Total
Current	Residential		Full		6,700	3,200	0	9,900
Assessment	Roll Notice	Estimate T	axes Po	olk Co	unty Treasure	er Tax Informa	tion Pay Taxes	5

Zoning	Description	SF	Assessor Zoning			
R-3	Multiple Family Residential District		Multi-Family Residential			
Source: Ci	Source: City of Des Moines Community Development Published: 2012-03-20 Contact: Planning and Urban Design 515 283-4182					

Land					
SQUARE FEET	5,852	FRONTAGE	44.0	DEPTH	133.0
ACRES	0.134	SHAPE	RC/Rectangle	TOPOGRAPHY	N/Normal

.

Residence # 1	· · · · · · · · · · · · · · · · · · ·				
OCCUPANCY	SF/Single Family	RESID TYPE	UA/1 Story with Unfinished Attic	BLDG STYLE	BG/Bungalow
YEAR BUILT	1885	# FAMILIES	1	GRADE	5
GRADE ADJUST	+05	CONDITION	VP/Very Poor	TSFLA	1,094
MAIN LV AREA	1,094	ATTIC UNFIN	377	BSMT AREA	1,094
ENCL PORCH	128	FOUNDATION	B/Brick	EXT WALL TYP	CO/Composition
ROOF TYPE	GB/Gable	ROOF MATERL	A/Asphalt Shingle	HEATING	A/Gas Forced Air
AIR COND	0	BATHROOMS	1	BEDROOMS	3
ROOMS	7				



<u>Seller</u>		Buyer	Sale Date	Sale I	Price Inst	rument	Book/Page
VANDI	ERHOEF, RICHARD	HILL, SUSAN	HILL, SUSAN <u>2010-05-10</u>		10,000 C/Co		13441/778
X 7				Truck	DIJ	A-D	d Total
Year	Type	Class	Kind	Land	Bldg	AgB	1 Iotal
2017	Assessment Roll	Residential	Full	6,700	3,200)	9,900
2015	Assessment Roll	Residential	Full	6,700	3,200		9,900
2013	Assessment Roll	Residential	Full	6,900	2,900		9,800
2011	Assessment Roll	Residential	Full	7,400	3,500		0 10,900
2009	Assessment Roll	Residential	Full	5,600	4,200		0 9,800
2007	Assessment Roll	Residential	Full	5,400	4,000)	0 9,400
2005	Assessment Roll	Residential	Full	5,400	19,900	1	0 25,300
2003	Assessment Roll	Residential	Full	4,420	16,230		0 20,650
2001	Assessment Roll	Residential	Full	4,250	16,000		0 20,250
1999	Assessment Roll	Residential	Full	4,000	11,160		0 15,160

http://www.assess.co.polk.ia.us/cgi-bin/invenquery/homequery.cgi

1997	Assessment Roll	Residential	Full	3,270	9,130	0	12,400
1995	Assessment Roll	Residential	Full	3,050	8,510	0	11,560
1989	Assessment Roll	Residential	Full	2,640	7,360	0	10,000

email this page

Room 195, 111 Court Avenue, Des Moines, 1A 50309 Phone 515 286-3140 / Fax 515 286-3386 polkweb@assess.co.polk.ia.us

No.



DATE OF NOTICE: March 6, 2017

PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA

DATE	OF	INSPECTION:	Februar

February 22, 2017

CASE NUMBER:	COD2017-01197
PROPERTY ADDRESS:	1108 13TH ST
LEGAL DESCRIPTION:	LOT 1 SAUCERMAN & ENGLISH ADD

SUSAN HILL Title Holder 2958 KADING RD PERRY IA 50220-2374

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-192 and 60-191 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council, sitting as the Board of Health, to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Jan L. Shafer (515) 283-4008

Nid Inspector

DATE MAILED: 3/6/2017

MAILED BY: JDH

\\CDMAPPS1\D-VOLUME\APPDATA\Tidemark\prd_41\Forms & Reports\dsmCODPubNo.rp

48B

Areas that need attention: 1108 13TH ST

Component:	Electrical Lighting Fixtures	Defect:	In disrepair
<u>Requirement:</u>		Location:	
Comments:			
Component:	Electrical System	Defect:	In disrepair
Requirement:	Compliance with National Electrical Code	Location:	
Comments:	Downsith and final increastion required for co		
	Permit and final inspection required for co	mpliance.	
			-
Component:	Exterior Doors/Jams	Defect:	In disrepair
Requirement:	Compliance with International Building	Lacation	
Comments:	Code	Location:	
Component:	Flooring	Defect:	Deteriorated
Requirement:	5		
Comments:		Location:	
<u>comments.</u>			
Component:	Foundation	Defect:	Collapsed
<u>Component:</u> <u>Requirement:</u>	Foundation Compliance with International Building	Defect:	Collapsed
Requirement:	Compliance with International Building Code	Location:	
	Compliance with International Building Code Have foundation inspected by qualified en	Location:	
Requirement:	Compliance with International Building Code	Location:	
Requirement: Comments:	Compliance with International Building Code Have foundation inspected by qualified en Permit and final inspection required for co	Location: gineer. Hav mpliance.	re repairs made as needed.
Requirement:	Compliance with International Building Code Have foundation inspected by qualified en	Location: gineer. Hav ompliance. Defect:	re repairs made as needed. In poor repair
Requirement: Comments: Component: Requirement:	Compliance with International Building Code Have foundation inspected by qualified en Permit and final inspection required for co Furnace Compliance, Uniform Mechanics Code	Location: gineer. Hav mpliance. Defect: Location:	re repairs made as needed. In poor repair
Requirement: Comments: Component:	Compliance with International Building Code Have foundation inspected by qualified en Permit and final inspection required for co Furnace	Location: gineer. Hav mpliance. Defect: Location:	re repairs made as needed. In poor repair
Requirement: Comments: Component: Requirement:	Compliance with International Building Code Have foundation inspected by qualified en Permit and final inspection required for co Furnace Compliance, Uniform Mechanics Code	Location: gineer. Hav mpliance. Defect: Location:	re repairs made as needed. In poor repair
Requirement: Comments: Component: Requirement: Comments:	Compliance with International Building Code Have foundation inspected by qualified en Permit and final inspection required for co Furnace Compliance, Uniform Mechanics Code Have furnace service and repaired by qua	Location: ogineer. Hav ompliance. Defect: Location: lified contra	re repairs made as needed. In poor repair actor. provide copy of receipt.
Requirement: Comments: Component: Requirement:	Compliance with International Building Code Have foundation inspected by qualified en Permit and final inspection required for co Furnace Compliance, Uniform Mechanics Code	Location: ogineer. Hav ompliance. Defect: Location: lified contra	re repairs made as needed. In poor repair actor. provide copy of receipt. Holes or major defect
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Requirement: Comments:	Compliance with International Building Code Have foundation inspected by qualified en Permit and final inspection required for co Furnace Compliance, Uniform Mechanics Code Have furnace service and repaired by qua Interior Walls /Ceiling	Location: ogineer. Hav ompliance. Defect: Location: lified contra	re repairs made as needed. In poor repair actor. provide copy of receipt. Holes or major defect
Requirement: Comments: Component: Requirement: Comments:	Compliance with International Building Code Have foundation inspected by qualified en Permit and final inspection required for co Furnace Compliance, Uniform Mechanics Code Have furnace service and repaired by qua Interior Walls /Ceiling Compliance with International Building	Location: ogineer. Hav ompliance. Defect: Location: Defect: Location:	re repairs made as needed. In poor repair actor. provide copy of receipt. Holes or major defect
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Requirement: Comments:	Compliance with International Building Code Have foundation inspected by qualified en Permit and final inspection required for co Furnace Compliance, Uniform Mechanics Code Have furnace service and repaired by qua Interior Walls /Ceiling Compliance with International Building Code	Location: ogineer. Hav ompliance. Defect: Location: Defect: Location:	re repairs made as needed. In poor repair actor. provide copy of receipt. Holes or major defect
Requirement: Comments: Component: Requirements: Comments: Component: Requirement: Component: Component: Component: Component: Component: Requirement: Comments:	Compliance with International Building Code Have foundation inspected by qualified en Permit and final inspection required for co Furnace Compliance, Uniform Mechanics Code Have furnace service and repaired by qua Interior Walls /Ceiling Compliance with International Building Code Permit and final inspection required for co	Location: ogineer. Hav ompliance. Defect: Location: lified contra Defect: Location: ompliance.	re repairs made as needed. In poor repair actor. provide copy of receipt. Holes or major defect
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Requirement: Comments:	Compliance with International Building Code Have foundation inspected by qualified en Permit and final inspection required for co Furnace Compliance, Uniform Mechanics Code Have furnace service and repaired by qua Interior Walls /Ceiling Compliance with International Building Code	Location: ompliance. Defect: Location: lified contra Defect: Location: ompliance.	re repairs made as needed. In poor repair actor. provide copy of receipt. Holes or major defect In poor repair
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Requirement:	Compliance with International Building Code Have foundation inspected by qualified en Permit and final inspection required for co Furnace Compliance, Uniform Mechanics Code Have furnace service and repaired by qua Interior Walls /Ceiling Compliance with International Building Code Permit and final inspection required for co Mechanical System	Location: ogineer. Hav ompliance. Defect: Location: lified contra Defect: Location: ompliance.	re repairs made as needed. In poor repair actor. provide copy of receipt. Holes or major defect In poor repair
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Requirement: Component: Requirement: Component: Requirement: Component: Component:	Compliance with International Building Code Have foundation inspected by qualified en Permit and final inspection required for co Furnace Compliance, Uniform Mechanics Code Have furnace service and repaired by qua Interior Walls /Ceiling Compliance with International Building Code Permit and final inspection required for co Mechanical System	Location: ompliance. Defect: Location: lified contra Defect: Location: ompliance. Defect: Location:	re repairs made as needed. In poor repair actor. provide copy of receipt. Holes or major defect In poor repair

	· · ·			
Component:	Plumbing System	Defect:	In poor repair	
Requirement:	Compliance with Uniform Plumbing Code			
1.		Location:		
Comments:				
	Permit and final inspection required for co	mpliance.	3	
Component:	Roof	Defect:	In poor repair	
Requirement:	Compliance with International Building	Dereder	In poor repair	
<u>Requirement:</u>		Location:		
	Code	LUCALIOII.		
Comments:	Permit and final inspection required for co	mpliance.		
Component:	Soffit/Facia/Trim	Defect:	In poor repair	
<u>Requirement:</u>	Compliance with International Building			
	Code	Location:		
Comments:				í.
Component:	Stairs/Stoon	Defect:	In poor repair	
Component:	Stairs/Stoop	Defect:	In poor repair	
Component: Requirement:	Compliance with International Building		In poor repair	
Requirement:		Defect: Location:	In poor repair	
	Compliance with International Building	Location:	In poor repair	
Requirement:	Compliance with International Building Code	Location:	In poor repair	
Requirement:	Compliance with International Building Code	Location:	In poor repair	
<u>Requirement:</u> <u>Comments:</u>	Compliance with International Building Code Permit and final inspection required for co	Location: mpliance.		
Requirement: Comments: Component:	Compliance with International Building Code Permit and final inspection required for co Windows/Window Frames	Location:	In poor repair In poor repair	
<u>Requirement:</u> <u>Comments:</u>	Compliance with International Building Code Permit and final inspection required for co Windows/Window Frames Compliance with International Building	Location: mpliance. Defect:		
Requirement: Comments: Component:	Compliance with International Building Code Permit and final inspection required for co Windows/Window Frames	Location: mpliance.		
Requirement: Comments: Component:	Compliance with International Building Code Permit and final inspection required for co Windows/Window Frames Compliance with International Building	Location: mpliance. Defect:		
Requirement: Comments: Component: Requirement:	Compliance with International Building Code Permit and final inspection required for co Windows/Window Frames Compliance with International Building	Location: mpliance. Defect:		
Requirement: Comments: Component: Requirement:	Compliance with International Building Code Permit and final inspection required for co Windows/Window Frames Compliance with International Building	Location: mpliance. Defect:		
Requirement: Comments: Component: Requirement:	Compliance with International Building Code Permit and final inspection required for co Windows/Window Frames Compliance with International Building	Location: mpliance. Defect: Location:	In poor repair	
Requirement: Comments: Component: Requirement:	Compliance with International Building Code Permit and final inspection required for co Windows/Window Frames Compliance with International Building	Location: mpliance. Defect:		
Requirement: Comments: Component: Requirement: Comments:	Compliance with International Building Code Permit and final inspection required for co Windows/Window Frames Compliance with International Building Code	Location: mpliance. Defect: Location:	In poor repair	
Requirement: Comments: Component: Requirement: Comments: Comments:	Compliance with International Building Code Permit and final inspection required for co Windows/Window Frames Compliance with International Building Code	Location: mpliance. Defect: Location:	In poor repair	
Requirement: Comments: Component: Requirement: Comments:	Compliance with International Building Code Permit and final inspection required for co Windows/Window Frames Compliance with International Building Code	Location: mpliance. Defect: Location: Defect: Location:	In poor repair	
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments:	Compliance with International Building Code Permit and final inspection required for co Windows/Window Frames Compliance with International Building Code	Location: mpliance. Defect: Location: Defect: Location:	In poor repair	
Requirement: Comments: Component: Requirement: Comments: Comments: Comments:	Compliance with International Building Code Permit and final inspection required for co Windows/Window Frames Compliance with International Building Code	Location: mpliance. Defect: Location: Defect: Location:	In poor repair	

48B 1108 13th St top 2017 12



1108 13th St

