

3

.....

Date March 19, 2018

ABATEMENT OF PUBLIC NUISANCES AT 2809 E 33rd STREET

WHEREAS, the property located at 2809 E 33rd Street, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure and garage structures in their present condition constitutes not only a menace to health and safety but are also public nuisances; and

WHEREAS, the Titleholder, Beth M. Lewis, and Mortgage Holder, Ocwen Loan Servicing, LLC, were notified more than thirty days ago to repair or demolish the main structure and garage structures and as of this date have failed to abate the nuisances.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA:

The main structure and garage structures on the real estate legally described as Lot 1003 in FOUR MILE, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 2809 E 33rd Street, have previously been declared public nuisances;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisances, and should the owner fail to abate the nuisances, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said structures.

Moved by ______to adopt.

FORM APPROVED: Almica D. Span

Jessica D. Spoden, Assistant City Attorney

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT	CERTIFICATE
COWNIE					
BOESEN					I, DIANE RAUH, City Clerk of said City hereby
COLEMAN					certify that at a meeting of the City Council of said City of Des Moines, held on the above date, among
GATTO					other proceedings the above was adopted.
GRAY					x v
MANDELBAUM					IN WITNESS WHEREOF, I have hereunto set my
WESTERGAARD					hand and affixed my seal the day and year first above written.
TOTAL					
MOTION CARRIED			AP	PROVED	
				Mayor	City Clerk



PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA

DATE OF INSPECTION:

July 27, 2017

DATE OF NOTICE: Nove	mber 30, 2017
CASE NUMBER:	COD2017-05291
PROPERTY ADDRESS:	2809 E 33RD ST
LEGAL DESCRIPTION:	LOT 1003 FOUR MILE

BETH M LEWIS Title Holder 1601 ARMY POST RD #4 DES MOINES IA 50315

OCWEN LOAN SERVICING LLC Mortgage Holder CORPORATION SERV. CO., R.A. 505 5TH AVE SUITE 729 DES MOINES IA 50309

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-192 and 60-191 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council, sitting as the Board of Health, to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Justin S. Denning

(515) 237-1484

Nid Inspector DATE MAILED: 11/30/2017

MAILED BY: JDH

Areas that need attention: 2809 E 33RD ST

Component:	Electrical System		Defect:	In poor repair
Requirement:	Electrical Permit			12204 • Krausson 20100 - 211000 Roome Lot
Commontes			Location:	Throughout
Comments:		7 <u>4</u>		
	2			
Component:	Mechanical System		Defect:	In disrepair
Requirement:	Mechanical Permit	25		26 D
C	e 28		Location:	Throughout
Comments:		•		
Component:	Plumbing System		Defect:	In disrepair
Requirement:	Plumbing Permit			3
Commenter		÷.	Location:	Throughout
Comments:				
Component:	Interior Walls /Ceiling		Defect:	Deteriorated
Requirement:	Building Permit			
Comments:			Location:	Throughout
<u>comments.</u>				
10		8		
Component:	Roof		Defect:	Deteriorated
<u>Component:</u> <u>Requirement:</u>	Roof Building Permit			
Requirement:		3		Deteriorated Throughout
Requirement:		e		
<u>Requirement:</u> <u>Comments:</u>	Building Permit	5	Location:	Throughout .
Requirement: Comments: Component:	Building Permit Exterior Doors/Jams			
<u>Requirement:</u> <u>Comments:</u>	Building Permit		Location: Defect:	Throughout Deteriorated
Requirement: Comments: Component: Requirement:	Building Permit Exterior Doors/Jams		Location: Defect:	Throughout .
Requirement: Comments: Component:	Building Permit Exterior Doors/Jams	ж 1	Location: Defect:	Throughout Deteriorated
Requirement: Comments: Component: Requirement:	Building Permit Exterior Doors/Jams		Location: Defect:	Throughout Deteriorated
Requirement: Comments: Component: Requirement: Comments:	Building Permit Exterior Doors/Jams Building Permit		Location: Defect: Location:	Throughout Deteriorated Throughout
Requirement: Comments: Component: Requirement: Comments:	Building Permit Exterior Doors/Jams Building Permit Exterior Walls		Location: Defect:	Throughout Deteriorated
Requirement: Comments: Component: Requirement: Comments:	Building Permit Exterior Doors/Jams Building Permit	a I	Location: Defect: Location: Defect:	Throughout Deteriorated Throughout Deteriorated
Requirement: Comments: Component: Requirement: Comments:	Building Permit Exterior Doors/Jams Building Permit Exterior Walls	2	Location: Defect: Location: Defect:	Throughout Deteriorated Throughout
Requirement: Comments: Component: Requirement: Comments: Component: Requirement:	Building Permit Exterior Doors/Jams Building Permit Exterior Walls		Location: Defect: Location: Defect:	Throughout Deteriorated Throughout Deteriorated
Requirement: Comments: Component: Requirement: Comments: Component: Requirement:	Building Permit Exterior Doors/Jams Building Permit Exterior Walls		Location: Defect: Location: Defect:	Throughout Deteriorated Throughout Deteriorated
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Building Permit Exterior Doors/Jams Building Permit Exterior Walls Building Permit		Location: Defect: Location: Defect: Location:	Throughout Deteriorated Throughout Deteriorated Throughout
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Building Permit Exterior Doors/Jams Building Permit Exterior Walls Building Permit		Location: Defect: Location: Defect:	Throughout Deteriorated Throughout Deteriorated
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Building Permit Exterior Doors/Jams Building Permit Exterior Walls Building Permit		Location: Defect: Location: Location: Defect:	Throughout Deteriorated Throughout Deteriorated Throughout In poor repair
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Building Permit Exterior Doors/Jams Building Permit Exterior Walls Building Permit		Location: Defect: Location: Location: Defect:	Throughout Deteriorated Throughout Deteriorated Throughout
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Building Permit Exterior Doors/Jams Building Permit Exterior Walls Building Permit		Location: Defect: Location: Location: Defect:	Throughout Deteriorated Throughout Deteriorated Throughout In poor repair


Component: Requirement: Comments:	Windows/Window Frames Building Permit	S	<u>Defect:</u> Location:	Improperly grounded
<u>Component:</u> <u>Requirement:</u>	Accessory Buildings Permit Required		Defect:	Deteriorated
<u>Comments:</u>	i cimic required	÷	Location:	Throughout
	Garage.			Ċ.
		and the second		
Component: Requirement:	Accessory Buildings Permit Required		Defect:	Deteriorated
	Pennic Required		Location:	Throughout
<u>Comments:</u>	Garage.	3		
Component:	Soffit/Eacia/Trim		Defect:	Deteriousted
Requirement:	Soffit/Facia/Trim Building Permit		Delett	Deteriorated
	<i></i>		Location:	Throughout
<u>Comments:</u>				2

52 A

Polk County Assessor

[<u>Home</u>] [<u>General Query</u>] [<u>Legal Query</u>] [<u>HomeOwner Query</u>] [<u>Book/Page Query</u>] [<u>Commercial Query</u>] [<u>Res Sales Query</u>] [[<u>Comm Sales Query</u>] [<u>Help</u>]

District/Parcel	GeoParcel	Map	Nbhd	Jurisdiction	Status
060/04686-000-000	7923-29-401-003	0813	DM12/B	DES MOINES	ACTIVE
School District	Tax Increment Finance District	Bond/Fire/Sewer/Cemetery		and the second second	
1/Des Moines					
Street Address			City State	Zipcode	
2809 E 33RD ST	Г		DES MOINES IA 50317-3733		33





Approximate date of photo 08/06/2014

Mailing Address

BETH M LEWIS 2809 E 33RD ST DES MOINES, IA 50317-3733

Legal Description

LOT 1003 FOUR MILE

Ownership	Name		Recorded	Book/Page	RevStan	nps
Title Holder #1	LEWIS, BETH M 1988-06-20		5886/549			
Assessment	Class	Kind	Land	Bldg	AgBd	Total

rissessment	Class	ising	Luna	B	1.9.0.0	2 0 0 Mi
Current	Residential	Full	27,500	16,000	0	43,500
	Assessment Roll Notice	Estimate Taxes	Polk County Treasu	urer Tax Informati	ion Pay Taxes	5


ZoningDescriptionSFAssessor ZoningFWFloodway District32662FloodwayR1-60One Family, Low Density Residential District29287Residential

-

Source: City of Des Moines Community Development Published: 2012-03-20 Contact: Planning and Urban Design 515 283-4182

Land						
SQUARE FEET	61,950	FRONTAGE	105.0	DEPTH	590.0	
ACRES	1.422	SHAPE	RC/Rectangle	TOPOGRAPHY	N/Normal	

Residence # 1					
OCCUPANCY	SF/Single Family	RESID TYPE	S2/2 Stories	BLDG STYLE	ET/Early 20s
YEAR BUILT	1920	# FAMILIES	1	GRADE	4
GRADE ADJUST	+00	CONDITION	VP/Very Poor	TSFLA	2,140
MAIN LV AREA	1,188	UPPR LV AREA	952	BSMT AREA	952
FIN BMT AREA	400	FIN BMT QUAL	AV/Average	OPEN PORCH	240
PATIO AREA	552	FOUNDATION	C/Concrete Block	EXT WALL TYP	VN/Vinyl Siding
ROOF TYPE	GB/Gable	ROOF MATERL	A/Asphalt Shingle	FIREPLACES	1
HEATING	A/Gas Forced Air	AIR COND	0	BATHROOMS	2
BEDROOMS	4	ROOMS	8		



Detached # 101					
OCCUPANCY	SHD/Shed	CONSTR TYPE	FR/Frame	MEASCODE	D/Dimensions
MEASURE1	10	MEASURE2	24	STORY HEIGHT	1
GRADE	4	YEAR BUILT	1965	CONDITION	BN/Below Normal
COMMENT	DET.201 GAR DE	T.301/302 BARN			

Detached # 201							
OCCUPANCY	GAR/Garage	CONSTR TYPE	FR/Frame	MEASCODE	D/Dimensions		
MEASURE1	24	MEASURE2	26	STORY HEIGHT	1		
GRADE	4	YEAR BUILT	1965	CONDITION	NM/Normal		

Detached # 301						
OCCUPANCY	BFL/Flat Barn	CONSTR TYPE	FR/Frame	MEASCODE	D/Dimensions	
MEASURE1	16	MEASURE2	24	STORY HEIGHT	1	

GRADE		1	4	YEAR BUILT			1965			CONDITION			PR/Poor			
Detached # 302																
										FR/Frame MEASCODE				D/Dimensions		
MEASURE1				MEASURE2			24			STORY HEIGHT			1			
GRADE		4		YEAR BUILT			1965		CONDITION			PR/Poor				
Seller	and the local sector of the	Buyer	and the second	Sale Da						rice Instrument		nt	Book/Page			
UNKNOWN			EWIS, BETH M.			88-06	-17	75,000 D/Deed 5886/549								
Year	Type Status			Applica			ication	Permit/Pickup Descript				cripti	on			
2017	U/Pick	cup	plete 2017-			-01-11	RV/CHECK COND			ITION						
Year	Туре			Class			Kind	Land			Bldg	A	gBd	Total		
2017		ment Roll	1	Residential			Full	27,500			16,000		0	43,500		
2015	Assess	ment Roll		Residential			Full	25,300			103,500		0	128,800		
2013	Assess	ment Roll	<u> </u>	Residential			Full	24,600			102,500		0	127,100		
2011	Assess	Assessment Roll		Residential			Full	24,600			101,700		0	126,300		
2009	Assess	ssessment Roll		Residential			Full	27,300			109,500		0	136,800		
2007	Assess	Assessment Roll		Residential			Full	29,400			118,000		0	147,400		
2005	Assessment Roll		1	Residential			Full	21,300			93,100		0	114,400		
2003	Assessment Roll			Residential			Full	19,670			87,040		0	106,710		
2001	Assessment Roll			Residential			Full	19,340			76,640		0	95,980		
1999	Assessment Roll			Residential			Full	4,560			69,830		0	74,390		
1997	Assessment Roll			Residential			Full	4,020			61,580		0	65,600		
1995	Assess	Assessment Roll			Residential			3,810			58,340		0	62,150		
1993	Assess	Assessment Roll			Residential			3,370			53,330		0			
1991	Board Action						Full	3,120			49,380	-	0	52,500		
1991	Assessment Roll			Residential			Full	3,120			49,380		0			
1991	Was Prior Year			Residential			Full		3,120		38,400		0	41,520		

email this page

Room 195, 111 Court Avenue, Des Moines, IA 50309 Phone 515 286-3140 / Fax 515 286-3386 polkveb@assess.co.polk.ia.us



2809 E. 33ml St 52A





