

Agenda Item Number

.....

Date April 9, 2018

ABATEMENT OF PUBLIC NUISANCE AT 814 OLINDA AVENUE

WHEREAS, the property located at 814 Olinda Avenue, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure in its present condition constitutes not only a menace to health and safety but is also a public nuisance; and

WHEREAS, the Titleholders, Teri King and Jerry King, was notified more than thirty days ago to repair or demolish the main structure and as of this date has failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA:

The main structure on the real estate legally described as Lot 382 in FIRST PLAT OF CLIFTON HEIGHTS, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 814 Olinda Avenue, has previously been declared a public nuisance;


The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner(s) fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said structure.

Moved by_____to adopt.

FORM APPROVED: ca D. Spoden, Assistant City Attorney

Jessica D. Spoden, Assistant City Automey

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT	CERTIFICATE
COWNIE					
BOESEN					I, DIANE RAUH, City Clerk of said City hereby
COLEMAN					certify that at a meeting of the City Council of said City of Des Moines, held on the above date, among
GATTO					other proceedings the above was adopted.
GRAY					
MANDELBAUM					IN WITNESS WHEREOF, I have hereunto set my hand and affixed my seal the day and year first
WESTERGAARD					above written.
TOTAL					
MOTION CARRIED			AP	PROVED	
					City Clark
				Mayor	City Clerk








> 0f1


40C

Polk County Assessor

[<u>Home</u>][<u>General Query</u>][<u>Legal Query</u>][<u>HomeOwner Query</u>][<u>Book/Page Query</u>][<u>Commercial Query</u>][<u>Res Sales Query</u>] [<u>Comm Sales Query</u>][<u>Help</u>]

District/Parcel	istrict/Parcel GeoParcel		Nbhd	Jurisdiction	Status	
010/00770-000-000	7824-16-205-010	0498	DM26/Z	DES MOINES	ACTIVE	
School District Tax Increment Finance District		Bond/Fire/Sewer/Cemetery				
1/Des Moines						
Street Address			City State	e Zipcode		
814 OLINDA AVE			DES MOINES IA 50315-1545			





Approximate date of photo 03/28/2017

Mailing Address

JERRY KING 10905 NW 106TH AVE GRANGER, IA 50109-9704

Legal Description

LOT 382 1ST PLAT OF CLIFTON HGTS

Ownership	Name	Recorded	Book/Page	RevStamps	
Title Holder #1	KING, JERRY	2016-01-12	15866/832		
Title Holder #2	KING, TERI				

Assessment	Class	Kind	Land	Bldg	AgBd	Total		
Current	Residential	Full	12,200	17,400	0	29,600		
Accomment Poll Notice Estimate Taxes Polk County Treasurer Tax Information Pay Taxes								


Assessment Roll Notice Estimate Taxes Polk County Treasurer Tax Information Pay Taxes

Zoning	Description	SF	Assessor Zoning
R1-60	One Family, Low Density Residential District		Residential
*Condition	Docket no <u>14361</u>		

Source: City of Des Moines Community Development Published: 2012-03-20 Contact: Planning and Urban Design 515 283-4182

Land						
SQUARE FEET	6,600	FRONTAGE	50.0	DEPTH	132.0	
ACRES	0.152	SHAPE	RC/Rectangle	TOPOGRAPHY	N/Normal	

Residence # 1					
OCCUPANCY	SF/Single Family	RESID TYPE	S1/1 Story	BLDG STYLE	BG/Bungalow
YEAR BUILT	1908	# FAMILIES	1	GRADE	5
GRADE ADJUST	+00	CONDITION	PR/Poor	TSFLA	648
MAIN LV AREA	648	BSMT AREA	576	DECK AREA	160
FOUNDATION	B/Brick	EXT WALL TYP	WS/Wood Siding	ROOF TYPE	GB/Gable
ROOF MATERL	A/Asphalt Shingle	HEATING	A/Gas Forced Air	AIR COND	0
BATHROOMS	1	BEDROOMS	1	ROOMS	4



201	
110	0

Seller	ller		Buyer		Sale	Sale Date		le Price	Ins	trument	Book/Page	
LOOSE, THOMAS E		KING, JERRY		2016-01-12			15,000	D/I	Deed	15866/832		
ESTATE OF JAMES A NICHOLS			LOOSE, 7	ГНОМ	AS E	<u>2013</u>	2013-12-13		5,000	D/I	Deed	15068/34
Year	ear Type Status Applica			catio	n	Per	mit	/Pickup l	Desc	cription		
2010	U/Pickup	CP/Comp	lete	2010-	01-13	8	CL,	/SK	ETCH			
2010	P/Permit	NA/No A	dd	2009-	12-29		RD	/FOUNDATION (24 sf)				
Year	Type			Kind	1	La	ind	Bl	dg	AgBd	Total	
2017	Assessment Ro	<u>əll</u>	Residential	1	Full		12,2	200	17,4	00	0	29,600
2015	Assessment Roll		Residential	1	Full		11,	100	28,7	00	0	39,800
2013	Assessment Roll		Residential Full			11,	100	29,1	00	0	40,200	
2011	Assessment Roll		Residential Full			11,1	100	28,8	00	0	39,900	
2010	Assessment Roll		Residential Ful		Full		11,9	900	30,7	00	0	42,600
2009	Assessment Ro	<u>oll</u>	Residential Fu		Full		11,9	900	31,6	00	0	43,500
2007	Assessment Ro	oll	Residential F		Full		11,0	500	34,2	00	0	45,800
2005	Assessment Ro	<u>əll</u>	Residential Full			11,4	400	30,7	00	0	42,100	
2003	Assessment Ro	oll	Residential Full			10,	590	28,2	70	0	38,860	
2001	Assessment Ro	<u>oll</u>	Residential Fu		Full		8,	350	25,8	50	0	34,700
1999	Assessment Ro	oll	Residential Fu		Full		9,4	160	26,6	60	0	36,120
1997	Assessment Ro	oll	Residentia	1	Full		8,4	120	23,7	40	0	32,160
1995	Assessment Ro	Assessment Roll R		1	Full		7,0	550	21,5	80	0	29,230
1993	Assessment Ro	oll	Residentia	1	Full		7,	150	20,1	70	0	27,320
1991	Assessment Ro	oll	Residentia	1	Full		6,:	500	18,3	40	0	24,840
1991	Was Prior Yea	ır	Residentia	1	Full		6,:	500	15,2	80	0	21,780

email this page

Room 195, 111 Court Avenue, Des Moines, IA 50309 Phone 515 286-3140 / Fax 515 286-3386 polkweb@assess.co.polk.ia.us



PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA

DATE OF NOTICE: December 13, 2017

DATE OF INSPECTION:

November 28, 2017

CASE NUMBER:	COD2017-07807
PROPERTY ADDRESS:	814 OLINDA AVE
107	

LEGAL DESCRIPTION:

LOT 382 1ST PLAT OF CLIFTON HGTS

TERI KING Title Holder 1233 ROSEWOOD DR ALTOONA IA 50009

JERRY KING Title Holder 1233 ROSEWOOD DR ALTOONA IA 50009

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-192 and 60-191 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council, sitting as the Board of Health, to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

\\CDMAPPS1\D-VOLUME\APPDATA\Tidemark\prd_41\Forms & Reports\dsmCODPubNo.rp

Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Daniel Adams

(515) 237-1612

Nid Inspector

DATE MAILED: 12/13/2017

MAILED BY: DDA

40C

Areas that need attention: 814 OLINDA AVE

Component:	Plumbing System	Defect:	In poor repair
Requirement:	Plumbing Permit		F - 2, 1 - F
Requirements	That hours a contract of the	Location:	Throughout
Comments:	*		
		8	a da g
	8		
		Defeate	To be an operation
Component:	Electrical System	Defect:	In poor repair
<u>Requirement:</u>	Electrical Permit	location:	Throughout
Comments:		Location	moughout
comments.		11	-
r.			
	2		
Component:	Exterior Walls	Defect:	Absence of paint
Requirement:	Complaince with Int Residential Code	1	Thursday
		Location:	Throughout
Comments:	Entire structure.		÷.
			æ
Component:	Foundation	Defect:	In poor repair
Requirement:	Building Permit		
40 1	_	Location:	Basement
Comments:			
		5	
		Defects	Turning only Installed
Component	Interior Stairway	Defect:	Improperty Installed
<u>Component:</u> Requirement:	Interior Stairway Building Permit	Defect:	Improperly Installed
<u>Component:</u> <u>Requirement:</u>	Interior Stairway Building Permit		Basement
Requirement:			
Requirement:			
<u>Requirement:</u> <u>Comments:</u>	Building Permit	Location:	Basement
Requirement: Comments: Component:	Building Permit Interior Walls /Ceiling		
<u>Requirement:</u> <u>Comments:</u>	Building Permit	Location: Defect:	Basement In poor repair
Requirement: Comments: Component: Requirement:	Building Permit Interior Walls /Ceiling	Location: Defect:	Basement
Requirement: Comments: Component:	Building Permit Interior Walls /Ceiling	Location: Defect:	Basement In poor repair
Requirement: Comments: Component: Requirement:	Building Permit Interior Walls /Ceiling	Location: Defect:	Basement In poor repair
Requirement: Comments: Component: Requirement: Comments:	Building Permit Interior Walls /Ceiling Building Permit	Location: Defect: Location:	Basement In poor repair Throughout
Requirement: Comments: Component: Requirement: Comments: Comments:	Building Permit Interior Walls /Ceiling Building Permit Mechanical System	Location: Defect:	Basement In poor repair
Requirement: Comments: Component: Requirement: Comments:	Building Permit Interior Walls /Ceiling Building Permit	Location: Defect: Location: Defect:	Basement In poor repair Throughout In poor repair
Requirement: Comments: Component: Requirement: Comments: Comments: Comments:	Building Permit Interior Walls /Ceiling Building Permit Mechanical System	Location: Defect: Location: Defect:	Basement In poor repair Throughout
Requirement: Comments: Component: Requirement: Comments: Comments:	Building Permit Interior Walls /Ceiling Building Permit Mechanical System	Location: Defect: Location: Defect:	Basement In poor repair Throughout In poor repair
Requirement: Comments: Component: Requirement: Comments: Comments: Comments:	Building Permit Interior Walls /Ceiling Building Permit Mechanical System	Location: Defect: Location: Defect:	Basement In poor repair Throughout In poor repair
Requirement: Comments: Component: Requirement: Comments: Comments: Comments:	Building Permit Interior Walls /Ceiling Building Permit Mechanical System	Location: Defect: Location: Defect:	Basement In poor repair Throughout In poor repair
Requirement: Comments: Component: Requirement: Comments: Comments: Comments:	Building Permit Interior Walls /Ceiling Building Permit Mechanical System Mechanical Permit Window Glazing/Paint	Location: Defect: Location: Defect:	Basement In poor repair Throughout In poor repair
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Comments:	Building Permit Interior Walls /Ceiling Building Permit Mechanical System Mechanical Permit	Location: Defect: Location: Defect: Location:	Basement In poor repair Throughout In poor repair Throughout In poor repair Throughout In poor repair
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Requirement: Comments: Component: Requirement: Component: Comments:	Building Permit Interior Walls /Ceiling Building Permit Mechanical System Mechanical Permit Window Glazing/Paint	Location: Defect: Location: Defect: Location:	Basement In poor repair Throughout In poor repair Throughout Throughout
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Requirement: Comments: Component: Requirement: Component: Comments:	Building Permit Interior Walls /Ceiling Building Permit Mechanical System Mechanical Permit Window Glazing/Paint	Location: Defect: Location: Defect: Location:	Basement In poor repair Throughout In poor repair Throughout In poor repair Throughout In poor repair
Requirement: Comments: Component: Requirement: Comments: Component: Requirements: Comments: Component: Requirements: Comments: Component: Requirement: Component: Requirement:	Building Permit Interior Walls /Ceiling Building Permit Mechanical System Mechanical Permit Window Glazing/Paint	Location: Defect: Location: Defect: Location:	Basement In poor repair Throughout In poor repair Throughout In poor repair Throughout In poor repair

<u>Component:</u> <u>Requirement:</u> <u>Comments:</u>	Windows/Window Frames Complaince with Int Residential Code	Defect: In poor re		
<u>Component:</u> <u>Requirement:</u> <u>Comments:</u>	- - -	Defect: Location:	р в в	