Roll Call Number		Agenda Item Numbe
Date February 11, 2019		
ABATEMENT OF PU	JBLIC NUISANCE AT 814 Oli	nda Avenue
WHEREAS, the property located a by representatives of the City of Des Moir condition constitutes not only a menace to	nes who determined that the mai	n structure in its present
WHEREAS, the Titleholder, Opt more than thirty days ago to repair or demandate the nuisance.		
NOW THEREFORE, BE IT RESOLVEI MOINES, IOWA:	O BY THE CITY COUNCIL C	OF THE CITY OF DES
The main structure on the real es CLIFTON HEIGHTS, an Official Plat, n Moines, Polk County, Iowa, and locally declared a public nuisance;	now included in and forming a	part of the City of Des
The City Legal Department is here a decree ordering the abatement of the pu nuisance, as ordered, that the matter may be take all necessary action to demolish and	ablic nuisance, and should the or be referred to the Department of	wner(s) fail to abate the
	Moved by	to adopt.
FORM APPROVED: Jessica D. Spoden, Assistant City Attorne	у	

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT
COWNIE				
BOESEN				
COLEMAN				
GATTO				
GRAY	_			
MANDELBAUM				
WESTERGAARD				
TOTAL				
MOTION CARRIED			AP	PROVED

Mayor

CERTIFICATE

I, DIANE RAUH, City Clerk of said City hereby certify that at a meeting of the City Council of said City of Des Moines, held on the above date, among other proceedings the above was adopted.

IN WITNESS WHEREOF, I have hereunto set my hand and affixed my seal the day and year first above written.

City Cler
City Citi



PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA



DATE OF NOTICE: November 16, 2018

DATE OF INSPECTION:

November 16, 2018

CASE NUMBER:

COD2018-08559

PROPERTY ADDRESS:

814 OLINDA AVE

LEGAL DESCRIPTION:

LOT 382 1ST PLAT OF CLIFTON HGTS

OPTIMUM WEALTH ASSET MANAGEMENT LLC Title Holder DAVID R ELKIN - REG. AGENT 315 E 5TH ST SUITE 5 DES MOINES IA 50309

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-192 and 60-191 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Daniel Adams

(515) 237-1612

Nid Inspector

DATE MAILED: 11/16/2018

MAILED BY: TSY



Areas that need attention: 814 OLINDA AVE

1	Areas that need	d attention: 814 OLINDA AVE		
Γ	Component:	Plumbing System	Defect:	In poor repair
ı	Requirement:	Plumbing Permit		
١	<u>kequirement.</u>	Plumbing Permit	Locations	Throughout
1			Location:	Throughout
l	Comments:	a a s		*
1				
ı		@ N	0)	
		(F) (F)		
Ė			Defect:	In poor ropair
١	Component:	Electrical System	Defect:	In poor repair
١	Requirement:	Electrical Permit		8 26 N 1 1
١	7		Location:	Throughout
١	Comments:			
ı				
ı		a second		
L			D-Ek	Al
١		Exterior Walls	Defect:	Absence of paint
١	Requirement:	Complaince with Int Residential Code		
١		*	Location:	Throughout
I	Comments:	8		
١	Commency:	Entire structure.		¥
١		*		
١				
L				
ſ	Component:	Foundation	Defect:	In poor repair
1	Requirement:	Building Permit		
ı	recognition content	building Ferrite	Location:	Basement
1			Locationi	Dascinent
١	Comments:			e
1				9
1		8"		
Į	88	1.40		
I	Components	Interior Stainway	Defect:	Improperly Installed
	Component:	Interior Stairway	Defect:	Improperly Installed
	Component: Requirement:	Interior Stairway Building Permit	18	
	Requirement:		18	Improperly Installed Basement
			18	
	Requirement:		18	
	Requirement:		18	
	Requirement:		18	
	Requirement: Comments:	Building Permit	Location:	Basement
	Requirement: Comments: Component:	Building Permit Interior Walls /Ceiling	18	
	Requirement: Comments:	Building Permit	Location: Defect:	Basement In poor repair
	Requirement: Comments: Component:	Building Permit Interior Walls /Ceiling	Location: Defect:	Basement
	Requirement: Comments: Component:	Building Permit Interior Walls /Ceiling	Location: Defect:	Basement In poor repair
	Requirement: Comments: Component: Requirement:	Building Permit Interior Walls /Ceiling	Location: Defect:	Basement In poor repair
	Requirement: Comments: Component: Requirement:	Building Permit Interior Walls /Ceiling	Location: Defect:	Basement In poor repair
	Requirement: Comments: Component: Requirement:	Building Permit Interior Walls /Ceiling	Location: Defect:	Basement In poor repair
	Requirement: Comments: Component: Requirement: Comments:	Building Permit Interior Walls /Ceiling Building Permit	Location: Defect: Location:	In poor repair Throughout
	Requirement: Comments: Requirement: Requirement: Comments:	Interior Walls /Ceiling Building Permit Mechanical System	Location: Defect:	Basement In poor repair
	Requirement: Comments: Component: Requirement: Comments:	Building Permit Interior Walls /Ceiling Building Permit	Location: Defect: Location:	In poor repair Throughout In poor repair
	Requirement: Comments: Requirement: Requirement: Comments:	Interior Walls /Ceiling Building Permit Mechanical System	Location: Defect: Location:	In poor repair Throughout
	Component: Requirement: Comments: Comments: Comments: Comments: Comments:	Interior Walls /Ceiling Building Permit Mechanical System	Location: Defect: Location:	In poor repair Throughout In poor repair
	Requirement: Comments: Requirement: Requirement: Comments:	Interior Walls /Ceiling Building Permit Mechanical System	Location: Defect: Location:	In poor repair Throughout In poor repair
	Component: Requirement: Comments: Comments: Comments: Comments: Comments:	Interior Walls /Ceiling Building Permit Mechanical System	Location: Defect: Location:	In poor repair Throughout In poor repair
	Component: Requirement: Comments: Comments: Comments: Comments: Comments:	Interior Walls /Ceiling Building Permit Mechanical System	Location: Defect: Location:	In poor repair Throughout In poor repair
	Component: Requirement: Comments: Comments: Comments: Comments: Comments: Comments:	Interior Walls /Ceiling Building Permit Mechanical System Mechanical Permit	Location: Defect: Location: Defect: Location:	In poor repair Throughout In poor repair Throughout
	Component: Requirement: Comments: Comments: Comments: Comments: Comments:	Interior Walls /Ceiling Building Permit Mechanical System Mechanical Permit Window Glazing/Paint	Location: Defect: Location: Defect: Location:	In poor repair Throughout In poor repair
	Component: Requirement: Component: Requirement: Component: Requirement: Component: Requirement:	Interior Walls /Ceiling Building Permit Mechanical System Mechanical Permit Window Glazing/Paint	Location: Defect: Location: Defect: Location:	In poor repair Throughout In poor repair Throughout
	Component: Requirement: Comments: Comments: Comments: Comments: Comments: Comments:	Interior Walls /Ceiling Building Permit Mechanical System Mechanical Permit	Defect: Location: Defect: Location:	In poor repair Throughout In poor repair Throughout In poor repair
	Component: Requirement: Comments: Comments: Comments: Comments: Comments: Requirement: Requirement: Requirement:	Interior Walls /Ceiling Building Permit Mechanical System Mechanical Permit Window Glazing/Paint	Defect: Location: Defect: Location:	In poor repair Throughout In poor repair Throughout
	Component: Requirement: Component: Requirement: Component: Requirement: Component: Requirement:	Interior Walls /Ceiling Building Permit Mechanical System Mechanical Permit Window Glazing/Paint	Defect: Location: Defect: Location:	In poor repair Throughout In poor repair Throughout In poor repair
	Component: Requirement: Comments: Comments: Comments: Comments: Comments: Requirement: Requirement: Requirement:	Interior Walls /Ceiling Building Permit Mechanical System Mechanical Permit Window Glazing/Paint	Defect: Location: Defect: Location:	In poor repair Throughout In poor repair Throughout In poor repair
	Component: Requirement: Comments: Comments: Comments: Comments: Comments: Requirement: Requirement: Requirement:	Interior Walls /Ceiling Building Permit Mechanical System Mechanical Permit Window Glazing/Paint	Defect: Location: Defect: Location:	In poor repair Throughout In poor repair Throughout In poor repair

 Component:
 Windows/Window Frames
 Defect:
 In poor repair


 Requirement:
 Complaince with Int Residential Code
 Location:
 Throughout

Polk County Assessor



[Home] [General Query] [Legal Query] [HomeOwner Query] [Book/Page Query] [Commercial Query] [Res Sales Query] [Comm Sales Query] [Help]

District/Parcel	GeoParcel	Map	Nbhd	Jurisdiction	Status
010/00770-000-000	7824-16-205-010	0498	DM26/Z	DES MOINES	<u>ACTIVE</u>
School District	Tax Increment Finance District	Bond	/Fire/Sewe	er/Cemetery	
1/Des Moines			1		
Street Address			City Stat	e Zipcode	
814 OLINDA	AVE		DES MO	OINES IA 50315-1	1545





Approximate date of photo 03/28/2017

Mailing Address

ZION CAPITAL GROUP LLC 13309 WOODBRIDGE ST STE 204 SHERMAN OAKS, CA 91423

Legal Description

LOT 382 1ST PLAT OF CLIFTON HGTS

Ownership	Name	Recorded	Book/Page	RevStamps
Title Holder #1	OPTIMUM WEALTH ASSET MANAGEMENT LLC	2018-09- 05	17065/480	

Assessment	Class	Kind	Land	Bldg	AgBd	Total
Current	Residential	Full	12,200	17,400	0	29,600
	Estimate Taxes	Polk County Tre	easurer Tax Infor	mation Pay	<u>Taxes</u>	


Zoning	Description	SF	Assessor Zoning	
R1-60	One Family, Low Density Residential District		Residential	

*Condition | Docket_no 14361

Source: City of Des Moines Community Development Published: 2012-03-20 Contact: Planning and Urban Design 515 283-4182

Land					
SQUARE FEET	6,600	FRONTAGE	50.0	DEPTH	132.0
ACRES	0.152	SHAPE	RC/Rectangle	TOPOGRAPHY	N/Normal

Residence # 1					
OCCUPANCY	SF/Single Family	RESID TYPE	S1/1 Story	BLDG STYLE	BG/Bungalow
YEAR BUILT	1908	# FAMILIES	1	GRADE	5
GRADE ADJUST	+00	CONDITION	VP/Very Poor	TSFLA	648
MAIN LV AREA	648	BSMT AREA	576	DECK AREA	160
FOUNDATION	B/Brick	EXT WALL TYP	WS/Wood Siding	ROOF TYPE	GB/Gable
ROOF MATERL	A/Asphalt Shingle	HEATING	A/Gas Forced Air	AIR COND	0
BATHROOMS	1	BEDROOMS	1	ROOMS	4



Seller	Buyer	Sale Date	Sale Price	Instrument	Book/Page
KING, JERRY	OPTIMUM WEALTH ASSET MANAGEMENT LLC	2018- 08-23	16,500	D/Deed	17065/480
LOOSE, THOMAS E	KING, JERRY	<u>2016-</u> <u>01-12</u>	15,000	D/Deed	15866/832
ESTATE OF JAMES A NICHOLS	LOOSE, THOMAS E	<u>2013-</u> <u>12-13</u>	5,000	D/Deed	15068/34

Year	Туре	Status	Application	Permit/Pickup Description
Current	P/Permit	TW/To Work	2018-06-22	AL/Alterations REMODEL Cost Estimate 15979
2010	U/Pickup	CP/Complete	2010-01-13	CL/SKETCH
2010	P/Permit	NA/No Add	2009-12-29	RD/FOUNDATION (24 sf)

Year	<u>Type</u>	Class	Kind	Land	Bldg	AgBd	Total
2017	Assessment Roll	Residential	Full	12,200	17,400	0	29,600

Polk/Des Moines Assessor - 010/00770-000-000 Listing


1/31/2019

	LOWDER MOI	103713300001	10,00110 000	9		2000
Assessment Roll	Residential	Full	11,100	28,700	0	39,800
Assessment Roll	Residential	Full	11,100	29,100	0	40,200
Assessment Roll	Residential	Full	11,100	28,800	0	39,900
Assessment Roll	Residential	Full	11,900	30,700	0	42,600
Assessment Roll	Residential	Full	11,900	31,600	0	43,500
Assessment Roll	Residential	Full	11,600	34,200	0	45,800
Assessment Roll	Residential	Full	11,400	30,700	0	42,100
Assessment Roll	Residential	Full	10,590	28,270	0	38,860
Assessment Roll	Residential	Full	8,850	25,850	0	34,700
Assessment Roll	Residential	Full	9,460	26,660	0	36,120
Assessment Roll	Residential	Full	8,420	23,740	0	32,160
Assessment Roll	Residential	Full	7,650	21,580	0	29,230
Assessment Roll	Residential	Full	7,150	20,170	0	27,320
Assessment Roll	Residential	Full	6,500	18,340	0	24,840
Was Prior Year	Residential	Full	6,500	15,280	0	21,780
	Assessment Roll	Assessment Roll	Assessment RollResidentialFullAssessment RollResidentialFull	Assessment RollResidentialFull11,100Assessment RollResidentialFull11,100Assessment RollResidentialFull11,100Assessment RollResidentialFull11,900Assessment RollResidentialFull11,900Assessment RollResidentialFull11,600Assessment RollResidentialFull11,400Assessment RollResidentialFull10,590Assessment RollResidentialFull8,850Assessment RollResidentialFull9,460Assessment RollResidentialFull8,420Assessment RollResidentialFull7,650Assessment RollResidentialFull7,150Assessment RollResidentialFull6,500	Assessment Roll Residential Full 11,100 29,100 Assessment Roll Residential Full 11,100 28,800 Assessment Roll Residential Full 11,900 30,700 Assessment Roll Residential Full 11,900 31,600 Assessment Roll Residential Full 11,600 34,200 Assessment Roll Residential Full 11,400 30,700 Assessment Roll Residential Full 10,590 28,270 Assessment Roll Residential Full 9,460 26,660 Assessment Roll Residential Full 8,420 23,740 Assessment Roll Residential Full 7,650 21,580 Assessment Roll Residential Full 7,150 20,170 Assessment Roll Residential Full 6,500 18,340	Assessment Roll Residential Full 11,100 28,700 0 Assessment Roll Residential Full 11,100 29,100 0 Assessment Roll Residential Full 11,100 28,800 0 Assessment Roll Residential Full 11,900 30,700 0 Assessment Roll Residential Full 11,900 31,600 0 Assessment Roll Residential Full 11,400 34,200 0 Assessment Roll Residential Full 11,400 30,700 0 Assessment Roll Residential Full 10,590 28,270 0 Assessment Roll Residential Full 9,460 26,660 0 Assessment Roll Residential Full 9,460 26,660 0 Assessment Roll Residential Full 7,650 21,580 0 Assessment Roll Residential Full 7,150 20,170 0

email this page

Room 195, 111 Court Avenue, Des Moines, IA 50309 Phone 515 286-3140 / Fax 515 286-3386 polkweb@assess.co.polk,ia.us

814 Olinda Ave



814 Olinda Ave 02/01/2019