

Agenda Item Number

Date August 5, 2019

ABATEMENT OF PUBLIC NUISANCE AT 2021 E 27th STREET

WHEREAS, the property located at 2021 E 27th Street, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure in its present condition constitutes not only a menace to health and safety but is also a public nuisance; and

WHEREAS, the Titleholders, Rodney Green and Cheryl Green, were notified more than thirty days ago to repair or demolish the main structure and as of this date have failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA:

The main structure on the real estate legally described as Lot 52 in CASS GRAND VIEW PLACE, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 2021 E 27th Street, has previously been declared a public nuisance;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner(s) fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said structure.

> Moved by to adopt.

FORM APPROVED . A. st

	Luke	DeSmet,	Assistant	City	Attorney
--	------	---------	-----------	------	----------

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT	CERTIFICATE
COWNIE					SERTINOATE
BOESEN					I, DIANE RAUH, City Clerk of said City hereby
COLEMAN					certify that at a meeting of the City Council of said
GATTO					City of Des Moines, held on the above date, among other proceedings the above was adopted.
GRAY	_				sener proceedings the above was adopted.
MANDELBAUM					IN WITNESS WHEREOF, I have hereunto set my
WESTERGAARD					hand and affixed my seal the day and year first above written.
TOTAL					above witten.
MOTION CARRIED			API	ROVED	
			1	Mayor	City Clerk

Polk County Assessor 060/00836-000-000

Polk County Assessor

111 Court Avenue #195 Des Moines, IA 50309-0904 (515) 286-3014 Fax (515) 286-3386 polkweb@assess.co.polk.ia.us

		Lo	cation				
Address	2021 E 27TH ST						
City	DES MOINES	Zip		50317	Jurisdiction	Des Moines	
District/Parcel	060/00836-000-000	Geoparcel	7923-31-27	7-002	Status	Active	
School	Des Moines	Nbhd/Pocket	DN	м11/Е	Tax Authority Group	DEM-C-DEM- 77131	
Submarket	Northeast Des Moines	Appraiser	Victor Scaglio 28	ne 515- 36-3898			
		Map and Curr	rent Photos -	1 Record	d		
Cliel	k on parcel to get a 1	new listing					
Photo Processed on 2012-01-09 a 2108 THOMPSON AVE 2102 2011 2018 2017 2018 2017 2018 2017 2018 2017 2018 2017 2018 2017 2018 2017 2018 2017 2019 2018 Bigger Map Polk County GIS Google Map Pictometry.							
		Histo	orical Photos	e to de la constante			
		Ownershi	p - 2 Records	1			
Ownership Num		Nam			corded	Book/Page	
Title Holder	1	GREEN, RODN			012-08-06	14381/714	
Title Holder	2	GREEN, CHER	a subscription of the subs	2012-08-06 <u>14381/714</u>			
LOT 52 CASS	Le S GRAND VIEW PL	gal Description	RO 274	RODNEY GREEN 2740 THOMPSON AVE DES MOINES, IA 50317-6174			
		Curre	nt Values				

		Curront fur	die 5			
Туре	Class	Kind La			Bldg	Total
2019 Value	Residential	Full	\$24,800	\$58,200		\$83,000
	Assessment Ro	<u>Il Notice</u> <u>Market</u> Zoning - 1 Re		<u>eport</u>		an a
Zoning D		scription		SF	Assess	or Zoning
R1-60	One Family, Low Density	Residential Dist	rict		Residential	


web.assess.co.polk.ia.us/cgi-bin/web/tt/infoqry.cgi?tt=card/card&dp=06000836000000&

Polk County Assessor 060/00836-000-000

City of Des Moines Community Development Planning and Urban Design 515 283-4182 (2012-03-20)

		La	nd						
Square Fee	et 13,50	13,500 Acres		13,500 Acres 0.310		Frontage	90.0		
Dept	h 150.	0 Topography	y Normal	Shape	Rectangle				
Vacanc	y N	o Unbuildable	e No						
		Residence	es - 1 Record						
Residence #1									
Occupancy	Single Family	Residence Type	1 Story Finished Attic	Building Style	Conventional				
Year Built	1930	Number Families	1	Grade	4-05				
Condition	Below Normal	Total Square Foot Living Area	1032	Main Living Area	795				
Attic Finished Area	237	Basement Area	676	Enclosed Porch Area	168				
Foundation	Concrete Block	Exterior Wall Type	Metal Siding	Roof Type	Gable				
Roof Material	Asphalt Shingle	Heating	Gas Forced Air	Air Conditioning	100				
Number Bathrooms	1	Bedrooms	2	Rooms	5				

48D



Sales - 5 Records

Seller	Buyer	Sale Date	Sale Price	Instrument	Book/Page
EH POOLED 112 LP	GREEN, RODNEY	<u>2012-08-03</u>	\$26,350	Deed	<u>14381/714</u>
DEUTSCHE BANK NATIONAL TRUST COMPANY	EH POOLED 112 LP	<u>2012-04-23</u>	\$19,000	Deed	<u>14265/977</u>
PLYM, SCOTT D	BOOTHROYD, RONALD	<u>2004-05-17</u>	\$85,000	Deed	<u>10594/956</u>
FURMAN, STEPHEN J	PLYM, SCOTT	2000-01-06	\$73,000	Deed	<u>8410/156</u>
ROE, LARRY	FURMAN, STEPHEN J	<u>1992-05-18</u>	\$44,000	Deed	<u>6562/150</u>

web.assess.co.polk.ia.us/cgi-bin/web/tt/infoqry.cgi?tt=card/card&dp=06000836000000&

Recent Ownership Transfers

Grant	tor		Grantee	Instrument Date	1	ecording ate	Instrument Type	Book/Pg
EH PO	DOLED 112	LP	GREEN, RODNEY GREEN, CHERYL	2012-08-01	20 06	12-08-	Special Warranty Deed	<u>14381/714</u>
NATIO COMI (Trust MORO STAN CAPI TRUS OCW. SERV		ST 	EH POOLED 112 LP	2012-04-23	20 10	12-05-	Quit Claim Deed	<u>14265/977</u>
Permits - 2 Records								
Year	Туре	Permit Status		Applicatio	Application		Description	
2018	Permit	No A	.dd	2017-07-25		addition/fence		
2013	Pickup	No A	.dd	2012-07-13		review val	ue/check conditio	on

Historical Values

Yr	Туре	Class	Kind	Land	Bldg	Total
2019	Assessment Roll	Residential	Full	\$24,800	\$58,200	\$83,000
2017	Assessment Roll	Residential	Full	\$23,000	\$55,500	\$78,500
2015	Assessment Roll	Residential	Full	\$21,300	\$53,000	\$74,300
2013	Assessment Roll	Residential	Full	\$20,400	\$52,100	\$72,500
2011	Assessment Roll	Residential	Full	\$20,400	\$67,300	\$87,700
2009	Assessment Roll	Residential	Full	\$21,100	\$68,900	\$90,000
2007	Assessment Roll	Residential	Full	\$20,800	\$68,100	\$88,900
2005	Assessment Roll	Residential	Full	\$22,300	\$62,000	\$84,300
2003	Assessment Roll	Residential	Full	\$20,800	\$57,950	\$78,750
2001	Assessment Roll	Residential	Full	\$18,790	\$50,670	\$69,460
1999	Assessment Roll	Residential	Full	\$10,580	\$46,060	\$56,640
1997	Assessment Roll	Residential	Full	\$9,520	\$41,460	\$50,980
1995	Assessment Roll	Residential	Full	\$8,810	\$38,380	\$47,190
1993	Assessment Roll	Residential	Full	\$7,760	\$33,800	\$41,560
1991	Assessment Roll	Residential	Full	\$7,760	\$29,210	\$36,970
1991	Was Prior Year	Residential	Full	\$7,760	\$25,550	\$33,310

This template was last modified on Sat Mar 4 12:31:48 2017 .

CITY OF DES MOINES

PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA

DATE OF NOTICE: April 12, 2019

DATE OF INSPECTION:

April 05, 2019

CASE	NUMBER:	COD2019-01436

PROPERTY ADDRESS: 2021 E 27TH ST

LEGAL DESCRIPTION:

LOT 52 CASS GRAND VIEW PLACE

RODNEY GREEN Title Holder 2740 THOMPSON AVE DES MOINES IA 50317-6174

CHERYL GREEN Title Holder 2740 THOMPSON AVE DES MOINES IA 50317-6174

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-192 and 60-191 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES. Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Casey Doran

(515) 283-4183

Nid Inspector

DATE MAILED: 4/12/2019

MAILED BY: JDH

Aleas that hee			
Component:	Electrical System	Defect:	Improperly Installed
Requirement:	Electrical Permit	51 E	54
	5 ° 8	Location:	Main Structure Throughout
			20
Comments:		*	e
	2 B		
	12		81
		23	
<u>.</u>	El 1- ista / Deseran	Defect:	Fire damaged
Component:	Floor Joists/Beams	Delect	rite uainageu
Requirement:	Building Permit		~
	Dunung Forme	Location:	Main Structure Throughout
		Location	Main Structure Throughout
Comments:	÷		
Gomman			a (d. 191
	(4) (2) (2) (2) (2) (2) (2) (2) (2) (2) (2	726	
		¥	
Component:	Ductwork	Defect:	Smoke Damage
Sector Construction			1000000000 FC - 12
<u>Requirement:</u>	Unknown	8 82	
		Location:	Main Structure Throughout
			una na una en altre a tender esperando por entre transfere de la tradición de la tendera
Comments:	Clean dust work throughout.		
	Gean dust work throughout.	12	
100			92
R			2
			*
Commence	Furnaça	Defect:	Smoke Damage
Component:	Furnace	Derecti	Smoke Damage
Requirement:	Unknown		
		Location:	Basement
	5	Location	basement
Comments:		ion	
5.	Clean and have inspected for proper funct	1011	7
	2 t _a		· ·
2			5
			-
	T I I M H /O-Illan	Defect	Emoko Damago
Component:	Interior Walls /Ceiling	Defect:	Smoke Damage
	Interior Walls /Ceiling	Defect:	Smoke Damage
<u>Component:</u> <u>Requirement:</u>	Interior Walls /Ceiling		
	Interior Walls /Ceiling		Smoke Damage Main Structure Throughout
Requirement:	Interior Walls /Ceiling		
	Interior Walls /Ceiling		
Requirement:	Interior Walls /Ceiling		
Requirement:	Interior Walls /Ceiling		
Requirement:	Interior Walls /Ceiling		
Requirement:		Location:	Main Structure Throughout
Requirement:	Interior Walls /Ceiling Water Heater		
Requirement: Comments: Component:	Water Heater	Location:	Main Structure Throughout
Requirement: Comments:		Location: Defect:	Main Structure Throughout Improperly Installed
Requirement: Comments: Component:	Water Heater	Location: Defect:	Main Structure Throughout
Requirement: Comments: Component: Requirement:	Water Heater Plumbing Permit	Location: Defect: Location:	Main Structure Throughout Improperly Installed Basement
Requirement: Comments: Component:	Water Heater Plumbing Permit	Location: Defect: Location:	Main Structure Throughout Improperly Installed Basement
Requirement: Comments: Component: Requirement:	Water Heater	Location: Defect: Location:	Main Structure Throughout Improperly Installed Basement
Requirement: Comments: Component: Requirement:	Water Heater Plumbing Permit	Location: Defect: Location:	Main Structure Throughout Improperly Installed Basement
Requirement: Comments: Component: Requirement:	Water Heater Plumbing Permit	Location: Defect: Location:	Main Structure Throughout Improperly Installed Basement
Requirement: Comments: Component: Requirement:	Water Heater Plumbing Permit	Location: Defect: Location: installed pr	Main Structure Throughout Improperly Installed Basement operly Permit required.
Requirement: Comments: Component: Requirement: Comments:	Water Heater Plumbing Permit Water heater is a safety hazzard. Must be	Location: Defect: Location:	Main Structure Throughout Improperly Installed Basement operly Permit required.
Requirement: Comments: Component: Requirement: Comments:	Water Heater Plumbing Permit Water heater is a safety hazzard. Must be Wiring	Location: Defect: Location: installed pr	Main Structure Throughout Improperly Installed Basement
Requirement: Comments: Component: Requirement: Comments:	Water Heater Plumbing Permit Water heater is a safety hazzard. Must be	Location: Defect: Location: installed pr Defect:	Main Structure Throughout Improperly Installed Basement roperly Permit required. Improperly Installed
Requirement: Comments: Component: Requirement: Comments:	Water Heater Plumbing Permit Water heater is a safety hazzard. Must be Wiring	Location: Defect: Location: installed pr Defect:	Main Structure Throughout Improperly Installed Basement operly Permit required.
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments:	Water Heater Plumbing Permit Water heater is a safety hazzard. Must be Wiring	Location: Defect: Location: installed pr Defect:	Main Structure Throughout Improperly Installed Basement roperly Permit required. Improperly Installed
Requirement: Comments: Component: Requirement: Comments:	Water Heater Plumbing Permit Water heater is a safety hazzard. Must be Wiring	Location: Defect: Location: installed pr Defect:	Main Structure Throughout Improperly Installed Basement roperly Permit required. Improperly Installed
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments:	Water Heater Plumbing Permit Water heater is a safety hazzard. Must be Wiring	Location: Defect: Location: installed pr Defect:	Main Structure Throughout Improperly Installed Basement roperly Permit required. Improperly Installed
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments:	Water Heater Plumbing Permit Water heater is a safety hazzard. Must be Wiring	Location: Defect: Location: installed pr Defect:	Main Structure Throughout Improperly Installed Basement roperly Permit required. Improperly Installed
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments:	Water Heater Plumbing Permit Water heater is a safety hazzard. Must be Wiring	Location: Defect: Location: installed pr Defect:	Main Structure Throughout Improperly Installed Basement roperly Permit required. Improperly Installed
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments:	Water Heater Plumbing Permit Water heater is a safety hazzard. Must be Wiring	Location: Defect: Location: installed pr Defect:	Main Structure Throughout Improperly Installed Basement roperly Permit required. Improperly Installed
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Comments:	Water Heater Plumbing Permit Water heater is a safety hazzard. Must be Wiring Compliance with National Electrical Code	Location: Defect: Location: installed pr Defect: Location:	Main Structure Throughout Improperly Installed Basement roperly Permit required. Improperly Installed Main Structure Throughout
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments:	Water Heater Plumbing Permit Water heater is a safety hazzard. Must be Wiring	Location: Defect: Location: installed pr Defect:	Main Structure Throughout Improperly Installed Basement roperly Permit required. Improperly Installed
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Component: Component: Component: Component: Component: Component:	Water Heater Plumbing Permit Water heater is a safety hazzard. Must be Wiring Compliance with National Electrical Code	Location: Defect: Location: installed pr Defect: Location:	Main Structure Throughout Improperly Installed Basement roperly Permit required. Improperly Installed Main Structure Throughout
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Comments:	Water Heater Plumbing Permit Water heater is a safety hazzard. Must be Wiring Compliance with National Electrical Code	Location: Defect: Location: installed pr Defect: Location: Defect:	Main Structure Throughout Improperly Installed Basement roperly Permit required. Improperly Installed Main Structure Throughout See Comments
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Component: Component: Component: Component: Component: Component:	Water Heater Plumbing Permit Water heater is a safety hazzard. Must be Wiring Compliance with National Electrical Code	Location: Defect: Location: installed pr Defect: Location: Defect:	Main Structure Throughout Improperly Installed Basement roperly Permit required. Improperly Installed Main Structure Throughout
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Water Heater Plumbing Permit Water heater is a safety hazzard. Must be Wiring Compliance with National Electrical Code	Location: Defect: Location: installed pr Defect: Location: Defect: Location:	Main Structure Throughout Improperly Installed Basement roperly Permit required. Improperly Installed Main Structure Throughout See Comments Garage Throughout
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Component: Component: Component: Component: Component: Component:	Water Heater Plumbing Permit Water heater is a safety hazzard. Must be Wiring Compliance with National Electrical Code Accessory Buildings Structure absent of one required The garage in its current condition does n	Location: Defect: Location: installed pr Defect: Location: Defect: Location: ot constitut	Main Structure Throughout Improperly Installed Basement roperly Permit required. Improperly Installed Main Structure Throughout See Comments Garage Throughout re a public nuisance. However,
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Water Heater Plumbing Permit Water heater is a safety hazzard. Must be Wiring Compliance with National Electrical Code Accessory Buildings Structure absent of one required The garage in its current condition does n	Location: Defect: Location: installed pr Defect: Location: Defect: Location: ot constitut	Main Structure Throughout Improperly Installed Basement roperly Permit required. Improperly Installed Main Structure Throughout See Comments Garage Throughout re a public nuisance. However,
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Water Heater Plumbing Permit Water heater is a safety hazzard. Must be Wiring Compliance with National Electrical Code Accessory Buildings Structure absent of one required The garage in its current condition does n if the primary structure is demolished and	Location: Defect: Location: installed pr Defect: Location: Defect: Location: ot constitut no primary	Main Structure Throughout Improperly Installed Basement roperly Permit required. Improperly Installed Main Structure Throughout See Comments Garage Throughout re a public nuisance. However, structure is immediately built
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Water Heater Plumbing Permit Water heater is a safety hazzard. Must be Wiring Compliance with National Electrical Code Accessory Buildings Structure absent of one required The garage in its current condition does n if the primary structure is demolished and on the property, the garage must be dem	Location: Defect: Location: installed pr Defect: Location: Defect: Location: ot constitut no primary olished as v	Main Structure Throughout Improperly Installed Basement operly Permit required. Improperly Installed Main Structure Throughout See Comments Garage Throughout te a public nuisance. However, structure is immediately built well because it is an accessory
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Water Heater Plumbing Permit Water heater is a safety hazzard. Must be Wiring Compliance with National Electrical Code Accessory Buildings Structure absent of one required The garage in its current condition does n	Location: Defect: Location: installed pr Defect: Location: Defect: Location: ot constitut no primary olished as v	Main Structure Throughout Improperly Installed Basement operly Permit required. Improperly Installed Main Structure Throughout See Comments Garage Throughout te a public nuisance. However, structure is immediately built well because it is an accessory

Areas that need attention: 2021 E 27TH ST

1	Component:	Plumbing System	Defect:	Improperly Installed	÷	
	Requirement:	Compliance with Uniform Plumbing Code	Location:	Throughout		ć
8	Comments:	Main stack.				

48D

