*	Roll	Call	Number

Agenda	Item	Number
J	20	IA
	0	114

Date	August 19, 2019	

ABATEMENT OF PUBLIC NUISANCE AT 1515 E 17th STREET

WHEREAS, the property located at 1515 E 17th Street, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure in its present condition constitutes not only a menace to health and safety but is also a public nuisance; and

WHEREAS, the Titleholder, Novella Hayes, and Mortgage Holder, Suntrust Mortgage Inc., were notified more than thirty days ago to repair or demolish the main structure and as of this date have failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA:

The main structure on the real estate legally described as 7 feet East of and adjacent and all Lot 6 EAST CAPITAL PARK, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 1515 E 17th Street, has previously been declared a public nuisance;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner(s) fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said structure.

Moved by ______to adopt.

FORM APPROVED:

Luke DeSmet, Assistant City Attorney

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT
COWNIE				
BOESEN				
COLEMAN				
GATTO				
GRAY				
MANDELBAUM				10
WESTERGAARD				
TOTAL				
MOTION CARRIED			AP	PROVED

CERTIFICATE

I, DIANE RAUH, City Clerk of said City hereby certify that at a meeting of the City Council of said City of Des Moines, held on the above date, among other proceedings the above was adopted.

IN WITNESS WHEREOF, I have hereunto set my hand and affixed my seal the day and year first above written.

	City Cler
or	city citi

34A

Polk County Assessor


111 Court Avenue #195 Des Moines, IA 50309-0904 (515) 286-3014 Fax (515) 286-3386 polkweb@assess.co.polk.ia.us

Location					
Address	1515 E 17TH ST				
City	DES MOINES	Zip	50316	Jurisdiction	Des Moines
District/Parcel	110/02110-000-000	Geoparcel	7924-36-329-006	Status	<u>Active</u>
School	Des Moines	Nbhd/Pocket	DM08/Z	Tax Authority Group	DEM-C-DEM- 77131
Submarket	Northeast Des Moines	Appraiser	Andrew Rand 515- 286-3368		and part of the second at the

Map and Current Photos - 1 Record

1524	Ŀ	1527	1530
1520		1523	1528
1516	m	1519	
1512	E 17TH ST	1515	1464
1508	7 L	1511	
1504:		1507	1458
1500		1603	1450

Google Map Pictometry



Historical Photos

Ownership - 1 Record					
Ownership	Num	Name	Recorded	Book/Page	
Title Holder	1	HAYES, NOVELLA	2003-08-01	10034/953	

Legal Description and Mailing Address

7F E OF & ADJ & ALL LT 6 EAST CAPITAL PARK

NOVELLA HAYES 1515 E 17TH ST DES MOINES, IA 50316-4047

Current Values

Туре	Class	Kind	Land	Bldg	Total
2019 Value	Residential	Full	\$10,400	\$75,000	\$85,400


Assessment Roll Notice Market Adjusted Cost Report

Auditor Adjustments to Value

Category	Name	Information
2018 Homestead Credit	HAYES, NOVELLA	Application <u>#163201</u>

Zoning - 1 Record

Zoning			Description		SF	Asses	sor Zoning
R1-60	One	Family, Lov	w Density Residential Dist	rict			sidential
City of Des	Moines	Community	Development Planning	and Urban Des	ign 515 2	83-4182	(2012-03-20)
			Land				
Square	Feet	7,000	Acres	0.161	Fro	ntage	50.0
D	epth	140.0	Topography	Normal		hape	Rectangle
Vac	ancy	No	Unbuildable	No			
			Residences - 1	Record			The state of the s
			Residence	#1		t the three transfers	
Occupanc	y	Single Family	Residence Type	1 Story	F	Building Style	Ranch
Year Bui	lt	1971	Number Families	1		Grade	4+00
Conditio	n	Above Normal	Total Square Foot Living Area	899	Main	Living Area	899
Basemer Are		899	Foundation	Concrete Block	1	Exterior all Type	Hardboard
Roof Typ	e	Gable	Roof Material	Asphalt Shingle]	Heating	Gas Forced Air
Ai Conditionin		0	Number Bathrooms	1	Be	drooms	3
Room	S	5		<u> </u>	1		



TTTO	W Y W
Historical	No Inno
Historical	values

Yr	Type	Class	Kind	Land	Bldg	Total
2019	Assessment Roll	Residential	Full	\$10,400	\$75,000	\$85,400
2017	Assessment Roll	Residential	Full	\$9,500	\$70,400	\$79,900
2015	Assessment Roll	Residential	Full	\$8,600	\$65,200	\$73,800
2013	Assessment Roll	Residential	Full	\$7,700	\$59,400	\$67,100
2011	Assessment Roll	Residential	Full	\$8,800	\$67,600	\$76,400
2009	Assessment Roll	Residential	Full	\$9,500	\$72,500	\$82,000
2007	Assessment Roll	Residential	Full	\$9,500	\$72,500	\$82,000
2005	Assessment Roll	Residential	Full	\$9,200	\$59,100	\$68,300
2003	Assessment Roll	Residential	Full	\$7,930	\$50,970	\$58,900
2001	Assessment Roll	Residential	Full	\$7,260	\$42,030	\$49,290
1999	Assessment Roll	Residential	Full	\$7,260	\$31,730	\$38,990
1997	Assessment Roll	Residential	Full	\$6,580	\$28,740	\$35,320
1995	Assessment Roll	Residential	Full	\$5,910	\$25,820	\$31,730
1993	Assessment Roll	Residential	Full	\$5,380	\$23,500	\$28,880
1989	Assessment Roll	Residential	Full	\$5,380	\$22,520	\$27,900

This template was last modified on Sat Mar 4 12:31:48 2017 .



PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA

DATE OF NOTICE: May 28, 2019

DATE OF INSPECTION:

March 27, 2019

CASE NUMBER:

COD2019-01241

PROPERTY ADDRESS:

1515 E 17TH ST

LEGAL DESCRIPTION:

7F E OF & ADJ & ALL LT 6 EAST CAPITAL PARK

NOVELLA HAYES Title Holder 100 SW WATER ST #303 DES MOINES IA 50309

SUNTRUST MORTGAGE INC Mortgage Holder CORPORATION SERV CO., R.A. 100 SHOCKOE SLIP - 2ND FLR RICHMOND VA 23219

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-192 and 60-191 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday

through Friday.

Steve Landwehr

(515) 283-4008

Nid Inspector

DATE MAILED: 5/28/2019

MAILED BY: JDH

Areas that need attention: 1515 E 17TH ST

Windows/Window Frames Component: Defect: Fire damaged Requirement: **Building Permit Location:** Main Structure Throughout Comments: Component: Flame/Smoke Spread Ductwork Defect: Requirement: Complaince with Int Residential Code **Location:** Main Structure Throughout Comments: Component: Electrical Service Defect: Fire damaged Requirement: **Electrical Permit Location:** Main Structure Throughout Comments: Component: Plumbing System Defect: Smoke Damage Requirement: Plumbing Permit **Location:** Main Structure Throughout Comments: **Component:** Mechanical System Defect: Water Damage Requirement: Mechanical Permit **Location:** Main Structure Throughout Comments: Component: **Electrical Lighting Fixtures** Defect: Fire damaged Requirement: **Electrical Permit Location:** Main Structure Throughout **Comments:** Electrical Receptacles Component: Defect: Fire damaged Requirement: **Electrical Permit Location:** Main Structure Throughout **Comments:** Electrical Other Fixtures Component: Defect: Fire damaged Requirement: **Electrical Permit Location:** Main Structure Throughout Comments:

25	e (9		
١٢.	Component:	Wiring	Defect:	Fire damaged
	Requirement:	Electrical Permit	12-14-2-10-10-10-10-10-10-10-10-10-10-10-10-10-	, and annual 3
			Location:	Main Structure Throughout
	Comments:	ž z		riam ou decare imoughout
				si l
	ş x			
		a *		Toes
	Component:	Exterior Deere/James	Defeat	
- 32		Exterior Doors/Jams	Defect:	Flame/Smoke Spread
1	Requirement:	Complaince with Int Residential Code		49
	<u>~</u>	v	<u>Location:</u>	Main Structure Throughout
1 5	Comments:			
	~ ·			te de
	=	p		
	3			
	Component:	Exterior Walls	Defect:	Fire damaged
1	Requirement:	Complaince with Int Residential Code		_
		Control of the contro	Location:	Main Structure Throughout
10	Comments:			a ou decare Throughout
'		*		¥
F	Component:	Flooring	Defect:	Fire damaged
- 63	Requirement:	Complaince with Int Residential Code	<u>Defect.</u>	rife damaged
1 '	Kedunement.	Complaince with the Residential Code	I	M
١.	Camananta.	g	Location:	Main Structure Throughout
1 3	Comments:	•		w.
10				
				š.
L				Ŷ ·
_	Component:	Exterior-Stairs	Defect:	Deteriorated -
_	Component: Requirement:	Exterior Stairs Complaince with Int Residential Code	\$\frac{1}{2}(The State of State of the State of Stat
1	Requirement:		Defect: Location:	The State of State And State of State o
1			\$\frac{1}{2}(The State of State And State of State o
1	Requirement:		\$\frac{1}{2}(The State of State And State of State o
1	Requirement:		\$\frac{1}{2}(The State of State And State of State o
1	Requirement:		\$\frac{1}{2}(The State of State And State of State o
2	Requirement:		\$\frac{1}{2}(Entry
9	Requirement: Comments:	Complaince with Int Residential Code Sub Floor	Location:	The State of State And State of State o
9	Requirement: Comments: Component:	Complaince with Int Residential Code	Location:	Entry Fire damaged
	Requirement: Comments: Component:	Complaince with Int Residential Code Sub Floor	Location:	Entry
	Requirement: Comments: Component: Requirement:	Complaince with Int Residential Code Sub Floor	Location:	Entry Fire damaged
	Requirement: Comments: Component: Requirement:	Complaince with Int Residential Code Sub Floor	Location:	Entry Fire damaged
	Requirement: Comments: Component: Requirement:	Complaince with Int Residential Code Sub Floor	Location:	Entry Fire damaged
	Requirement: Comments: Component: Requirement: Comments:	Complaince with Int Residential Code Sub Floor Building Permit	Location: Defect: Location:	Fire damaged Main Structure Throughout
	Component: Comments: Component: Comments: Comments:	Complaince with Int Residential Code Sub Floor Building Permit Soffit/Facia/Trim	Location: Defect: Location:	Entry Fire damaged
	Requirement: Comments: Component: Requirement: Comments:	Complaince with Int Residential Code Sub Floor Building Permit	Defect: Location:	Fire damaged Main Structure Throughout Fire damaged
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Component: Comments: Component: Comments: Comments: Comments: Component: Component:	Complaince with Int Residential Code Sub Floor Building Permit Soffit/Facia/Trim	Defect: Location:	Fire damaged Main Structure Throughout
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Component: Comments: Component: Comments: Comments:	Complaince with Int Residential Code Sub Floor Building Permit Soffit/Facia/Trim	Defect: Location:	Fire damaged Main Structure Throughout Fire damaged
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Component: Comments: Component: Comments: Comments: Comments: Component: Component:	Complaince with Int Residential Code Sub Floor Building Permit Soffit/Facia/Trim	Defect: Location:	Fire damaged Main Structure Throughout Fire damaged
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Component: Comments: Component: Comments: Comments: Comments: Component: Component:	Complaince with Int Residential Code Sub Floor Building Permit Soffit/Facia/Trim	Defect: Location:	Fire damaged Main Structure Throughout Fire damaged
2 1 2 2 2 2 2	Component: Component: Comments: Comments: Comments: Comments: Comments: Comments:	Sub Floor Building Permit Soffit/Facia/Trim Complaince with Int Residential Code	Defect: Location: Defect: Location:	Fire damaged Main Structure Throughout Fire damaged Main Structure Throughout
2 - <u>1</u>	Component: Component: Component: Component: Component: Component: Component: Component: Component:	Sub Floor Building Permit Soffit/Facia/Trim Complaince with Int Residential Code Floor Joists/Beams	Defect: Location: Defect: Location:	Fire damaged Main Structure Throughout Fire damaged
2 - <u>1</u>	Component: Component: Comments: Comments: Comments: Comments: Comments: Comments:	Sub Floor Building Permit Soffit/Facia/Trim Complaince with Int Residential Code	Location: Defect: Location: Defect: Location:	Fire damaged Main Structure Throughout Fire damaged Main Structure Throughout Fire damaged
2 1 2 2 2 2 2 2	Component: Comments: Component: Comments: Comments: Comments: Comments: Comments: Comments: Comments: Comments:	Sub Floor Building Permit Soffit/Facia/Trim Complaince with Int Residential Code Floor Joists/Beams	Location: Defect: Location: Defect: Location:	Fire damaged Main Structure Throughout Fire damaged Main Structure Throughout
2 1 2 2 2 2 2 2	Component: Component: Component: Component: Component: Component: Component: Component: Component:	Sub Floor Building Permit Soffit/Facia/Trim Complaince with Int Residential Code Floor Joists/Beams	Location: Defect: Location: Defect: Location:	Fire damaged Main Structure Throughout Fire damaged Main Structure Throughout Fire damaged
2 1 2 2 2 2 2 2	Component: Comments: Component: Comments: Comments: Comments: Comments: Comments: Comments: Comments: Comments:	Sub Floor Building Permit Soffit/Facia/Trim Complaince with Int Residential Code Floor Joists/Beams	Location: Defect: Location: Defect: Location:	Fire damaged Main Structure Throughout Fire damaged Main Structure Throughout Fire damaged
2 1 2 2 2 2 2 2	Component: Comments: Component: Comments: Comments: Comments: Comments: Comments: Comments: Comments: Comments:	Sub Floor Building Permit Soffit/Facia/Trim Complaince with Int Residential Code Floor Joists/Beams	Location: Defect: Location: Defect: Location:	Fire damaged Main Structure Throughout Fire damaged Main Structure Throughout Fire damaged

top

1515 E 17 H

