

Date September 23, 2019

## ABATEMENT OF PUBLIC NUISANCES AT 1304 E 37th STREET

WHEREAS, the property located at 1304 E 37th Street, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure and garage structure in their present condition constitutes not only a menace to health and safety but are also public nuisances; and

WHEREAS, the Titleholder, Richard A. Reynolds, was notified more than thirty days ago to repair or demolish the main structure and garage structure and as of this date has failed to abate the nuisances.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA:

The main structure and garage structure on the real estate legally described as Lot 255 in GRAYS WOODS, an Official Plat, now included in and forming a part of the City of Des Moines. Polk County, Iowa, and locally known as 1304 E 37<sup>th</sup> Street, have previously been declared public nuisances;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisances, and should the owner(s) fail to abate the nuisances, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said structures.

> Moved by to adopt.

FORM APPROVED

Luke DeSmet, Assistant City Attorney

| COUNCIL ACTION | YEAS | NAYS | PASS | ABSENT | CERTIFICATE  |
|----------------|------|------|------|--------|--|
| COWNIE         |      |      |      |        | O EIKIN IO/KIE   |
| BOESEN         |      |      |      |        | I, DIANE RAUH, City Clerk of said City hereby  |
| COLEMAN        |      |      |      |        | certify that at a meeting of the City Council of said                                      |
| GATTO          |      |      |      |        | City of Des Moines, held on the above date, among other proceedings the above was adopted. |
| GRAY           |      |      |      |        |  |
| MANDELBAUM     |      |      |      |        | IN WITNESS WHEREOF, I have hereunto set my   |
| WESTERGAARD    |      |      |      |        | hand and affixed my seal the day and year first<br>above written.                          |
| TOTAL          |      |      |      |        | above written.   |
| OTION CARRIED  | 1    |      | API  | PROVED |  |
|                |      |      |      |        |  |
|                |      |      |      |        |  |
|                |      |      |      | Mayor  | City Clerk   |



DATE OF NOTICE: July 15, 2019

#### PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA

DATE OF INSPECTION: May 10, 2019

| COD2019-02109       |
|---------------------|
| 1304 E 37TH ST      |
| LOT 255 GRAYS WOODS |
|                     |

RICHARD A REYNOLDS Title Holder 2745 E GRAND AVE DES MOINES IA 50317

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-192 and 60-191 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

### ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Casey Doran

(515) 283-4183

Nid Inspector DATE MAILED: 7

7/15

MAILED BY: JDH

| Areas that hee   |  |  |   |
|--|--|--|---|
| <u>Component:</u><br><u>Requirement:</u>   | Roof<br>Compliance with Int. Exiting Building  | Defect:  | Cracked/Broken  |
|  | Code   | Location:  | Garage Throughout   |
| <u>Comments:</u>   | Roof needs repaired where tree fell on. Pre-   | emit may be  | e required.   |
|  |  |  | ÷.  |
| Component:   | Soffit/Facia/Trim  | Defect:  | Absence of paint  |
| Requirement:   | Unknown  |  |   |
|  | 3  | Location:  | Garage Throughout   |
| <u>Comments:</u>   | Needs fixed and painted to match.  |  |   |
|  | 4  |  |   |
| Component:   | Exterior Doors/Jams  | Defect:  | Cracked/Broken  |
| Requirement:   | Compliance with Int. Exiting Building  | 800 - 10 COS   |   |
|  | Code   | Location:  | Garage Throughout   |
| Comments:  | All doors must shut and secure. Including  | roll up door   |   |
|  | à  |  |   |
| Component:   | Exterior Walls   | Defect:  | In poor repair  |
| Requirement:   |  |  |   |
| Comments:  |  | -  | Garage Throughout   |
| Gommonton  | Repair or replace and deteriorated and date house.   | maged sidir  | ng. I rim included. Must match  |
|  | nouse.   |  |   |
|  |  |  | and the second  |
| Component:   | Exterior Walls   | Defect:  | In poor repair  |
| <u>Component:</u><br><u>Requirement:</u>   | Exterior Walls   |  |   |
| a second so a second day i   |  | Location:  | Main Structure Throughout   |
| <u>Requirement:</u>  | Repair or replace and deteriorated and da  | Location:  | Main Structure Throughout   |
| <u>Requirement:</u>  |  | Location:  | Main Structure Throughout   |
| Requirement:<br>Comments:<br>Component:  | Repair or replace and deteriorated and da garage.  | Location:  | Main Structure Throughout   |
| Requirement:<br>Comments:  | Repair or replace and detériorated and da garage.  | Location:<br>maged sidir<br>Defect:  | Main Structure Throughout<br>nd. Trim included. Must match<br>Smoke Damage  |
| Requirement:<br>Comments:<br>Component:  | Repair or replace and deteriorated and da<br>garage.<br>Ductwork<br>Licensed Contractor Certification  | Location:<br>maged sidir<br>Defect:  | Main Structure Throughout<br>nd. Trim included. Must match  |
| Requirement:<br>Comments:<br>Component:<br>Requirement:  | Repair or replace and deteriorated and da garage.  | Location:<br>maged sidir<br>Defect:  | Main Structure Throughout<br>nd. Trim included. Must match<br>Smoke Damage  |
| Requirement:<br>Comments:<br>Component:<br>Requirement:  | Repair or replace and deteriorated and da<br>garage.<br>Ductwork<br>Licensed Contractor Certification<br>Clean all duct work in living space.  | Location:<br>maged sidir<br>Defect:<br>Location:   | Main Structure Throughout<br>nd. Trim included. Must match<br>Smoke Damage<br>Main Structure Throughout   |
| Requirement:   Comments:   Component:   Requirement:   Comments:   Comments:   | Repair or replace and deteriorated and da<br>garage.<br>Ductwork<br>Licensed Contractor Certification<br>Clean all duct work in living space.<br>Electrical System   | Location:<br>maged sidir<br>Defect:  | Main Structure Throughout<br>nd. Trim included. Must match<br>Smoke Damage  |
| Requirement:<br>Comments:<br>Component:<br>Requirement:<br>Comments:   | Repair or replace and deteriorated and da<br>garage.<br>Ductwork<br>Licensed Contractor Certification<br>Clean all duct work in living space.  | Location:<br>maged sidir<br>Defect:<br>Location:<br>Defect:                                      | Main Structure Throughout<br>nd. Trim included. Must match<br>Smoke Damage<br>Main Structure Throughout   |
| Requirement:   Comments:   Component:   Requirement:   Comments:   Comments:   | Repair or replace and deteriorated and da<br>garage.<br>Ductwork<br>Licensed Contractor Certification<br>Clean all duct work in living space.<br>Electrical System<br>Licensed Contractor Certification  | Location:<br>maged sidir<br>Defect:<br>Location:<br>Location:                                    | Main Structure Throughout<br>nd. Trim included. Must match<br>Smoke Damage<br>Main Structure Throughout<br>In poor repair<br>Main Structure Throughout  |
| Requirement:   Comments:   Component:   Requirement:   Comments:   Comments:   Comments:   Requirement:   Requirement:   Requirement:   Component:   Requirement:                                | Repair or replace and deteriorated and da<br>garage.<br>Ductwork<br>Licensed Contractor Certification<br>Clean all duct work in living space.<br>Electrical System   | Location:<br>maged sidir<br>Defect:<br>Location:<br>Defect:<br>Location:<br>actor and pr         | Main Structure Throughout<br>nd. Trim included. Must match<br>Smoke Damage<br>Main Structure Throughout<br>In poor repair<br>Main Structure Throughout  |
| Requirement:   Comments:   Component:   Requirement:   Comments:   Component:   Requirement:   Component:   Comments:  | Repair or replace and deteriorated and da<br>garage.<br>Ductwork<br>Licensed Contractor Certification<br>Clean all duct work in living space.<br>Electrical System<br>Licensed Contractor Certification<br>Have electrical system inspected by contra<br>working condition. Permit may be required   | Location:<br>maged sidir<br>Defect:<br>Location:<br>Defect:<br>Location:<br>actor and pr         | Main Structure Throughout<br>nd. Trim included. Must match<br>Smoke Damage<br>Main Structure Throughout<br>In poor repair<br>Main Structure Throughout<br>rovide documents of proper  |
| Requirement:   Comments:   Component:   Requirement:   Comments:   Component:   Requirement:   Component:   Requirement:   Component:   Requirement:   Component:   Requirement:   Comments:     | Repair or replace and deteriorated and da<br>garage.<br>Ductwork<br>Licensed Contractor Certification<br>Clean all duct work in living space.<br>Electrical System<br>Licensed Contractor Certification<br>Have electrical system inspected by contra<br>working condition. Permit may be required<br>Exterior Doors/Jams  | Location:<br>maged sidir<br>Defect:<br>Location:<br>Defect:<br>Location:<br>actor and pr         | Main Structure Throughout<br>nd. Trim included. Must match<br>Smoke Damage<br>Main Structure Throughout<br>In poor repair<br>Main Structure Throughout  |
| Requirement:   Comments:   Component:   Requirement:   Comments:   Component:   Requirement:   Component:   Comments:  | Repair or replace and deteriorated and da<br>garage.<br>Ductwork<br>Licensed Contractor Certification<br>Clean all duct work in living space.<br>Electrical System<br>Licensed Contractor Certification<br>Have electrical system inspected by contra<br>working condition. Permit may be required   | Location:<br>maged sidir<br>Defect:<br>Location:<br>Defect:<br>Location:<br>actor and pr         | Main Structure Throughout<br>nd. Trim included. Must match<br>Smoke Damage<br>Main Structure Throughout<br>In poor repair<br>Main Structure Throughout<br>rovide documents of proper  |
| Requirement:   Comments:   Component:   Requirement:   Comments:   Component:   Requirement:   Component:   Requirement:   Component:   Requirement:   Component:   Requirement:   Comments:     | Repair or replace and deteriorated and da<br>garage.<br>Ductwork<br>Licensed Contractor Certification<br>Clean all duct work in living space.<br>Electrical System<br>Licensed Contractor Certification<br>Have electrical system inspected by contra<br>working condition. Permit may be required<br>Exterior Doors/Jams<br>Compliance with Int. Exiting Building         | Location:<br>maged sidir<br>Defect:<br>Location:<br>Defect:<br>Location:<br>Defect:<br>Location: | Main Structure Throughout<br>nd. Trim included. Must match<br>Smoke Damage<br>Main Structure Throughout<br>In poor repair<br>Main Structure Throughout<br>rovide documents of proper<br>In poor repair<br>Main Structure Throughout |
| Requirement:   Comments:   Component:   Requirement:   Comments:   Component:   Requirement:   Comments:   Comments:   Component:   Requirement:   Comments:   Comments:   Comments:   Comments: | Repair or replace and deteriorated and da<br>garage.<br>Ductwork<br>Licensed Contractor Certification<br>Clean all duct work in living space.<br>Electrical System<br>Licensed Contractor Certification<br>Have electrical system inspected by contra<br>working condition. Permit may be required<br>Exterior Doors/Jams<br>Compliance with Int. Exiting Building<br>Code | Location:<br>maged sidir<br>Defect:<br>Location:<br>Defect:<br>Location:<br>Defect:<br>Location: | Main Structure Throughout<br>nd. Trim included. Must match<br>Smoke Damage<br>Main Structure Throughout<br>In poor repair<br>Main Structure Throughout<br>rovide documents of proper<br>In poor repair<br>Main Structure Throughout |

## Areas that need attention: 1304 E 37TH ST

|  |  |              |                                 | 1.7   |
|--|--|--------------|---------------------------------|-------|
| <u>Component:</u>                        | Flooring   | Defect:      | Smoke Damage                    | 421   |
| Requirement:                             |  | 1.000040000  | Main Church and Thursday have   | ) ) ) |
|  | 3  | Location:    | Main Structure Throughout       |       |
| Comments:                                | Clean all flooring. Repair or replace as nee   | ded.         |                                 |       |
|  |  |              | ,                               | 2     |
|  | 3  |              |                                 |       |
| Component:                               | Furnace  | Defect:      | Smoke Damage                    | 1     |
| Requirement:                             | Licensed Contractor Certification  |              |                                 |       |
|  | R BEREFERSTON AND REPEATION AND AND A REPEATION AND A REPEATIO | Location:    | Basement                        |       |
| Comments:                                | Furnace must be cleaned and documents  | hat show n   | roper operation                 |       |
|  | Tumace must be cleaned and documents   | inde show p  |                                 |       |
| -<br>87                                  | -  |              | 1                               |       |
| Component:                               | Interior Walls /Ceiling  | Defect:      | Smoke Damage                    | 1     |
| <u>Component:</u><br><u>Requirement:</u> | Unknown  | Derecti      | Smoke Danage                    |       |
| <u>Requirement.</u>                      | UTKHUWI  | Location:    | Main Structure Throughout       |       |
| Comments:                                | Olema interior wells and sailing thoughout   | Daint ac no  |                                 |       |
|  | Clean interior walls and ceiling thoughout.  | Pallit as he | eueu.                           |       |
| 2  | 1.55   |              | -                               |       |
|  |  | Defeate      | Net in the line is a second and | 1     |
| Component:                               | Smoke Detectors  | Defect:      | Not installed as required       |       |
| <u>Requirement:</u>                      | Unknown  | Location     | Main Structure Throughout       |       |
| Comments:                                |  | ·            |                                 |       |
| <u>comments.</u>                         | Installed smoke detectors in bedrooms, ha  | all and base | ment. Permit may be required.   |       |
|  | 2 S at   |              |                                 | 5.    |
|  |  |              |                                 |       |
| Component:                               | Windows/Window Frames  | Defect:      | Deteriorated                    |       |
| <u>Requirement:</u>                      | Unknown  | 2            |                                 |       |
| 850 560                                  | 191  | Location:    | Main Structure Throughout       | 1     |
| Comments:                                | Fix all windows and frames. Need to open   | and close v  | without speacial tools of       |       |
|  | knowledge. Permit may be required.   |              | •                               |       |
|  |  |              |                                 |       |
|  |  |              |                                 |       |

## Polk County Assessor

111 Court Avenue #195 Des Moines, IA 50309-0904 (515) 286-3014 Fax (515) 286-3386 polkweb@assess.co.polk.ia.us

|              |   |  | Lo                   | cation                      | l  |                      |  |                     |
|--------------|---|--|----------------------|-----------------------------|--|----------------------|--|---------------------|
| Address      | 1304 E 37TH ST  | AND DECIDENT OF THE OWNER OF THE   |                      |                             |  |                      |  |                     |
| City         | DES MOINES  | S  | Zip                  |                             | 50317                                    | 7 Ju                 | risdiction   | Des Moines          |
|              | 060/05810-000-000   | ) Geo  | oparcel              | 792                         | 3-32-478-020                             | 5                    | Status   | Active              |
| School       | Des Moine   |  |                      |                             | DM13/2                                   | Tax                  | Authority<br>Group   | DEM-C-DEM-<br>77131 |
| Submarket    | Northeast Des Moine   | praiser  | Victo                | or Scaglione 515<br>286-389 |  |                      |  |                     |
|              | 2   | Map a  | and Curr             | ent P                       | hotos - 1 Re                             | cord                 |  |                     |
| Clic         | k on parcel to get a  | new list   | ting                 |                             |  |                      |  |                     |
|              | NUQUE AVE   |  |                      |                             | P  | hoto Proc            | essed on 2   | 013-09-27 a         |
| DOB          |   |  |                      | _                           |  |                      |  | A. Sec. 1.          |
|              | 1304<br>101 1300<br>1275 12<br>271 15<br>1 <u>gger Map Polk Con</u> | 1313<br>13<br>13<br>13<br>13<br>13<br>13<br>13<br>13<br>13<br>13<br>13<br>13 | 13D5<br>13D1<br>37D4 |                             |  |                      |  |                     |
|              |   |  | Histo                | orical                      | <u>Photos</u>                            | een ander tweetersta | and the second |                     |
|              |   | 0  | Ownersh              | ip - 1                      | Record                                   |                      |  |                     |
| Ownership    | Num   |  | Nam                  |                             |  | Reco                 |  | Book/Page           |
| Title Holder | 1 F   | REYNOI   | LDS, RIC             | HARI                        | DA                                       | 2010                 | -05-28   | 13460/132           |
|              | I   | legal De   | scription            | and I                       | Mailing Add                              | ress                 |  |                     |
| LOT 255 GR   | AYS WOODS   |  |                      | 130                         | CHARD A RI<br>4 E 37TH SI<br>5 MOINES, 1 |                      |  |                     |
|              |   |  | Curre                | ent Va                      | lues                                     |                      |  |                     |
| Туре         | Class   |  | Kir                  | nd                          | Lan                                      | d                    | Bldg   | Total               |
| 2019 Value   | Residential   |  | Fu                   | 11                          | \$13,50                                  | 0                    | \$66,800   | \$80,300            |


Assessment Roll Notice Market Adjusted Cost Report

## Auditor Adjustments to Value

| Category              | Name                | Information                |
|-----------------------|---------------------|----------------------------|
| 2019 Homestead Credit | REYNOLDS, RICHARD A | Application <u>#248133</u> |

## Zoning - 1 Record

| Zoning      |             |                      | Description                |              | SF         | Asses             | sor Zoning        |                    |
|-------------|-------------|----------------------|----------------------------|--------------|------------|-------------------|-------------------|--------------------|
| R1-60       | One         | Family, Low D        | ensity Residential Dis     |              |            | Re                | esidential        |                    |
| City of Des | Moines      | Community D          | evelopment Planning        | g and l      | Urban Desi | gn 515 2          | 83-4182           | (2012-03-20)       |
|             |             |                      | Land                       |              |            |                   |                   |                    |
| Square      | Feet        | 6,350                | Acres                      |              | 0.146      | Fron              | tage              | 50.0               |
| <u> </u>    | )epth       | 127.0                | Topography                 | 1            | Vormal     | S                 | hape              | Rectangle          |
|             | cancy       | No                   | Unbuildable                |              | No         |                   |                   |                    |
|             |             |                      | Residences -               | 1 Rec        | cord       |                   |                   |                    |
|             | <u></u>     |                      | Residenc                   | e #1         |            |                   |                   |                    |
| Occupar     | ncy         | Single<br>Family     |                            |              |            | Building<br>Style |                   | Ranch              |
| Year Bu     | ailt        | 1955                 | Number Fami                | ilies        | 1          | Grade             |                   | 5+10               |
| Condit      | ion         | Normal               | Total Square F<br>Living A |              |            | Main              | n Living<br>Area  | 675                |
| Basem       | ent<br>rea  | 675                  | Veneer A                   | rea          | 96         | Fou               | ndation           | Concrete<br>Block  |
| Exterior W  | Vall<br>ype | Metal<br>Siding      | Roof T                     | f Type Gable |            | N                 | Roof<br>Aaterial  | Asphalt<br>Shingle |
| Heat        |             | Gas<br>Forced<br>Air | Air Condition              | ing 0        |            | 1 A               | Number<br>throoms | 1                  |
| Bedroo      | ms          | 2                    | Ro                         | oms          | 4          |                   |                   |                    |



| Yr   | Туре            | Class       | Kind | Land     | Bldg     | Total    |
|------|-----------------|-------------|------|----------|----------|----------|
| 2019 | Assessment Roll | Residential | Full | \$13,500 | \$66,800 | \$80,300 |
| 2017 | Assessment Roll | Residential | Full | \$11,700 | \$60,300 | \$72,000 |
| 2015 | Assessment Roll | Residential | Full | \$11,000 | \$57,700 | \$68,700 |
| 2013 | Assessment Roll | Residential | Full | \$10,400 | \$56,300 | \$66,700 |
| 2013 | Assessment Roll | Residential | Full | \$10,400 | \$56,600 | \$67,000 |
| 2009 | Assessment Roll | Residential | Full | \$11,500 | \$62,300 | \$73,800 |
| 2007 | Assessment Roll | Residential | Full | \$11,100 | \$60,100 | \$71,200 |
| 2007 | Assessment Roll | Residential | Full | \$8,900  | \$56,500 | \$65,400 |

where a part is us/agi bip/wob/tt/infogry cgi2tt=card/card&dp=0600581000000@amp;

| 9/12/2019   |      |                 | Polk Cour   | nty Assessor 060/0 | )5810-000-000 |          | 43D      |
|-------------|------|-----------------|-------------|--------------------|---------------|----------|----------|
|             | Yr   | Туре            | Class       | Kind               | Land          | Bldg     | Total    |
|             | 2003 | Assessment Roll | Residential | Full               | \$8,080       | \$52,250 | \$60,330 |
|             | 2001 | Assessment Roll | Residential | Full               | \$7,220       | \$42,410 | \$49,630 |
|             | 1999 | Assessment Roll | Residential | Full               | \$5,940       | \$38,430 | \$44,370 |
|             | 1997 | Assessment Roll | Residential | Full               | \$5,380       | \$34,810 | \$40,190 |
|             | 1995 | Assessment Roll | Residential | Full               | \$4,660       | \$30,170 | \$34,830 |
|             | 1993 | Assessment Roll | Residential | Full               | \$4,390       | \$28,450 | \$32,840 |
| Carl Contra | 1991 | Assessment Roll | Residential | Full               | \$4,390       | \$25,460 | \$29,850 |
|             | 1990 | Board Action    | Residential | Full               | \$4,390       | \$24,910 | \$29,300 |
|             | 1990 | Assessment Roll | Residential | Full               | \$4,390       | \$28,210 | \$32,600 |

This template was last modified on Sat Mar 4 12:31:48 2017 .



19:01 6102/91/60

ATTACK MUST

4051

901

## 89:01 6102/91/60

# 45 mLE ≥ 4021

got

TTTI

.....