Roll Call Number	•
------------------	---

Agenda Iter	n Number
" 44	

Date December 16, 2019

#### ABATEMENT OF PUBLIC NUISANCE AT 400 E CRESTON AVENUE

WHEREAS, the property located at 400 E Creston Avenue, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the garage structure in its present condition constitutes not only a menace to health and safety but is also a public nuisance; and

WHEREAS, the Titleholder, Lacey C. Boles, and Mortgage Holder, Bankers Trust Company, N.A., were notified by personal service more than thirty days ago to repair or demolish the garage structure and as of this date have failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA:

The garage structure on the real estate legally described as The East 60 feet of Lot 129, CRAWFORD PLACE, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 400 E Creston Avenue, has previously been declared a public nuisance;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner(s) fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said garage structure.

Moved by	to adopt.

FORM APPROVED:

Megan Norberg Assistant City Attorney

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT
COWNIE				
BOESEN				
COLEMAN				
GATTO				
GRAY				
MANDELBAUM				
WESTERGAARD				
TOTAL				
MOTION CARRIED			API	PROVED

#### CERTIFICATE

I, P. Kay Cmelik, City Clerk of said City hereby certify that at a meeting of the City Council of said City of Des Moines, held on the above date, among other proceedings the above was adopted.

IN WITNESS WHEREOF, I have hereunto set my hand and affixed my seal the day and year first above written.


Mayor City Clerk


# **Polk County Assessor**

111 Court Avenue #195 Des Moines, IA 50309-0904 (515) 286-3014 Fax (515) 286-3386 polkweb@assess.co.polk.ia.us

Location								
Address	400 E CRESTON AVE							
City	DES MOINES Zip 50315 Jurisdiction Des M							
District/Parcel	010/01258-001-000	Geoparcel	7824-15-326-008	Status	<u>Active</u>			
School	Des Moines	Nbhd/Pocket	DM26/Z	Tax Authority Group	DEM-C-DEM- 77131			
Submarket	South Des Moines	Appraiser	Andrew Rand 515- 286-3368		V			

#### Map and Current Photos - 1 Record





#### **Historical Photos**

Ownership - 1 Record						
Ownership	Num	Name	Recorded	Book/Page		
Title Holder	1	BOLES, LACEY C	2009-08-19	<u>13176/33</u>		

#### Legal Description and Mailing Address

E 60F LOT 129 CRAWFORD PLACE

LACEY C BOLES 400 E CRESTON AVE DES MOINES, IA 50315-1964

#### **Current Values**

Туре	Class	Kind	Land	Bldg	Total
2019 Value	Residential	Full	\$22,200	\$118,800	\$141,000


#### Assessment Roll Notice Market Adjusted Cost Report

#### Auditor Adjustments to Value

Category	Name	Information
2019 Homestead Credit	BOLES, LACEY C	Application #238725

#### Zoning - 1 Record

			7 Olk County 7 look				
Zoning			Description		SF		ssor Zoning
R1-70	One	e Family, Low	Density Residential Dis	trict		R	esidential
			Conditional Z	Zoning			
			Docket_no <u>1</u>				
City of Des	Moine	es Community .	Development Planning	and Urban Des	sign 515 2	83-4182	(2012-03-20)
			Land				
Square	Feet	21,600	Acres	0.496	From	ntage	60.
	epth	360.0	Topography	Normal	S	hape	Rectangl
	ancy	No	Unbuildable	No			
			Residences -	1 Record			
			Residence	e #1			
Occupar	ncy	Single Family	Residence Type	1 Story	<b>Building Style</b>		
Year Bu	ıilt	1962	Number Families	1	Grade		
Conditi	ion	Above Normal	Total Square Foot Living Area	973	Main Living Area		9/
Basemo	ent rea	973	Finished Basement Area 1	500	Finished Basement Quality 1		nt Averag
To Baseme Fin		500	Deck Area	100	Cai	rport Ar	ea 30
Foundat	ion	Concrete Block	Exterior Wall Type	Brick	Brick%		
Roof Ty	уре	Hip	Roof Material	Asphalt Shingle	Number Fireplaces		1
Heat	ing	Gas Forced Air	Air Conditioning	100	Number Bathrooms		
Bedroo	ms	3	Rooms	5			



Detached Structures - 1 Record							
Detached Structure #101							
Occupancy	Garage	<b>Construction Type</b>	Measurement Code	Dimensions			
Measure 1	14	Measure 2	20	Story Height	1		
Grade	4	Year Built	1963	Condition	Normal		

### Sales - 1 Record

Sell	er	Buyer	Sale Date	Sale Price		Instrument	Book/Page		
ADAIR, WILBUR	W	BOLES, LACEY C	2009-08-12	\$117,000		\$117,000		Deed	<u>13176/33</u>
	Permits - 4 Records								
Year	Туре	Permit Status	Applicati	ion	Description				
Current	Permit	To Work	2019-08-20	0 fix damage/fire					
1996	Permit	No Add	1995-04-11	11 addition/fence (cost \$200)		0)			

## 1989-09-28 Historical Values

1995-03-31

Vr	Type	Class	Kind	Land	Bldg	Total

addition/fence (cost \$600)

carport - reval

No Add

Complete

Permit

Pickup

1996

1990

			~~. *	w 1	DLI.	Total
Yr	Туре	Class	Kind	Land	Bldg	Total
2019	Assessment Roll	Residential	Full	\$22,200	\$118,800	\$141,000
2017	Assessment Roll	Residential	Full	\$20,000	\$109,500	\$129,500
2015	Assessment Roll	Residential	Full	\$18,200	\$101,600	\$119,800
2013	Assessment Roll	Residential	Full	\$18,100	\$103,600	\$121,700
2011	Assessment Roll	Residential	Full	\$18,100	\$104,000	\$122,100
2009	Assessment Roll	Residential	Full	\$19,100	\$107,300	\$126,400
2007	Assessment Roll	Residential	Full	\$19,700	\$110,800	\$130,500
2005	Assessment Roll	Residential	Full	\$20,700	\$96,800	\$117,500
2003	Assessment Roll	Residential	Full	\$18,550	\$87,380	\$105,930
2001	Assessment Roll	Residential	Full	\$14,140	\$67,580	\$81,720
1999	Assessment Roll	Residential	Full	\$11,680	\$69,840	\$81,520
1997	Assessment Roll	Residential	Full	\$10,400	\$62,190	\$72,590
1995	Assessment Roll	Residential	Full	\$9,450	\$56,540	\$65,990
1993	Assessment Roll	Residential	Full	\$8,830	\$52,840	\$61,670
1991	Assessment Roll	Residential	Full	\$8,030	\$48,040	\$56,070
1990	Assessment Roll	Residential	Full	\$8,030	\$50,310	\$58,340

This template was last modified on Sat Mar 4 12:31:48 2017 .



# PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA

**DATE OF NOTICE: September 12, 2019** 

DATE OF INSPECTION:

April 09, 2019

CASE NUMBER:

COD2019-01750

**PROPERTY ADDRESS:** 

400 E CRESTON AVE

**LEGAL DESCRIPTION:** 

E 60F LOT 129 CRAWFORD PLACE

LACEY C BOLES
Title Holder
400 E CRESTON AVE
DES MOINES IA 50315-1964

BANKERS TRUCST COMPANY, N.A.
Mortgage Holder - ATTN: DON COFFIN - PRESIDENT
453 7TH ST
DES MOINES IA 50309

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-192 and 60-191 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Daniel Adams

(515) 237-1612

Nid Inspector

DATE MAILED: 9/12/2019

MAILED BY: TSY

#### Areas that need attention: 400 E CRESTON AVE

Areas that nee	d attention: 400 E CRESTON AVE				
Component:	Electrical Service	Defect:	Fire damaged		
Requirement:	Electrical Permit				
<u>iccquirement</u>	Electrical i citilic	Location:	Garage Throughout		¥
Commonia					
<u>Comments:</u>			* ·	,	
		f w			
Component:	Exterior Doors/Jams	Defect:	Fire damaged	100	N.
Requirement:	Building Permit				
	* 1	Location:	Garage Throughout		
Comments:					
Component:	Exterior Walls	Defect:	Fire damaged		
Requirement:		<u> </u>	i ii c damagea		
<u>Requirement:</u>	Building Permit	Location	Garage Throughout		
		LOCATION	darage miloughout		
<u>Comments:</u>	N.				
	4		•		,
Component:	Interior Walls /Ceiling	Defect:	Fire damaged		
Requirement:	Building Permit		* 1		
		Location:	Garage Throughout		
Comments:					
,	,				
Component:	Roof	Defect:	Fire damaged		
Component:	Roof Ruilding Permit	Defect:	Fire damaged		
Component: Requirement:	Roof Building Permit				,
Requirement:			Fire damaged Garage Throughout		v
Requirement:					
Requirement:					
Requirement: Comments:	Building Permit	Location:	Garage Throughout		,
Requirement:  Comments:  Component:	Building Permit  Shingles Flashing			-	
Requirement: Comments:	Building Permit  Shingles Flashing Compliance with International Building	Location:  Defect:	Garage Throughout Fire damaged		
Requirement: Comments: Component: Requirement:	Building Permit  Shingles Flashing	Location:  Defect:	Garage Throughout		
Requirement:  Comments:  Component:	Building Permit  Shingles Flashing Compliance with International Building	Location:  Defect:	Garage Throughout Fire damaged		
Requirement: Comments: Component: Requirement:	Building Permit  Shingles Flashing Compliance with International Building	Location:  Defect:	Garage Throughout Fire damaged		
Requirement: Comments: Component: Requirement:	Building Permit  Shingles Flashing Compliance with International Building	Location:  Defect:	Garage Throughout Fire damaged		
Requirement: Comments: Component: Requirement:	Building Permit  Shingles Flashing Compliance with International Building	Location:  Defect:	Garage Throughout  Fire damaged  Garage Throughout		
Requirement: Comments: Component: Requirement: Comments:	Shingles Flashing Compliance with International Building Code	Location:  Defect:	Garage Throughout Fire damaged	* * * * * * * * * * * * * * * * * * *	
Requirement: Comments: Component: Requirement: Comments:	Shingles Flashing Compliance with International Building Code  Soffit/Facia/Trim	Location:  Defect: Location:	Garage Throughout  Fire damaged  Garage Throughout	* * * * * * * * * * * * * * * * * * *	
Requirement: Comments: Component: Requirement: Comments:	Shingles Flashing Compliance with International Building Code	Location:  Defect: Location:	Garage Throughout  Fire damaged  Garage Throughout  Fire damaged		
Requirement: Comments: Component: Requirements: Comments: Comments: Requirement:	Shingles Flashing Compliance with International Building Code  Soffit/Facia/Trim	Location:  Defect: Location:	Garage Throughout  Fire damaged  Garage Throughout		
Requirement: Comments: Component: Requirement: Comments:	Shingles Flashing Compliance with International Building Code  Soffit/Facia/Trim	Location:  Defect: Location:	Garage Throughout  Fire damaged  Garage Throughout  Fire damaged		
Requirement: Comments: Component: Requirements: Comments: Comments: Requirement:	Shingles Flashing Compliance with International Building Code  Soffit/Facia/Trim	Location:  Defect: Location:	Garage Throughout  Fire damaged  Garage Throughout  Fire damaged		
Requirement: Comments: Component: Requirements: Comments: Comments: Requirement:	Shingles Flashing Compliance with International Building Code  Soffit/Facia/Trim	Location:  Defect: Location:	Garage Throughout  Fire damaged  Garage Throughout  Fire damaged		
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Shingles Flashing Compliance with International Building Code  Soffit/Facia/Trim Building Permit	Location:  Defect: Location:  Defect: Location:	Fire damaged Garage Throughout  Fire damaged Garage Throughout  Garage Throughout		
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments:	Shingles Flashing Compliance with International Building Code  Soffit/Facia/Trim Building Permit  Window Glazing/Paint	Location:  Defect: Location:	Garage Throughout  Fire damaged  Garage Throughout  Fire damaged		
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Shingles Flashing Compliance with International Building Code  Soffit/Facia/Trim Building Permit	Location:  Defect: Location:  Defect: Location:	Fire damaged Garage Throughout  Fire damaged Garage Throughout  Fire damaged Fire damaged		
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments: Requirement: Requirement: Requirement:	Shingles Flashing Compliance with International Building Code  Soffit/Facia/Trim Building Permit  Window Glazing/Paint	Location:  Defect: Location:  Defect: Location:	Fire damaged Garage Throughout  Fire damaged Garage Throughout  Garage Throughout		
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments:	Shingles Flashing Compliance with International Building Code  Soffit/Facia/Trim Building Permit  Window Glazing/Paint	Location:  Defect: Location:  Defect: Location:	Fire damaged Garage Throughout  Fire damaged Garage Throughout  Fire damaged Fire damaged		
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments: Requirement: Requirement: Requirement:	Shingles Flashing Compliance with International Building Code  Soffit/Facia/Trim Building Permit  Window Glazing/Paint	Location:  Defect: Location:  Defect: Location:	Fire damaged Garage Throughout  Fire damaged Garage Throughout  Fire damaged Fire damaged		
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments: Requirement: Requirement: Requirement:	Shingles Flashing Compliance with International Building Code  Soffit/Facia/Trim Building Permit  Window Glazing/Paint	Location:  Defect: Location:  Defect: Location:	Fire damaged Garage Throughout  Fire damaged Garage Throughout  Fire damaged Fire damaged		

 Component:
 Windows/Window Frames
 Defect:
 Fire damaged

 Requirement:
 Building Permit
 Location:
 Garage Throughout

 Comments:
 Comments:
 Comments:
 Comments:
 Comments:
 Comments:
 Comments:

