

Agenda Item Number



Date January 13, 2020

ABATEMENT OF PUBLIC NUISANCE AT 2020 10th STREET

WHEREAS, the property located at 2020 10th Street, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure in its present condition constitutes not only a menace to health and safety but is also a public nuisance; and

WHEREAS, the Titleholder, Rashawn Lovejoy, was notified more than thirty days ago to repair or demolish the main structure and as of this date has failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA:

The main structure on the real estate legally described as Lot 112 in THIRD PLAT OF PROSPECT PARK, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 2020 10th Street, has previously been declared a public nuisance;


The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner(s) fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said structure.

Moved by to adopt.

FORM APPROVED:

Megan Norberg, Assistant City Attorney

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT	CERTIFICATE
COWNIE					
BOESEN					I, P. Kay Cmelik, City Clerk of said City hereby
GATTO					certify that at a meeting of the City Council of said
GRAY					City of Des Moines, held on the above date, among other proceedings the above was adopted.
MANDELBAUM					other proceedings the above was adopted.
VOSS					IN WITNESS WHEREOF, I have hereunto set my
WESTERGAARD					hand and affixed my seal the day and year first
TOTAL					above written.
MOTION CARRIED			API	PROVED	
]	Mayor	City Clerk







2020 10th St





PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA

DATE OF NOTICE: Februa	ary 13, 2019	DATE OF INSPECTION:	February 12, 2019
CASE NUMBER:	COD2019-00526		
PROPERTY ADDRESS:	2020 10TH ST		
LEGAL DESCRIPTION:	LOT 112 THIRD PLAT PRO	SPECT PARK	

RASHAWN LOVEJOY Title Holder 1143 65TH ST WINDSOR HEIGHTS IA 50324

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-192 and 60-191 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

\\CDMAPPS1\D-VOLUME\APPDATA\Tidemark\prd_41\Forms & Reports\dsmCODPubNo.rp

Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Nid Inspector (Sist えるき ムリレイ DATE MAILED: 2/13/2019

MAILED BY: SMB1

	d attention: 2020 10TH ST		
Component:	Electrical System	Defect:	Deteriorated
Requirement:	Compliance with National Electrical Code	•	
		Location:	Main Structure Throughout
Comments:			
<u>commenter</u>	Permit and final inspection required for co	mpliance.	
Component:	Floor Joists/Beams	Defect:	Deteriorated
Requirement:	Compliance with International Building		
Reguirementi	Code	Location:	Main Structure Throughout
Comments:			
<u>comments.</u>	Permit and final inspection required for co	mpliance.	
Component:	Foundation	Defect:	Collapsed
Requirement:	Compliance with International Building	Dereett	Condpsed
<u>Requirement.</u>		Location	Main Structure
Commontes	Code		í.
<u>Comments:</u>	Have foundation inspected by qualified en	gineer. Mak	e structural repairs as needed.
	Must be done with building permit and fin	al inspection	n for compliance.
Common anti	F	Defect:	In disrepair
<u>Component:</u>	Furnace	Delecti	
<u>Requirement:</u>	Compliance, Uniform Mechanics Code	Location	Basement
C		LOCATION	Dasement
<u>Comments:</u>	Have furnace inspected and serviced by q	ualified cont	tractor. Provide copy of
	receipt.		
Common on the	Flagwing	Defect:	Deteriorated
<u>Component:</u>	Flooring	Delecti	Detenorated
<u>Requirement:</u>		Location	Main Structure Throughout
Commonter		Location	Main Structure Throughout
Comments:			
	Tutovicy Mollo (Coiling	Defect:	Cracked/Broken
Component:	Interior Walls /Ceiling	Defect:	Cracked/Broken
Component: Requirement:	Compliance with International Building		
Requirement:			Cracked/Broken Main Structure Throughout
	Compliance with International Building		
Requirement:	Compliance with International Building		
Requirement:	Compliance with International Building		
Requirement: Comments:	Compliance with International Building Code	Location:	Main Structure Throughout
Requirement: Comments: Component:	Compliance with International Building Code Landings		
Requirement: Comments:	Compliance with International Building Code	Location: Defect:	Main Structure Throughout Major sagging
Requirement: Comments: Component: Requirement:	Compliance with International Building Code Landings Complaince with Int Residential Code	Location: Defect: Location:	Main Structure Throughout
Requirement: Comments: Component:	Compliance with International Building Code Landings	Location: Defect: Location:	Main Structure Throughout Major sagging
Requirement: Comments: Component: Requirement:	Compliance with International Building Code Landings Complaince with Int Residential Code	Location: Defect: Location:	Main Structure Throughout Major sagging
Requirement: Comments: Component: Requirement:	Compliance with International Building Code Landings Complaince with Int Residential Code	Location: Defect: Location:	Main Structure Throughout Major sagging
Requirement: Comments: Component: Requirement: Comments:	Compliance with International Building Code Landings Complaince with Int Residential Code Repair front steps to meet height requirer	Location: Defect: Location: nents.	Main Structure Throughout Major sagging Main Structure Throughout
Requirement: Comments: Component: Requirement: Comments:	Compliance with International Building Code Landings Complaince with Int Residential Code Repair front steps to meet height requirer Plumbing System	Location: Defect: Location:	Main Structure Throughout Major sagging
Requirement: Comments: Component: Requirement: Comments:	Compliance with International Building Code Landings Complaince with Int Residential Code Repair front steps to meet height requirer	Location: Defect: Location: nents. Defect:	Main Structure Throughout Major sagging Main Structure Throughout Deteriorated
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments:	Compliance with International Building Code Landings Complaince with Int Residential Code Repair front steps to meet height requirer Plumbing System	Location: Defect: Location: nents. Defect:	Main Structure Throughout Major sagging Main Structure Throughout
Requirement: Comments: Component: Requirement: Comments:	Compliance with International Building Code Landings Complaince with Int Residential Code Repair front steps to meet height requirer Plumbing System Compliance with Uniform Plumbing Code	Location: Defect: Location: nents. Defect: Location:	Main Structure Throughout Major sagging Main Structure Throughout Deteriorated
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments:	Compliance with International Building Code Landings Complaince with Int Residential Code Repair front steps to meet height requirer Plumbing System	Location: Defect: Location: nents. Defect: Location:	Main Structure Throughout Major sagging Main Structure Throughout Deteriorated
Requirement: Comments: Component: Requirement: Comments: Comments: Comments:	Compliance with International Building Code Landings Complaince with Int Residential Code Repair front steps to meet height requirer Plumbing System Compliance with Uniform Plumbing Code	Location: Defect: Location: nents. Defect: Location:	Main Structure Throughout Major sagging Main Structure Throughout Deteriorated

Areas that need attention: 2020 10TH ST

<u>Component:</u> <u>Requirement:</u> <u>Comments:</u>	Windows/Window Frames Compliance International Building Code	Defect: Location:	Deteriorated Main Structure Throughout
<u>Component:</u> <u>Requirement:</u> <u>Comments:</u>	Wiring Compliance with National Electrical Code Permit and final inspection required for con		In poor repair Main Structure Throughout
Component: Requirement: Comments:	Flooring Compliance with International Building Code Replace broken concrete floor throughout		Cracked/Broken Main Structure Throughout

. .

. .

. .

,

. .

Polk County Assessor

111 Court Avenue #195 Des Moines, IA 50309-0904 (515) 286-3014 Fax (515) 286-3386 polkweb@assess.co.polk.ia.us

		L	ocation			
Address	2020 10TH ST					
City	DES MOINES	5 Zip	50.	314 Jurisdiction	Des Moines	
District/Parcel	080/05571-000-00) Geoparcel	7924-34-128-	017 Status		
School	Des Moine	s Nbhd/Pocket	DM7	8/Z Tax Authority Group		
Submarket	Northwest Des Moine	s Appraiser	Andrew Rand 515-	286- 3368		
		Map and Cu	rrent Photos - 1 R	ecord		
Clic	k on parcel to get a	new listing				
2034 2034 2032 2028 2020 2028 2020 2021 2011 2012 2011 2012 2011 2011 2008 2021 2011 2011 2011 2011 2009 2001 UNCOLNAVE UNCOLNAVE						
			storical Photos			
			ship - 1 Record			
Ownership		Na		Recorded	Book/Page	
Title Holder	1	LOVEJOY, RA		2018-02-01	<u>16807/839</u>	
	.]	Legal Descriptio	on and Mailing A	aress		
LOT 112 THIRD PLAT PROSPECT PARK RASHAWN LOVEJOY 1143 65TH ST WINDSOR HEIGHTS, IA 50324-1807						

Current Values

Туре	Гуре Class		Land	Bldg	Total			
2019 Value	Residential	Full	\$12,100	\$5,000	\$17,100			
Assessment Roll Notice Market Adjusted Cost Report								
	Zoning - 1 Record							
Zoning	ing Description			Assessor	Zoning			
R-3 Multiple Family Residential District				Multi-Family	Residential			
Conditional Zoning								

		Conditional			
		Docket_no			
City of Des Moin	es Community	Development Planning	g and Urban Des	ign 515 283-4182 (.	2012-03-20)
		Land			
Square Fee	t 11,:	553 Acres	0.26	5 Frontage	50.0
Topography			Rectangula	r Vacancy	v No
Unbuildabl		No			
		Residences -	- 1 Record		
		Residenc	e #1		
Occupancy	Single Family	Residence Type	1 Story	Building Style	Bungalow
Year Built	1921	Number Families	1	Grade	4-05
Condition	Very Poor	Total Square Foot Living Area	1040	Main Living Area	1040
Basement Area	1031	Foundation	Brick	Exterior Wall Type	Stucco
Roof Type	Gable	Roof Material	Asphalt Shingle	Heating	Gas Forced Air
Air Conditioning	0	Number Bathrooms	1	Bedrooms	2
Rooms	5				
	43 1= 9	<u>1</u> 5 Батб 1031		39	

Seller	Buyer	Sale Date	Sale Price	Instrument	Book/Page
RANSEY, TANISHA	LOVEJOY, RASHAWN	<u>2018-01-30</u>	\$2,000	Deed	<u>16807/839</u>
CASTRO, RAFAEL	RANSEY- ELNOUR, TANISHA	<u>2002-04-30</u>	\$59,000	Deed	<u>9130/749</u>
FATHER & SON, ENTERPRISES	CASTRO, RAFAEL	<u>1995-05-01</u>	\$26,000	Contract	<u>7187/999</u>
ROBERTS, DWAINE L	RUPERTO, CHARLES DBA FATHER & SON ENTERP	<u>1993-06-22</u>	\$15,000	Contract	<u>6806/123</u>
ROBERTS, DWAINE L	SHOUDEL, GREGORY A	<u>1993-02-04</u>	\$16,000	Contract	<u>6720/587</u>

Sales - 5 Records

Recent Ownership Transfers

Granto	Grantor Grantee		Grantee Instrument Reco Date Date		Recording Date	Instrument Type	Book/Pg	
	RANSEY, LOVEJOY, TANISHA RASHAWN		2018-0	1-18	2018-02- 01	Quit Claim Deed	<u>16807/839</u>	
	Permits - 1 Record							
Year	Type Permit Status		tus	Application		Description		
2019	Pickup	Complete		2018-08-24		review value/per sale		

Historical Values

Yr	Туре	Class	Kind	Land	Bldg	Total
2019	Assessment Roll	Residential	Full	\$12,100	\$5,000	\$17,100
2017	Assessment Roll	Residential	Full	\$10,900	\$45,400	\$56,300
2015	Assessment Roll	Residential	Full	\$10,200	\$43,000	\$53,200
2013	Assessment Roll	Residential	Full	\$9,700	\$40,400	\$50,100
2011	Assessment Roll	Residential	Full	\$9,700	\$40,700	\$50,400
2009	Assessment Roll	Residential	Full	\$9,700	\$43,500	\$53,200
2007	Assessment Roll	Residential	Full	\$10,000	\$44,800	\$54,800
2005	Assessment Roll	Residential	Full	\$10,800	\$40,100	\$50,900
2003	Assessment Roll	Residential	Full	\$9,050	\$34,080	\$43,130
2001	Assessment Roll	Residential	Full	\$6,780	\$24,730	\$31,510
1999	Assessment Roll	Residential	Full	\$5,140	\$14,910	\$20,050
1997	Assessment Roll	Residential	Full	\$4,750	\$13,770	\$18,520
1995	Assessment Roll	Residential	Full	\$4,310	\$12,480	\$16,790
1995	Was Prior Year	Residential	Full	\$3,730	\$13,060	\$16,790

This template was last modified on Sat Mar 4 12:31:48 2017 .