

Date February 10, 2020

ABATEMENT OF PUBLIC NUISANCE AT 3720 ML KING JR PKWY

WHEREAS, the property located at 3720 ML King Jr Pkwy, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the commercial structure in its present condition constitutes not only a menace to health and safety but is also a public nuisance; and

WHEREAS, the Titleholder, Summer Woods Apts, LLC, and the Mortgage Holder, Community Business Lenders, LLC, were notified more than thirty days ago to repair or demolish the commercial structure and as of this date have failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA:

The commercial structure on the real estate legally described as The North 276 feet of Lot 3 in EUCLID HEIGHTS, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 3720 ML King Jr Pkwy, has previously been declared a public nuisance;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner(s) fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said structure.

> to adopt. Moved by

FORM APPROVED:

Megan Norberg, Assistant City Attorney

	COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT	CE
_	COWNIE					
-	BOESEN					I, P. Kay Cmelik, Cit
-	GATTO					certify that at a meetin
-	GRAY					City of Des Moines, h other proceedings the
-	MANDELBAUM					other proceedings the
	VOSS					IN WITNESS WHERE
-	WESTERGAARD					hand and affixed my
	TOTAL					above written.
N	10TION CARRIED			API	PROVED	

ERTIFICATE

ty Clerk of said City hereby ng of the City Council of said held on the above date, among e above was adopted.

EOF, I have hereunto set my y seal the day and year first

City Clerk

Mayor



PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA

DATE OF NOTICE: May 3	DATE OF	Marc		
CASE NUMBER:	COD2019-01056		-	
PROPERTY ADDRESS:	3720 MARTIN LUTHER KIN	g.jr pkwy		
LEGAL DESCRIPTION:	N 276 F LOT 3 EUCLID HEI	GHTS		

SUMMER WOODS APTS LLC Title Holder - RYAN WINTER, REG AGENT 4214 FLEUR DR STE 10 DES MOINES IA 50321

COMMUNITY BUSINESS LENDERS LLC. Mortgage Holder - MURRAY WILLIAMS, REG AGENT 7745 OFFICE PLAZA DR N STE 170 WEST DES MOINES IA 50266

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-192 and 60-191 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES. Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Justin S. Denning

(515) 237-1484

Nid Inspector DATE MAILED: 5/31/2019

MAILED BY: KMD

\\CDMAPPS1\D-VOLUME\APPDATA\Tidemark\prd_41\Forms & Reports\dsmCODPubNo.rp

Areas that need attention: 3720 MARTIN LUTHER KING JR PKWY

Component	Flastrian Convice	Defect:	Fire damaged		
Component:	Electrical Service	Delecti	Fire damaged		
Requirement:	Compliance with National Electrical Code				
	· .	Location:	Throughout		
Comments:	Permit required	_			£
	Permit required	· .			
~.;					
Component:	Mechanical System	Defect:	Fire damaged		
Requirement:	Compliance, Uniform Mechanics Code		The damaged		
Kequitementi	compliance, oniform mechanics code	Location	Throughout		
Ö.		Location	moughout		
Comments:	Permit required				
	·				
	•		/		
Component:	Plumbing System	Defect:	Fire damaged		
Requirement:	Compliance with Uniform Plumbing Code				
	· · · · ·	Location:	Throughout		
Comments:			meagneat		
commentor	Permit required				· · · · ·
		D.C.I			
Component:	Exterior Walls	Defect:	Fire damaged		
<u>Requirement:</u>	Compliance with International Building				
	Code	Location:	Throughout		
Comments:	Downit waguirad				
	Permit required				
Component:	Electrical Lighting Fixtures	Defect:	Fire damaged		
<u>Component:</u> Requirement:	Electrical Lighting Fixtures	Defect:	Fire damaged		
<u>Component:</u> <u>Requirement:</u>	Electrical Lighting Fixtures Compliance with National Electrical Code		, –		
Requirement:	Compliance with National Electrical Code		Fire damaged Throughout		
			, –		
Requirement:	Compliance with National Electrical Code		, –		
Requirement:	Compliance with National Electrical Code		, –	-	
<u>Requirement:</u> <u>Comments:</u>	Compliance with National Electrical Code Permit required	Location:	Throughout	-	
Requirement: Comments: Component:	Compliance with National Electrical Code Permit required Electrical Other Fixtures		, –		
<u>Requirement:</u> <u>Comments:</u>	Compliance with National Electrical Code Permit required	Location: Defect:	Throughout Fire damaged	-	
Requirement: Comments: Component:	Compliance with National Electrical Code Permit required Electrical Other Fixtures	Location: Defect:	Throughout	-	
Requirement: Comments: Component:	Compliance with National Electrical Code Permit required Electrical Other Fixtures Compliance with National Electrical Code	Location: Defect:	Throughout Fire damaged		
Requirement: Comments: Component: Requirement:	Compliance with National Electrical Code Permit required Electrical Other Fixtures	Location: Defect:	Throughout Fire damaged		
Requirement: Comments: Component: Requirement:	Compliance with National Electrical Code Permit required Electrical Other Fixtures Compliance with National Electrical Code	Location: Defect:	Throughout Fire damaged		
Requirement: Comments: Component: Requirement:	Compliance with National Electrical Code Permit required Electrical Other Fixtures Compliance with National Electrical Code	Location: Defect:	Throughout Fire damaged		
Requirement: Comments: Component: Requirement: Comments:	Compliance with National Electrical Code Permit required Electrical Other Fixtures Compliance with National Electrical Code Permit required	Location: Defect: Location:	Throughout Fire damaged Throughout		
Requirement: Comments: Component: Requirement: Comments:	Compliance with National Electrical Code Permit required Electrical Other Fixtures Compliance with National Electrical Code Permit required Flooring	Location: Defect:	Throughout Fire damaged		
Requirement: Comments: Component: Requirement: Comments:	Compliance with National Electrical Code Permit required Electrical Other Fixtures Compliance with National Electrical Code Permit required	Location: Defect: Location: Defect:	Throughout Fire damaged Throughout Fire damaged		
Requirement: Comments: Component: Requirement: Comments: Comments: Component: Requirement:	Compliance with National Electrical Code Permit required Electrical Other Fixtures Compliance with National Electrical Code Permit required Flooring	Location: Defect: Location: Defect:	Throughout Fire damaged Throughout		
Requirement: Comments: Component: Requirement: Comments:	Compliance with National Electrical Code Permit required Electrical Other Fixtures Compliance with National Electrical Code Permit required Flooring	Location: Defect: Location: Defect:	Throughout Fire damaged Throughout Fire damaged		
Requirement: Comments: Component: Requirement: Comments:	Compliance with National Electrical Code Permit required Electrical Other Fixtures Compliance with National Electrical Code Permit required Flooring Complaince with Int Residential Code	Location: Defect: Location: Defect:	Throughout Fire damaged Throughout Fire damaged		
Requirement: Comments: Component: Requirement: Comments:	Compliance with National Electrical Code Permit required Electrical Other Fixtures Compliance with National Electrical Code Permit required Flooring Complaince with Int Residential Code	Location: Defect: Location: Defect:	Throughout Fire damaged Throughout Fire damaged		
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Component: Comments:	Compliance with National Electrical Code Permit required Electrical Other Fixtures Compliance with National Electrical Code Permit required Flooring Complaince with Int Residential Code Permit required	Location: Defect: Location: Defect: Location:	Throughout Fire damaged Throughout Fire damaged Throughout		
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Compliance with National Electrical Code Permit required Electrical Other Fixtures Compliance with National Electrical Code Permit required Flooring Complaince with Int Residential Code Permit required	Location: Defect: Location: Defect:	Throughout Fire damaged Throughout Fire damaged		
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Comments:	Compliance with National Electrical Code Permit required Electrical Other Fixtures Compliance with National Electrical Code Permit required Flooring Complaince with Int Residential Code Permit required	Location: Defect: Location: Defect: Location:	Throughout Fire damaged Throughout Fire damaged Throughout		
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Compliance with National Electrical Code Permit required Electrical Other Fixtures Compliance with National Electrical Code Permit required Flooring Complaince with Int Residential Code Permit required	Location: Defect: Location: Defect: Location:	Throughout Fire damaged Throughout Fire damaged Throughout		
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Compliance with National Electrical Code Permit required Electrical Other Fixtures Compliance with National Electrical Code Permit required Flooring Complaince with Int Residential Code Permit required Ductwork Compliance, Uniform Mechanics Code	Location: Defect: Location: Defect: Location:	Throughout Fire damaged Throughout Fire damaged Throughout		
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Compliance with National Electrical Code Permit required Electrical Other Fixtures Compliance with National Electrical Code Permit required Flooring Complaince with Int Residential Code Permit required	Location: Defect: Location: Defect: Location:	Throughout Fire damaged Throughout Fire damaged Throughout		· · ·
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Compliance with National Electrical Code Permit required Electrical Other Fixtures Compliance with National Electrical Code Permit required Flooring Complaince with Int Residential Code Permit required Ductwork Compliance, Uniform Mechanics Code	Location: Defect: Location: Defect: Location:	Throughout Fire damaged Throughout Fire damaged Throughout		

· · ·				
Component:	Interior Walls /Ceiling	Defect:	Fire damaged	
Requirement:	Compliance with International Building			· .
Commenter	Code	Location:	Throughout	
Comments:	Permit required			
				3
Component:	Interior Stairway	Defect:	Fire damaged	
<u>Requirement:</u>	Compliance with International Building		·	
Commenter	Code	Location:	Throughout	
<u>Comments:</u>	Permit required		· ·	
	, · · · ·	· ,		
Component:	Roof	Defect:	Fire damaged	
Requirement:	Compliance with International Building			
Gamma	Code	Location:	Throughout	
Comments:	Permit required			
	· .			
Component:	Shingles Flashing	Defect:	Fire damaged	
Requirement:	Compliance with International Building	· · · · ·		
	Code	Location:	Throughout	
Comments:	Permit required			
		· · ·		
Component:	Soffit/Facia/Trim	Defect:	Fire damaged	
Requirement:	Compliance with International Building			
0	Code	Location:	Throughout	
Comments:	Permit requiredThird Floor			
				N
Component:	Trusses	Defect:	Fire damaged	
Requirement:	Compliance with International Building			
Commenter	Code	Location:	Throughout	
Comments:	Permit requiredThird Floor			· · ·
				× -
Component:	Windows/Window Frames	Defect:	Fire damaged	
Requirement:	Complaince with Int Residential Code	1		
Commenter		Location:	Throughout	а — та —
Comments:		, ·	74 -	3 m

Polk County Assessor

Polk County Assessor 080/01781-000-000

111 Court Avenue #195 Des Moines, IA 50309-0904 (515) 286-3014 Fax (515) 286-3386 polkweb@assess.co.polk.ia.us

32A

Location						
Address	3700 MARTIN LU	THER KING J	R PKWY			
City	DES MOINES	Zip	50310	Jurisdiction	Des Moines	
District/Parcel	080/01781-000-000	Geoparcel 7924-28-126-009		Status	<u>Active</u>	
School	Des Moines	Nbhd/Pocket			DEM-C-DEM- 77131	
Submarket	Northwest Des Moines	Appraiser				
		Map and Curr	ent Photos - 2 Reco	ords		
Clic	k on parcel to get a	new listing				
2535 2525 2518 3800 HR Photo Processed on 2016-10-03 a CLARKSON AVE CLARKSON AVE Photo Processed on 2016-10-03 a Photo Processed on 2016-10-03 a 2503 2518 3720 Photo Processed on 2016-10-03 a 2503 2518 3720 Photo Processed on 2016-10-03 a 2701 2614 3700 Photo Processed on 2016-10-03 a 2701 2603 2551 25262501 2425 076 2551 25262501 2425 2423 Bigger Map Polk County GIS Google Map Pictometry.						
Google Map Protometry Photo Processed on 2016-10-03 b Image: Cooperative state of the state						
	Ownership - 1 Record					
					\mathbf{D}_{-} , \mathbf{I}_{-} / \mathbf{D}_{-} .	
Ownership Title Holder	Num 1 SU	Nan MMER WOODS		Recorded 2011-07-07	Book/Page 13900/169	

1/30/2020

Polk County Assessor 080/01781-000-000

N 276 F LOT 3 EUCLID HEIGHTS

SUMMER WOODS APTS LLC 4214 FLEUR DR STE 10 DES MOINES, IA 50321

				Curr	ent Va	lues								
Туре		Class		Kir	nd	Land		B	Bldg	Total				
2019 Value		Multi-Residen		Fı		\$152,000		508,	,000	\$1,660,000				
		Asse	ssment Ro	oll Notic	<u>ce</u> Una	djusted Cost I	Report							
Zoning - 1 Record														
Zoning		Description SF						Asses	sor Zoning					
C-2	Gene	eral Retail and Highway Oriented Commercial Highw						ighway mmercial						
City of Des	Moine	es Community	Developm	ent Pl	anning	and Urban De	esign 51	5 28	3-4182	(2012-03-20)				
					Land									
Square	Feet	47,196		A	cres	1.083	F	ront	age	276.0				
	Depth	171.0	,	Topogra	aphy	Blank		Sh	ape	Rectangle				
	cancy	Blank	1	Unbuild	lable	Blank								
			C	Commen	cial Su	immary								
				Age,		1072	To	tal S	Story	3				
Occupanc	y	Apartment	Weig			1973		Η	eight	3				
Land Are	a	47,196	Gross A	Area		36,000			ished Area	36,000				
Unfinishe Bsmt Are		0	Fini Bsmt A	shed Area		0	N		oer of Units	48				
Primar Grou		Apartment	Prin	rcent nary roup		100.00	S	econ	rcent Idary Froup	0.00				
Grade Weighte		4/Grade 4	Bldg C Weig			4/Frame, concrete Blk, Tile, Tilt Up			ition, ghted	NM/Normal				
Groun Floor Are		12,000	Perin	neter		708								
			Comm	nercial S	Section	s - 2 Records								
			Co	ommerc	ial Sec	tion #101								
Occup	pant	BIRCHWO	OD APTS	S			1							
Sec Multip	tion olier	1	Occuj	pancy		Apartmo	ent	Fou	ndation	Concrete				
Submer	rged	Yes	Ex	terior Wall		Siding/Shingle		Siding/Shingle		Siding/Shingle		le Bri Vene		3,310
Insula	tion	Yes		Roof		Gable		Gable		ole Roo Materia		Shingle		
Land Square I		80		nding uality	Normal		rmal		Wiring	Adequate				
Plumb	bing	Adequate	Total H	Story Ieight			3		Frame Type	Frame				
Firep: Construc		No	Bldg	Class		Frame, Concr Blk, Tile, Tilt			Total Section Area	18,000				

Ground Floor	6,	,000	Peri	imeter		354	Grade	4-	+00
Area Year Built		973	Con	dition		Normal			
Comment				IDINGS		1.0111101			
					Groups - 1 R	lecord			1
					l Group #10				4
Use (Code	Apar	tment		ase Story		Number Stories		
Total G	roup Area	1	8,000	В	ase Floor Area	6,000	Number Units		
	ating		entral		Air ditioning	Yes	Exhaust System		
Com	ment	SLEE	EVE TY	PE A/C					
	34	4				5 9 3 1#5 94			
45	34	5 ^{P-81#5}	9		A-3s 6000			45	
45	34	5 P-91#5		4	A-35 5000	94	34	45	
45 Occupant				4 ommercia		94		45	
			C DD APT Occu	<u>•</u> ommercia S ıpancy	al Section #2	94	Foundation	Conc	rete
Occupant Section		CHWO	C DD APT Occu	₄ ommercia `S	al Section #2	94 4 4		Conc:	rete 310

Landings	[00	La	Polk Cou		Normal	Wiring	Adequat
Square Foot		80	Q	uality		INOTIMAI		Aucquai
Plumbing	Adeo	quate		Story Teight	3		Frame Type	Fram
Fireproof Construction		No Bldg		Frame,		, Concrete le, Tilt Up	Total Section Area	18,00
Ground Floor Area	6	6,000 Perim		imeter		354	Grade	4+0
Year Built		1973		dition		Normal		
Comment	P &	Q=CON	IC. LAN	IDINGS				
			Com	mercial (Groups - 1 R	lecord		
			Co	mmercia	al Group #20)1 1		
Use	Code	Apar	tment		Base Story	1	Number Stories	3
Total G	roup Area	1	8,000	E	Base Floor Area	6,000	Number Units	24
He	ating	С	entral	Со	Air nditioning	Yes	Exhaust System	No
Com	ment	SLE	EVE TY	PE A/C				
						<u>ς Q⁸1≉ ς</u>		
		F				5 ^{Q.⁵1≠ 5 40}		
	34		ŧ					
	34		ł					
			8					
45			k		A-3≠ 6000			45
45			k		A-35 6000			45
45	34		ł		A-3s 6000			45
45	34		ł		A-3≠ 6000		34	45
45	34	= P ^S 1s =	,	4	R−3 ≠ 6000		34	45
45	34	5 P-81# 5	ŀ 9	4	A-3# 6000	94	34	45
45		5 P-15 5 40	ş	4	A-3s 6000	94	34	45
45		5 P-13 5	1	4	A-3≠ 6000	94	34	45
45		5 P <u>⁸1</u> ≇ 5	ş	4	A-3≠ 6000	94	34	45
45	34	5 P-81#5	, ,	4	A−3 <i>z</i> 6000	94	34	45
45	34	5 P-1= 5 40	, ,	4	A-3# 6000	94	34	45

Detached Structures - 2 Records

Polk County Assessor 080/01781-000-000

32	4
Jon	5

Detached Structure #101							
Occupancy	AsphaltMeasurementPavingCode			Measure 1	23,500		
Grade	4	Year Built	1973	Condition	Normal		
		Detached Struc	ture #201				
	Trash	Construction	Frame	Measurement	Lineal		
Occupancy	Enclosure	Туре	Flame	Code	Feet		
Lineal Feet	40	Height	6	Grade	5		
Year Built	2012	Condition	Normal				

Sales - 3 Records

Seller	Buyer	Sale Date	Sale Price	Instrument	Book/Page
VALLEY BANK	SUMMER WOODS APTS, LLC	<u>2011-06-30</u>	\$1,122,000	Deed	<u>13900/169</u>
BIRCHWOOD APTS LC	AQUEOUS MANAGEMENT GROUP, LLC	<u>2006-03-21</u>	\$1,450,000	Deed	<u>11646/424</u>
IRVING, PAUL	BIRCHWOOD APTS LC	<u>2004-08-03</u>	\$1,150,500	Deed	<u>11646/418</u>

Appeals - 1 Record

Year	Туре	Case #	Status	Appellant				
2009	PAAB	09-77-1290	Dismissed	AQUEOUS MANAGEMENT LLC				
	Permits - 10 Records							
Year	Туре	Permit Status	Application	Description				
Current	Permit	To Work	2019-09-20	alterations/misc				
Current	Permit	To Work	2019-06-21	fix damage/fire				
2018	Permit	No Add	2017-06-13	fix damage/foundation				
2013	Permit	No Add	2012-12-12	fix damage/misc				
2013	Permit	No Add	2012-12-12	fix damage/misc				
2013	Permit	No Add	2012-10-01	addition/misc (100 sf)				
2011	Permit	No Add	2010-12-20	addition/misc				
2009	Permit	No Add	2008-10-22	fix damage/fire				
2009	Pickup	No Add	2007-08-02	review value/board of review				
2008	Pickup	Pass	2007-08-02	review value/board of review				

Historical Values

Yr	Туре	Class	Kind	Land	Bldg	Total
2019	Assessment Roll	Multi-Residential	Full	\$152,000	\$1,508,000	\$1,660,000
2017	<u>Assessment</u> <u>Roll</u>	Multi-Residential	Full	\$151,900	\$1,228,100	\$1,380,000
2015	<u>Assessment</u> <u>Roll</u>	Multi-Residential	Full	\$127,000	\$1,123,000	\$1,250,000
2013	<u>Assessment</u> <u>Roll</u>	Commercial Multiple	Full	\$127,000	\$983,000	\$1,110,000
2011	<u>Assessment</u> <u>Roll</u>	Commercial Multiple	Full	\$127,000	\$983,000	\$1,110,000

Polk County Assessor 080/01781-000-000

2020			For County Assessor 000/01/01-000-000						
Yr	Туре	Class	Kind	Land	Bldg	Total			
2009	Board Action	Commercial Multiple	Full	\$127,000	\$983,000	\$1,110,000			
2009	<u>Assessment</u> <u>Roll</u>	Commercial Multiple	Full	\$127,000	\$1,089,000	\$1,216,000			
2007	Board Action	Commercial Multiple	Full	\$127,000	\$1,089,000	\$1,216,000			
2007	<u>Assessment</u> <u>Roll</u>	Commercial Multiple	Full	\$127,000	\$1,089,000	\$1,216,000			
2005	Board Action	Commercial Multiple	Full	\$115,000	\$690,000	\$805,000			
2005	<u>Assessment</u> <u>Roll</u>	Commercial Multiple	Full	\$115,000	\$902,000	\$1,017,000			
2003	<u>Assessment</u> <u>Roll</u>	Commercial Multiple	Full	\$100,000	\$659,000	\$759,000			
2001	<u>Assessment</u> <u>Roll</u>	Commercial Multiple	Full	\$94,390	\$513,000	\$607,390			
1999	Assessment Roll	Commercial Multiple	Full	\$129,000	\$513,000	\$642,000			
1994	Board Action	Commercial Multiple	Full	\$125,000	\$498,000	\$623,000			
1993	Assessment Roll	Commercial Multiple	Full	\$125,000	\$713,000	\$838,000			
1990	Board Action	Commercial Multiple	Full	\$120,000	\$685,490	\$805,490			

This template was last modified on Sat Mar 4 12:31:48 2017 .

3720 ML King Jr PKwy



3720 ML King Jr Phuy



