Roll Call Number		Agenda Item Number <i>3み</i> C
February 10, 2020		
ABATEMENT OF PUBLI	IC NUISANCE AT 1624 (CARPENTER AVENUE
WHEREAS, the property locate inspected by representatives of the City of its present condition constitutes not only a and	of Des Moines who determ	nined that the main structure in
WHEREAS, the Titleholders, A Known & Unknown Heirs to Rosetta Si demolish the main structure and as of thi	ims, were notified more th	nan thirty days ago to repair or
NOW THEREFORE, BE IT RESOLVE MOINES, IOWA:	ED BY THE CITY COUN	NCIL OF THE CITY OF DES
The main structure on the real es TO NORTH DES MOINES an Official Des Moines, Polk County, Iowa, and lo been declared a public nuisance;	Plat, now included in and	d forming a part of the City of
The City Legal Department is her a decree ordering the abatement of the p nuisance, as ordered, that the matter may take all necessary action to demolish and	oublic nuisance, and should be referred to the Departr	d the owner(s) fail to abate the
	Moved by	to adopt.
FORM APPROVED:		
Megan Norberg, Assistant City Attorney		

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT
COWNIE				
BOESEN				
GATTO				
GRAY				
MANDELBAUM				
VOSS				
WESTERGAARD				
TOTAL				
MOTION CARRIED	APPROVED			

CERTIFICATE

I, P. Kay Cmelik, City Clerk of said City hereby certify that at a meeting of the City Council of said City of Des Moines, held on the above date, among other proceedings the above was adopted.

IN WITNESS WHEREOF, I have hereunto set my hand and affixed my seal the day and year first above written.

_____Mayor ______ City Clerk



PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA

DATE OF NOTICE: October 8, 2019

DATE OF INSPECTION:

August 27, 2019

CASE NUMBER:

COD2019-05283

PROPERTY ADDRESS:

1624 CARPENTER AVE

LEGAL DESCRIPTION:

LOT 7 GARDEN ADDITION

LINDA SIMS- DECEASED Title Holder 1624 CARPENTER AVE DES MOINES IA 50314

ROSETTA SIMS- DECEASED Title Holder 1624 CARPENTER AVE DES MOINES IA 50314

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-192 and 60-191 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Brad Rissman

(515) 283-4754

Nid Inspector

DATE MAILED: 10/8/2019

MAILED BY: BJR

Areas that need attention: 1624 CARPENTER AVE

	d attention: 1624 CARPENTER AVE		5. L. L. 1999	
Component:	Electrical System	Defect:	Disconnected Utility	
Requirement:	Electrical Permit	'l continu	Water/Gas/Electric	
	*	Location:	Main Structure Throughout	
<u>Comments:</u>	Permit also needs to include any interior v	iolations tha	it may exist.	
	,			
			٠.	٠,
Component:	Exterior Doors/Jams	Defect:	Deteriorated	
Requirement:	Compliance, International Property		Deteriorated	
Requirement	Maintenance Code	Location:	Main Structure Throughout	
Comments:				
	Repair or replace all damaged or missing of	doors and o	r jams as needed. Permit	
	required if changing opening size.			
,			<u>` </u>	
Component:	Exterior Walls	Defect:	Excessive rot	
Requirement:	Building Permit			
		<u>Location:</u>	Main Structure Throughout	
Comments:	Permit required to repair or replace any da	amaged or r	missing exterior walls.	
•				
Carrananink	Foundation	Defect:	Holes or major defect	
Component:	Building Permit	Delecti	i i i i i i i i i i i i i i i i i i i	
Requirement:	building Permit	Location:	Main Structure Throughout	
Comments:		Locationi	Hall Screen Thoughout	
Commenta	Foundation Needs Engineers Report			
	·		T	
Component:	Roof	Defect:	Deteriorated	
Requirement:	Building Permit			
* .	*	<u>Location:</u>	Main Structure Throughout	
Comments:	Permit required for repairs other than shir	nalės.		
•	Torrine roquired for repairs states at an area	.5.		
	a.3			
Component	Coffit/Engin/Trim	Defect:	Deteriorated	
Component:	Soffit/Facia/Trim	Defect:	Deteriorated	
Component: Requirement:	Compliance, International Property	1		
Requirement:	Compliance, International Property Maintenance Code	Location:	Main Structure Throughout	
	Compliance, International Property	Location:	Main Structure Throughout	
Requirement:	Compliance, International Property Maintenance Code	Location:	Main Structure Throughout	
Requirement:	Compliance, International Property Maintenance Code	Location:	Main Structure Throughout	
Requirement: Comments:	Compliance, International Property Maintenance Code Repair or replace all damaged or missing	Location:	Main Structure Throughout	
Requirement:	Compliance, International Property Maintenance Code	Location: items as nee	Main Structure Throughout eded. Deteriorated	
Requirement: Comments: Component:	Compliance, International Property Maintenance Code Repair or replace all damaged or missing Stairs/Stoop	Location: items as nee	Main Structure Throughout eded.	
Requirement: Comments: Component:	Compliance, International Property Maintenance Code Repair or replace all damaged or missing Stairs/Stoop Building Permit	Location: items as nee Defect: Location:	Main Structure Throughout eded. Deteriorated Main Structure Throughout	
Requirement: Comments: Component: Requirement:	Compliance, International Property Maintenance Code Repair or replace all damaged or missing Stairs/Stoop	Location: items as nee Defect: Location:	Main Structure Throughout eded. Deteriorated Main Structure Throughout	
Requirement: Comments: Component: Requirement:	Compliance, International Property Maintenance Code Repair or replace all damaged or missing Stairs/Stoop Building Permit	Location: items as nee Defect: Location:	Main Structure Throughout eded. Deteriorated Main Structure Throughout	
Requirement: Comments: Component: Requirement: Comments:	Compliance, International Property Maintenance Code Repair or replace all damaged or missing Stairs/Stoop Building Permit Permit needed to repair or replace stairs,	Location: items as need Defect: Location: ramps and s	Main Structure Throughout eded. Deteriorated Main Structure Throughout stoops at entry ways.	
Requirement: Comments: Component: Requirement: Comments:	Compliance, International Property Maintenance Code Repair or replace all damaged or missing Stairs/Stoop Building Permit Permit needed to repair or replace stairs, Windows/Window Frames	Location: items as nee Defect: Location:	Main Structure Throughout eded. Deteriorated Main Structure Throughout	
Requirement: Comments: Component: Requirement: Comments:	Compliance, International Property Maintenance Code Repair or replace all damaged or missing Stairs/Stoop Building Permit Permit needed to repair or replace stairs, Windows/Window Frames Compliance, International Property	Location: items as need Defect: Location: ramps and s Defect:	Main Structure Throughout eded. Deteriorated Main Structure Throughout stoops at entry ways. Deteriorated	
Requirement: Comments: Component: Requirements: Comments: Comments:	Compliance, International Property Maintenance Code Repair or replace all damaged or missing Stairs/Stoop Building Permit Permit needed to repair or replace stairs, Windows/Window Frames Compliance, International Property Maintenance Code	Location: items as need Defect: Location: ramps and elements Defect: Location:	Main Structure Throughout eded. Deteriorated Main Structure Throughout stoops at entry ways. Deteriorated Main Structure Throughout	
Requirement: Comments: Component: Requirement: Comments:	Compliance, International Property Maintenance Code Repair or replace all damaged or missing Stairs/Stoop Building Permit Permit needed to repair or replace stairs, Windows/Window Frames Compliance, International Property Maintenance Code	Location: items as need Defect: Location: ramps and elements Defect: Location:	Main Structure Throughout eded. Deteriorated Main Structure Throughout stoops at entry ways. Deteriorated Main Structure Throughout	
Requirement: Comments: Component: Requirements: Comments: Comments:	Compliance, International Property Maintenance Code Repair or replace all damaged or missing Stairs/Stoop Building Permit Permit needed to repair or replace stairs, Windows/Window Frames Compliance, International Property Maintenance Code Repair or replace all damaged or missing	Location: items as need Defect: Location: ramps and elements Defect: Location:	Main Structure Throughout eded. Deteriorated Main Structure Throughout stoops at entry ways. Deteriorated Main Structure Throughout	
Requirement: Comments: Requirement: Comments: Comments: Comments:	Compliance, International Property Maintenance Code Repair or replace all damaged or missing Stairs/Stoop Building Permit Permit needed to repair or replace stairs, Windows/Window Frames Compliance, International Property Maintenance Code	Location: items as need Defect: Location: ramps and elements Defect: Location:	Main Structure Throughout eded. Deteriorated Main Structure Throughout stoops at entry ways. Deteriorated Main Structure Throughout	


Component: Requirement:	See Comments	Defect:	See Comments				0.00	-
		Location:	Main Structure				•	
<u>Comments:</u>	Unable to gain access into the structure. Possibly more violations.						,	٠.
					•			

Polk County Assessor

111 Court Avenue #195 Des Moines, IA 50309-0904 (515) 286-3014 Fax (515) 286-3386 polkweb@assess.co.polk.ia.us

Location									
Address	Address 1624 CARPENTER AVE								
City	DES MOINES	Zip	50314	Jurisdiction	Des Moines				
District/Parcel	080/02310-000-000	Geoparcel	7924-33-481-008	Status	<u>Active</u>				
School	Des Moines	Nbhd/Pocket	DM76/Z	Tax Authority Group	DEM-C-DEM- 77131				
Submarket	Northwest Des Moines	Appraiser	Andrew Rand 515- 286-3368						

Map and Current Photos - 1 Record





Historical Photos

Ownership - 2 Records								
Ownership	Num	Recorded	Book/Page					
Title Holder	1	SIMS, ROSETTA	2004-06-04	10575/768				
Title Holder	2	SIMS, LINDA						

Legal Description and Mailing Address

LOT 7 GARDEN ADDITION


ROSETTA SIMS 1317 E 17TH ST DES MOINES, IA 50316-4019

Current Values

Type Class		Kind	Land		Bldg	Total		
2019 Value Residential		Value Residential Full \$8,500		\$1	7,800	\$26,300		
	Assessment Roll Notice Market Adjusted Cost Report							
	Zoning - 1 Record							
Zoning	Descr	Description		SF	Ass	essor Zoning		
R1-60	One Family, Low Density Residential District				F	Residential		

20 Polk County Assessor 060/02310-000-000									
Conditional Zoning									
Docket_no <u>14361</u>									
City of Des Moines Community Development Planning and Urban Design 515 283-4182 (2012-03-20)									
	Land								
Square Fee	t 8,100	Acres	0.186	Frontage	50.0				
Depth	162.0	Topography	Normal	Shape	Rectangle				
Vacancy	y No	Unbuildable	No						
		Residences -	1 Record						
		Residence	: # 1						
Occupancy	Single Family	Residence Type	1.5 Stories	Building Style	Conventional				
Year Built	1953	Number Families	1	Grade	4+00				
Condition	Very Poor	Total Square Foot Living Area	1283	Main Living Area	768				
Upper Living Area	515	Basement Area	768	Foundation	Concrete Block				
Exterior Wall Type	Wood Siding	Roof Type	Gable	Roof Material	Asphalt Shingle				
Heating	Gas Forced Air	Air Conditioning	0	Number Bathrooms	2				
Bedrooms	2	Rooms	6						





	Detached Structures - 1 Record								
	Detached Structure #101								
Occup	pancy	Garage	Constructi	on Type	Frame	Measurement Code	Dimensions		
Meas	sure 1	14	Me	Measure 2 20		Story Height	1		
(Grade	5	Ye	Year Built 1953		Condition	Very Poor		
				Permits -	2 Record	S			
Year	Type	Per	mit Status	Applic	cation	Description	n		
2015	Pickup	Comple	te	2014-07-07		review value/check condition	on		
1995	Permit	No Add		1994-08-03 handicap ramp					

Historical Values

Yr	Type Class		Kind	Land	Bldg	Total
2019	Assessment Roll	Residential	Full	\$8,500	\$17,800	\$26,300
2017	Assessment Roll	Residential	Ful1	\$7,600	\$16,900	\$24,500
2015	Assessment Roll	Residential	Full	\$7,600	\$19,400	\$27,000
2013	Assessment Roll	Residential	Full	\$7,300	\$41,600	\$48,900
2011	Assessment Roll	Residential	Full	\$7,900	\$50,800	\$58,700
2009	Assessment Roll	Residential	Full	\$6,600	\$61,100	\$67,700
2007	Assessment Roll	Residential	Full	\$6,300	\$58,600	\$64,900
2005	Assessment Roll	Residential	Ful1	\$7,400	\$55,900	\$63,300

Yr	Туре	Class	Kind	Land	Bldg	Total
2003	Assessment Roll	Residential	Full	\$6,010	\$52,940	\$58,950
2001	Assessment Roll	Residential	Full	\$5,460	\$37,860	\$43,320
1999	Assessment Roll	Residential	Full	\$4,470	\$19,000	\$23,470
1997	Assessment Roll	Residential	Full	\$3,660	\$15,550	\$19,210
1995	Assessment Roll	Residential	Full	\$3,410	\$14,500	\$17,910
1989	Assessment Roll	Residential	Full	\$2,950	\$12,550	\$15,500

This template was last modified on Sat Mar 4 12:31:48 2017 .



